

Date: 29.05.2019
Vehicle No: SJG8989P
Model: AUDI A4 1.8
Chassis: WAUZZZ8K5FA149835 - 2015
Reg.Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SMK4590E
Date of Accident: 27.05.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER BRACKET RH	1		<i>11</i> \$155.00
2	FRONT BUMPER SIDE RETAINER RH	1		\$168.00
3	FRONT BUMPER CLIPS	12	\$11.50	<i>11</i> \$138.00
SUB TOTAL				\$461.00
LESS 5%				-\$23.05
PARTS TOTAL				\$437.95

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE & READJUST, REPLACE FRONT BUMPER BRACKET,
FRONT BUMPER ETC. BACK TO ORIGINAL CONDITIONS

\$200.00 *100%*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINTS & FURNISHING MATERIAL
AT FRONT BUMPER

\$400.00 *25%*

LABOUR TOTAL \$600.00

ONG TOTAL \$1,037.95

*Not Authorized
1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: