

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

WEN HONG ENGINEERING SERVICES
 Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

30th MAY 2019

TP AIG.
 Kharchan.

AGH300010234.

Accident date: 28th MAY 2019

Estimated repair cost for vehicle no: Sku1335I Toyota Alphard 2.5 '15

S/n	Qty	Items	U/price	Amount
1	1	bonnet <i>Peris</i>		\$2,250.00 ✓
2	1	Front emble logo <i>new</i>		\$75.00 ✓
3	1	Front Support Panel <i>new</i>		\$858.00 ✓
4	1	Front bumper <i>Deband</i>		\$1,810.20 1655
5	1	Front bumper side bracket <i>new</i>		\$131.20 ✓
6	1	Front head lamp -LH <i>cracked</i>		\$2,518.71 ✓
7	1	Front fender <i>Peris</i>		\$1,252.10 ✓
8	1	Front Bumper Fog Lamp-LH <i>cracked</i>		\$388.50 ✓
9	1	Front Bumper Fog Lamp cover -LH <i>new</i>		\$158.00 ✓
10	1	Front Bumper seonsor -set <i>new</i>		\$600.00 ✓
11	1	Front Grille <i>cracked</i>		\$412.00 ✓
12	1	front grille clips <i>new</i>		\$60.00 20
13	1	front bumper lower grille / garnish <i>new</i>		\$225.00 ✓
14	1	water tank -LH <i>new</i>		\$352.00 ✓
15	1	Front tyre -LH		\$500.00 ✓
16	1	Sport rim-front LH <i>new</i>		\$600.00 ✓

Subtotal :- \$12,190.71

5200.41

3900.30

Labour charges

Wheel alignment computer

To check wiring system

Panel beating

Spray painting

\$120.00 X

~~\$80.00~~ 30

~~\$1,000.00~~ 400

~~\$800.00~~ 600.

Subtotal :- \$2,000.00

Total:- \$14,190.71

1030

Total: 4930.30
H/S: 3.9K
04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: