

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

30th MAY 2019

WEN HONG ENGINEERING SERVICES

Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

Accident date: 28th MAY 2019

Estimated repair cost for vehicle no: Sku1335I Toyota Alphard 2.5 '15

S/n	Qty	Items	U/price	Amount
				\$2,250.00
1	1	bonnet		\$75.00
2	1	Front emble logo		\$858.00
3	1	Front Support Panel		\$1,810.20
4	1	Front bumper		\$131.20
5	1	Front bumper side bracket		\$2,518.71
6	1	Front head lamp -LH		\$1,252.10
7	1	Front fender		\$388.50
8	1	Front Bumper Fog Lamp-LH		\$158.00
9	1	Front Bumper Fog Lamp cover -LH		\$600.00
10	1	Front Bumper seonsor -set		\$412.00
11	1	Front Grille		\$60.00
12	1	front grille clips		\$225.00
13	1	front bumper lower grille / garnish		\$352.00
14	1	water tank -LH		\$500.00
15	1	Front tyre -LH		\$600.00
16	1	Sport rim-front LH		

Subtotal :- \$12,190.71

<u>Labour charges</u>	\$120.00
Wheel alignment computer	\$80.00
To check wiring system	\$1,000.00
Panel beating	\$800.00
Spray painting	
Subtotal :-	<u>\$2,000.00</u>
Total:-	<u>\$14,190.71</u>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 0089K

Vehicle Details

Vehicle No.: SKU1335L

Vehicle to be Exported: Yes

Intended Deregistration Date: 30 May 2019

Vehicle Make: TOYOTA

Vehicle Model: ALPHARD 2.5S-C CVT

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: 2ARH543010

Chassis No.: AGH300010234

Maximum Power Output: 134.0 kW (179 bhp)

Open Market Value: \$38,064.00

Original Registration Date: 30 Jun 2015

First Registration Date: 30 Jun 2015

Transfer Count: 0

Actual ARF Paid: \$45,290.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jun 2025

PARF Rebate Amount: \$33,967.00

Intended COE Rebate Details

COE Expiry Date: 29 Jun 2025

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$75,801.00

COE Rebate Amount: \$45,624.00

Total Rebate Amount: \$79,591.00

The information contained herein is correct as at 30 May 2019

OK

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

30th MAY 2019

WEN HONG ENGINEERING SERVICES

Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

Accident date: 28th MAY 2019

Estimated repair cost for vehicle no: Sku1335l Toyota Alphard 2.5 '15

S/n	Qty	Items	U/price	Amount
	1	bonnet		\$2,250.00
1	1	Front bumper		\$1,810.20
2	1	Front bumper side bracket		\$131.20
3	1	Front head lamp -LH		\$2,518.71
4	1	Front fender		\$1,252.10
5	1	Front Bumper Fog Lamp-LH		\$388.50
6	1	Front Bumper Fog Lamp cover -LH		\$158.00
7	1	Front tyre -LH		\$500.00
8	1	Sport rim-front LH		\$600.00

Subtotal :- \$9,608.71

Labour charges

Wheel alignment computer

To check wiring system

Panel beating

Spray painting

\$120.00

\$80.00

\$800.00

\$800.00

Subtotal :- \$1,800.00

Total:- \$11,408.71

*Water tank
 Fuel sensor
 Fuel goni.*

bumper (cover) cables