

AXH-LKK

Kj



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLX 7271 U

Finalised

Parts	(a) Cost / List Price Items	\$ 5124.20	8,726.10
	Plus/Less 20%	\$ 1281.05	1,745.22
	Total of Cost / List	\$ 3843.15	6,980.88
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$ 360.00	415.00
Total Parts Cost		\$ 4203.15	7,395.88
Labour		\$ 2290.00	3,630.00
Total		\$ 6493.15	11,025.88

Not Authorized
Return By Repairer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

4/6/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 06-8 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Sc

Date:

4/6/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLX 7271 U**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71104082**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$120.00	S.N	✓
2	Rear windscreen sealant	1	\$50.00	S.N	40W ✓
3	Reverse sensor	2	\$200.00	S.N	✓
4	Rear number plate	1	\$45.00	S.N	X
5	Rear No.plate lamp LH	1	\$38.50		X
6	Rear No.plate lamp RH	1	\$38.50		X
7	Rear bumper	1	\$1,150.60		✓
8	Rear bumper clip	10	\$35.00		✓
9	Rear bumper side retainer LH	1	\$26.50		✓
10	Rear bumper side retainer RH	1	\$26.50		X
11	Rear bumper bracket LH	1	\$48.70		X
12	Rear bumper bracket RH	1	\$48.70		X
13	Rear bumper sponge	2	\$179.00		X
14	Rear bumper tow cover	1	\$16.50		✓
15	Rear bumper reinforcement	1	N/A		
16	Rear bumper reflector LH	1	\$45.00		X
17	Rear bumper reflector RH	1	\$45.00		X
18	Rear bumper reflector garnish LH	1	\$45.00		X
19	Rear bumper reflector garnish RH	1	\$45.00		X
20	Tail door	1	\$1,193.00		✓
21	Tail door lock	1	\$157.10		✓
22	Tail door emblem	1	\$38.00		✓
23	Wording "SHUTTLE"	1	\$55.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

287170

36051N

Spare Parts

Vehicle No. : SLX 7271 U
 Make & Model : HONDA SHUTTLE
 Chassis No : GP71104082

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Wording "HYBRID"	1	\$80.10		✓
25	Tail door chrome	1	\$383.10		X
26	Tail door trim	1	\$320.00		✓
27	Tail door trim clip	10	\$35.00		✓
28	Taildoor reflector LH	1	\$395.00		X
29	Taildoor reflector RH	1	\$395.00		X
30	Taildoor inner pocket	1	\$19.50		✓
31	Tail end panel	1	\$560.80		✓
32	Tail end panel garnish	1	\$155.50		✓
33	Tail end panel garnish clip	10	\$35.00		✓
34	Boot weatherstrip	1	\$168.50		✓
35	Tail lamp LH	1	\$520.50		X
36	Tail lamp RH	1	\$520.50		X
37	Spare tyre well panel	1	\$956.00		✓
38	Spare tyre board	1	\$655.00		✓
39	Gargo Box	1	\$295.00		✓
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2279.40



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221

Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112

Fax : 6451 0394

Co. Reg No. : 200005485N

GST Reg No. : 20-0005485-N

Spare Parts

Vehicle No. :

SLX 7271 U

Make & Model :

HONDA SHUTTLE

Chassis No. :

GP71104082

Submit By :

CARMEN LIM

Year Manufacture :

2016

Engine No. :

Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear antenna control <i>CM</i>	1	\$58.10		☒
2	Rear pillar lower quarter panel LH <i>B7</i>	1	\$105.00		☒
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

163.10



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLX 7271 U

Submit By : Carmen Lim

Make & Model : HONDA SHUTTLE

Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	800 - 1200 ⁹⁰⁰
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	800
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	80
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$150.00	760 ✓
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

2290