



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLX 7271 U

Not Authorized  
Resurvey B & Paint

Parts	(a) Cost / List Price Items	\$	8,726.10
	Plus/Less 20%	\$	1,745.22
	<b>Total of Cost / List</b>	<b>\$</b>	<b>6,980.88</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	415.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>7,395.88</b>
<b>Labour</b>		<b>\$</b>	<b>3,630.00</b>
<b>Total</b>		<b>\$</b>	<b>11,025.88</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 4/6/19 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 06-8 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Sc Date: 4/6/19



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLX 7271 U**  
Make & Model : **HONDA SHUTTLE**  
Chassis No : **GP71104082**

Submit By : **Carmen Lim**  
Year Manufacture : **2016**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>na</i>	1	\$120.00	S.N	—
2	Rear windscreen sealant <i>na</i>	1	\$50.00	S.N	4000
3	Reverse sensor <i>nd</i>	2	\$200.00	S.N	—
4	Rear number plate <i>sn</i>	1	\$45.00	S.N	X
5	Rear No.plate lamp LH <i>sn</i>	1	\$38.50		X
6	Rear No.plate lamp RH <i>sn</i>	1	\$38.50		X
7	Rear bumper <i>B1</i>	1	\$1,150.60		✓
8	Rear bumper clip <i>na</i>	10	\$35.00		✓
9	Rear bumper side retainer LH <i>nd</i>	1	\$26.50		✓
10	Rear bumper side retainer RH	1	\$26.50		?
11	Rear bumper bracket LH	1	\$48.70		?
12	Rear bumper bracket RH	1	\$48.70		?
13	Rear bumper sponge	2	\$179.00		?
14	Rear bumper tow cover <i>nd</i>	1	\$16.50		✓
15	Rear bumper reinforcement	1	N/A		
16	Rear bumper reflector LH	1	\$45.00		?
17	Rear bumper reflector RH <i>sn</i>	1	\$45.00		X
18	Rear bumper reflector garnish LH	1	\$45.00		?
19	Rear bumper reflector garnish RH <i>sn</i>	1	\$45.00		X
20	Tail door <i>B1</i>	1	\$1,193.00		✓
21	Tail door lock <i>nd</i>	1	\$157.10		✓
22	Tail door emblem <i>na</i>	1	\$38.00		✓
23	Wording "SHUTTLE" <i>na</i>	1	\$55.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : SLX 7271 U  
Make & Model : HONDA SHUTTLE  
Chassis No : GP71104082

Submit By : Carmen Lim  
Year Manufacture : 2016  
Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Wording "HYBRID" <i>Me</i>	1	\$80.10		✓
25	Tail door chrome <i>Sn</i>	1	\$383.10		X
26	Tail door trim	1	\$320.00		?
27	Tail door trim clip	10	\$35.00		?
28	Taildoor reflector LH <i>Sn</i>	1	\$395.00		X
29	Taildoor reflector RH <i>Sn</i>	1	\$395.00		X
30	Taildoor inner pocket <i>Ref</i>	1	\$19.50		✓
31	Tail end panel <i>Ref</i>	1	\$560.80		✓
32	Tail end panel garnish <i>Ref</i>	1	\$155.50		✓
33	Tail end panel garnish clip <i>Me</i>	10	\$35.00		✓
34	Boot weatherstrip <i>Dis/Ref</i>	1	\$168.50		✓
35	Tail lamp LH <i>Sn</i>	1	\$520.50		X
36	Tail lamp RH <i>Sn</i>	1	\$520.50		X
37	Spare tyre well panel <i>Ref</i>	1	\$956.00		?
38	Spare tyre board	1	\$655.00		?
39	Gargo Box <i>Dis</i>	1	\$295.00		✓
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLX 7271 U** Submit By : **Carmen Lim**  
Make & Model : **HONDA SHUTTLE** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	800 - 1000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	880
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	80
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$150.00	?
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.