



13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

68441184 / 9657234
 (Anna)

Vehicle No. SLV1136C TOYOTA CHR

TY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	FRONT DOOR RH		1209 1320.00	bt✓
1	FRONT INNER DOOR BOARD RH		590.00	x✓
1	FRONT DOOR LOWER MOULDING RH		242.00	x✓
1	FRONT DOOR UPPER MOULDING RH		211.00	x✓
1	FRONT DOOR GLASS RUN CHANNEL RH		142.00	x✓
1	FRONT DOOR LOWER TRIM COVER RH		342.00	cut✓
1	FRONT DOOR BLACK TAPE RH		25.00	neu✓
1	FRONT DOOR LOCK RH		473.90 520.00	bt✓
1	FRONT DOOR POWER WINDOW REGULATOR RH		585.00	2 n n
1	REAR DOOR RH		1284.90 1420.00	bt✓
1	REAR INNER DOOR BORD RH		490.00	x✓
1	REAR DOOR GLASS RUN CHANNEL RH		142.00	x✓
1	REAR DOOR LOWER MOULDING RH		242.00	x✓
1	REAR DOOR UPPER MOULDING RH		211.00	x✓
1	REAR DOOR LOWER TRIM COVER RH		342.00	cut✓
1	REAR DOOR BLACK TAPE RH		25.00	neu✓
1	REAR DOOR POWER WINDOW REGULATOR RH		585.00	2 n n
1	REAR FENDER RH		980.00	R x
1	REAR FENDER ARCH RH		210.00	ab
1	REAR FENDER SPLASH SHIELD RH		253.00	x
1	REAR SHOCK ABSORBER RH		592.00	x
1	REAR LOWER ARM RH		298.00	x
1	REAR TIE ROD RH		145.00	x
1	REAR WHEEL BEARING RH		278.00	x
1	REAR KNUCKLE ARM RH		398.00	x
1	REAR BUMPER		1030.00	x
1	REAR BUMPER SIDE RETAINER RH		115.00	x
1	REAR BUMPER LOWER		620.00	x
1	REAR BUMPER LOWER REFLECTOR RH		355.00	x
1	REAR BUMPER LOWER REFLECTOR COVER RH		291.00	x
			12999.00	
less			25%	25%
			3249.75	
			9749.25	
<u>SPECIAL NETT ITEMS</u>				
SET	REAR FENDER INNER SHEILD CLIPS		80.00	x n n
SET	REAR BUMPER CLIPS		120.00	x n n
1	FRONT BODY BIG STICKER		300.00	200 neu
1	FRONT FENDER GRILLE RH		310.00	x n n
1	DOOR VISOR		280.00	180 neu
1	REAR 18' TYRE RH		350.00	x n n
1	REAR SPORT RIM RH		980.00	600 cut✓
Total Parts			12169.25	

3911.80
 2933.25

980.



Vehicle No. SLV1136C TOYOTA CHR

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	700.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	700.
3	To remove, re-fix wiring system at accident damage areas and check for proper function	150.00	30.
4	To perform anti-rust treatment on affected areas	180.00	60.
5	To clear fault code with diagnostic computer and reset to specification.	250.00	Xun.
6	To remove and replace / re-fix front & rear door inner parts fitting etc rhs	150.00	120.
7	To conduct computerised wheel alignment test	120.00	80.
8	To remove and replace front undercarriage parts rhs	350.00	Xun.
	Labour Total :	4600.00	1690.
	TOTAL (PARTS & LABOUR):	16769.25	

Tan Hin 87415749
 - WP
 12/2/20
 Lump sum
 Repair after repair
 5 days.

2933.25
 980
 1690.
 5603.25
 1/s \$4500 #
 5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: