

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009877/T1QD3E2

Date: 24/09/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/19-998534-WTT
Claimant Vehicle No :	SLV1136C	Insured Vehicle No :	FBE7292C
Date of Loss:	27/05/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000611

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV1136C	Engine No:	2ZR8180700
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102069976
Reg. Date:	21/12/2017 (Man. Year: 2017)	Odometer:	98928 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,169.25	3,913.85	8,255.40	67.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	1,690.00	2,910.00	63.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,769.25	5,603.85	11,165.40	66.58
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	16,769.25	4,500.00	12,269.25	73.17

INSPECTION

Date of Assignment:	04/06/2019	
Date Inspected:	12/07/2019	Inspected At:
		Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2020)
Parts: M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV1136C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	1,320.00 FL	*1,209.00 FL
2	1		*FRONT INNER DOOR BOARD RH	Not Necessary	590.00 FL	*- FL
3	1		*FRONT DOOR LOWER MOULDING RH	Not Necessary	242.00 FL	*- FL
4	1		*FRONT DOOR UPPER MOULDING RH	Not Necessary	211.00 FL	*- FL
5	1		*FRONT DOOR GLASS RUN CHANNEL RH	Not Necessary	142.00 FL	*- FL
6	1		*FRONT DOOR LOWER TRIM COVER RH	Cut	342.00 FL	*342.00 FL
7	1		*FRONT DOOR BLACK TAPE RH	Necessary	25.00 FL	*25.00 FL
8	1		*FRONT DOOR LOCK RH	Bent	520.00 FL	*473.90 FL
9	1		*FRONT DOOR POWER WINDOW REGULATOR RH	Not Necessary	585.00 FL	*- FL
10	1		*REAR DOOR RH	Bent	1,420.00 FL	*1,284.90 FL
11	1		*REAR INNER DOOR BORD RH	Not Necessary	490.00 FL	*- FL
12	1		*REAR DOOR GLASS RUN CHANNEL RH	Not Necessary	142.00 FL	*- FL
13	1		*REAR DOOR LOWER MOULDING RH	Not Necessary	242.00 FL	*- FL
14	1		*REAR DOOR UPPER MOULDING RH	Not Necessary	211.00 FL	*- FL
15	1		*REAR DOOR LOWER TRIM COVER RH	Cut	342.00 FL	*342.00 FL
16	1		*REAR DOOR BLACK TAPE RH	Necessary	25.00 FL	*25.00 FL
17	1		*REAR DOOR POWER WINDOW REGULATOR RH	Not Necessary	585.00 FL	*- FL
18	1		*REAR FENDER RH	Repair	980.00 FL	*- FL
19	1		*REAR FENDER ARCH RH	Cut	210.00 FL	*210.00 FL
20	1		*REAR FENDER SPLASH SHIELD RH	Not Necessary	253.00 FL	*- FL
21	1		*REAR SHOCK ABSORBER RH	Not Necessary	592.00 FL	*- FL
22	1		*REAR LOWER ARM RH	Not Necessary	298.00 FL	*- FL
23	1		*REAR TIE ROD RH	Not Necessary	145.00 FL	*- FL
24	1		*REAR WHEEL BEARING RH	Not Necessary	278.00 FL	*- FL
25	1		*REAR KNUCKLE ARM RH	Not Necessary	398.00 FL	*- FL
26	1		*REAR BUMPER	Not Necessary	1,030.00 FL	*- FL
27	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	115.00 FL	*- FL
28	1		*REAR BUMPER LOWER	Not Necessary	620.00 FL	*- FL
29	1		*REAR BUMPER LOWER REFLECTOR RH	Not Necessary	355.00 FL	*- FL
30	1		*REAR BUMPER LOWER REFLECTOR COVER RH	Not Necessary	291.00 FL	*- FL
31	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
32	1		*SET REAR BUMPER CLIPS	Not Necessary	120.00 FS	*- FS
33	1		*FRONT BODY BIG STICKER	Necessary	300.00 FS	*200.00 FS
34	1		*FRONT FENDER GRILLE RH	Not Necessary	310.00 FS	*- FS
35	1		*DOOR VISOR	Necessary	280.00 FS	*180.00 FS
36	1		*REAR 18 TYRE RH	Not Necessary	350.00 FS	*- FS
37	1		*REAR SPORT RIM RH	Cut	980.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,419.00 4,891.80

- List Item Discount on L Items 25.00/25.00% (\$\$) 3,249.75 977.95

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	12,169.25	3,913.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	700.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	700.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	60.00
5	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATION	New	250.00	0.00
6	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	80.00
7	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS RHS	New	350.00	0.00
8	TO REMOVE AND REPLACE / REFIX FRONT & REAR DOOR INNER PARTS FITTING ETC RHS	New	150.00	120.00
Gross Labour Cost (S\$)			4,600.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >