COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 3001C

MAKE

DATE 3/6/2019 10:13

Otv	: HYUNDAI i40 Parts Description/ Labour	Type	Unit Price	A	mount
Qty	Rear Bumper		de	\$	553.00
	Rear Bumper Clip 10 pcs		uer-	\$	22.00
	Real Bumper Chip To pes		,		
	SUB TOTAL			\$	575.00
	LESS 20%			\$	115.00
	DISCOUNTED TOTAL			\$	460.00
	DISCOUNTED TO THE				
	Rear Bumper Rubber Mat		ue -	-\$	50.00
				\$	50.00
	Labour Charge		0.50		400.00
	Panel Beating		200	\$	400.00
	Spray Painting Charge		200	\$	300.00
	Wiring Charge				30.00
	Remove/Refix Reverse Sensor		30	- \$	80.00
	TOTAL LABOUR			\$	810.00
	ESTIMATE TOTAL			\$	1,320.00
	Tanfilh 97495749 WP' 3/1/198520pm Permy before point part by part. Sure librarita com 02 days.		LKK Auto Consultants hen- the Repairer of the for with The Repairer of the form of the form Third party survey is on a form The Repairer of the form The Repair	ing residenting out Freward resurv	arvey

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.