

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MD SHAMSUR RAHMAN
13 ST ANNE'S WOOD
S 545529

WAUZZ24LX ADO18832
TPEQ Vivion.

Date :12.06.2019
Vehicle No :SLX 6073 G
Make/Model :AUDI Q7
Accident date :01.06.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear tailgate <i>Dented</i>	1	\$ 4997 ✓
2	Rear tailgate hinges @ \$ 165.00 <i>2 x new</i>	2	\$ 330 +
3	Rear tailgate shock absorber @ \$ 106.70	2	\$ 213.4 +
4	Rear tailgate upper lock <i>Damaged</i>	1	\$ 149.6 ✓
5	Rear tailgate lower lock <i>new</i>	1	\$ 90.2 +
6	Rear tailgate weather strip <i>new</i>	1	\$ 143 ✓
7	Rear tailgate inner board <i>Crushed</i>	1	\$ 2420 985
8	Rear tailgate centre logo	1	\$ 85.8 ✓
9	Rear tailgate Q7 emblem <i>new</i>	1	\$ 68.2 ✓
10	Rear tailgate 3.6 emblem	1	\$ 68.2 ✓
11	Rear tailgate quattro emblem <i>new</i>	1	\$ 68.2 ✓
12	Rear tailgate camera <i>new</i>	1	\$ 880 +
13	Rear number plate lamp @ \$24.20 <i>new</i>	2	\$ 48.4 +
14	Rear handle <i>new</i>	1	\$ 286 +
15	Rear number plate <i>new</i>	1	\$ 55 30 (SW)
16	Rear number plate holder <i>new</i>	1	\$ 55 30 (SW)
17	Rear end panel <i>Dented</i>	1	\$ 575 +
18	Rear end panel inner top garnish <i>new</i>	1	\$ 462 ✓
19	Rear bumper <i>Distorted</i>	1	\$ 2015 ✓
20	Rear bumper side holder @ \$ 44.00 <i>new</i>	2	\$ 88 ✓
21	Rear bumper reflector @ \$ 247.50 <i>new</i>	2	\$ 495 ✓
22	Rear bumper <i>new</i> moulding <i>new</i>	1	\$ 209 ✓
* 23	Rear bumper side moulding @ \$ 121.00 <i>new</i>	2	\$ 242 ✓
24	Rear bumper towing hook cover @ \$ 22.00 <i>LH Missing</i>	2	\$ 44 22
25	Rear lower bumper <i>new</i>	1	\$ 1302 ✓
26	Rear bumper reverse sensor @ \$ 198.00 <i>2 pieces damaged</i>	4	\$ 792 396
27	Rear bumper reinforcement <i>new</i>	1	\$ 1246 ✓
28	Rear bumper bracket @ \$ 82.50 <i>new</i>	2	\$ 165 ✓
29	Rear bumper clips (1 set) <i>new</i>	1	\$ 16.5 ✓
30	Rear exhaust pipe chrome @ \$ 286.00 <i>new</i>	2	\$ 572 +

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MD SHAMSUR RAHMAN
13 ST ANNE'S WOOD
S 545529

Date :12.06.2019
Vehicle No :SLX 6073 G
Make/Model :AUDI Q7
Accident date :01.06.2019

No	DESCRIPTION	Qty	Amount (\$)
31	Rear exhaust pipe @ \$ 2,442.00 <i>Deleted.</i>	2	\$ 4884 2270
32	Rear exhaust pipe cover <i>implied</i>	1	\$ 214.5
33	Rear exhaust pipe outer garnish <i>new</i>	1	\$ 93.5
34	Rear reverse sensor wire (1 set) <i>new</i>	1	\$ 517
35	Rear end panel stopper @ \$ 16.50 <i>new</i>	2	\$ 33
36	Rear fender inner side garnish @ \$ 319.00 <i>new</i>	2	\$ 638
37	Rear spare tyre top board <i>new</i>	1	\$ 935
38	Rear spare tyre well side sponge @ \$ 71.50 <i>rehd</i>	2	\$ 143
39	Rear spare tyre well <i>3 new</i>	1	\$ 1430
40	Rear spare tyre well insulation <i>new</i>	1	\$ 308
41	Taillamp @ 988 <i>could 1978</i>	5	\$ 25800.5
			\$ 6450.1
		Less 20% Disc	
		Total	\$ 19350.4

Labour Cost

1	To supply rear windscreen sealant	\$ 50
2	To supply rear end panel inner sealant	\$ 200
3	Remove & reinstall rear windscreen	\$ 150-120
4	Remove & reinstall reverse sensor	\$ 200-60
5	Remove & reinstall exhaust pipe	\$ 300-100
6	Remove & reinstall camera	\$ 100-60
7	Remove & reinstall bootlid inner garnish	\$ 200-80
8	Remove ,replace & repair consistent to the accident	\$ 2000-1000
9	Respray painting	\$ 1500-1000
10	Tuff kote	\$ 150
11	To check wiring	\$ 100-30
12	To reset <i>diagnostic</i>	\$ 100
	Total	\$ 5050

Grand Total

\$ 24400.4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 20083.80

L/S : 16K

100%

16K
100%