

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCZ 6361X

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 14/04/2019

TP Veh Reg No: SLL7499T

Estimate No: ES1991602/YISHUN

Date: 06 Jun 2019

Policy No: 5017225405-12

Veh Reg No: SCZ6361X

Make/Model: HONDA CITY M

Chassis No: MRHGD85906P010108

Engine No: L15A24801984

Reg. Date: 22/11/2006

Estimate Repair Cost to Vehicle No :SCZ6361X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	481.90	1 PC	481.90	—
2 REAR BUMPER LH SIDE RETAINER	23.90	1 PC	23.90	—
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
4 REAR BOOT INNER LOCK	49.80	1 PC	49.80	—
			576.60	
		Less 20%	115.32	461.28
Labour				
5 REMOVE & REFIX REAR BUMPER ASSY,KNOCK & REPAIR REAR PANEL & REALIGN THE SAME	400.00	1 LA	400.00	320
6 PUTTY & RESPRAY ON REAR BUMPER,REAR PANEL	500.00	1 LA	500.00	400
			900.00	900.00
Total				S\$ 1,361.28
Add GST @ 7%				95.29
Total Amount Payable				<u>S\$ 1,456.57</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: