LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #08-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur Date: 06 Jun 2019

Preliminary Advice

Vehicle No : SLR6713A Accident Date : 31/05/2019 : SUBARU IMPREZA Make Policy No. : 1700043771 **Assignment Date** : 04/06/2019 **Excess** : S\$800.00 Date of Inspection Est. Duration of Repair : 04/06/2019 : 04/06/2019

Inspection At : Motorimage Enterprises Pte Ltd (HQ)

19 LORONG 8, TOA PAYOH

Singapore 319255

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,772.40
Revised Amount	:S\$	2,785.00
Check Items (Estimated)	:S\$	6,929.80
Total	:S\$	9,714.80

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 76,000.00 COE / PARF Rebate :S\$ 46,140.00

Salvage Value :S\$

Margin for Repair :S\$ 29,860.00

Remarks

X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments: