

ASS. REC. BY:

REF:

CS/19009891/Kud322

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Gabriel use

of

TH

Date/Time:

04/6/19

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 1328H

Insured:

SHC 8334Z

at Workshop m/s

EM SOLUTION

Tel:

91018302

91796610

of

160 SLM ANGLITY #03-18/19

Policy No:

Claim No:

MCT19060032

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/6/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

LWP

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN OUT

Date/Time	Action/Instruction () Estimate
	SMA 1328H x
	SHC 8334Z x
13/6	L1 Day @ 11,400 email to customer (Real 7842.72, 4110)

ASS. REC. BY:

REF:

TV /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMG132814 Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes 5 C.C. 1998

Colour: M. Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 72653 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JM8CW10711-0120738

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / S/D A/Rlm or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 8 mm

L/Bal: 8 mm

D.O.A: 1/6/19

D.O.I: 4/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/14

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

1 File per 1 to

RECEIVED 10 JUN 2019

Date/Time, File Pass to?

☐ : Prel. Report

11

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 11

Resurvey No. of Trip: 1

Survey Fee

Transportation

S + RS \$

Fuel

Others

Total

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Merimen

Lump Sum / I.B.I. (\$

11,400/2

460
11
461

Veron Chen (LKKAUTO)

From: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>
Sent: Monday, 17 June 2019 9:27 AM
To: Veron Chen (LKKAUTO)
Cc: Pooi Chin Han Daniel; Sundari Nagarajan - III; Gabriel Wee; Stanley Lai
Subject: MCT19060032 FW: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCLGCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Claim Audit	History Checking	Activity Log	Documents	Duplicate
Assign Solicitor	File Review	Adj Market Value	Transfer To Repairer	Send RI
Claim Details	Set/Modify Adj Mandate			

AIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		04 Jun 2019 00:00			Pending Adjuster Survey Cancel Case

Main	Offer Processing	Claim Details	Adjuster's Details
------	------------------	---------------	--------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	-, Co. Reg. No.: -		
Vehicle Reg. No.:	SMG1328H	Date of Loss:	01/06/2019 22:00 -
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. Insured):	SHC8334Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Em Solution Pte Ltd (HQ) PROFILE BLK 17 SIN MING IND EST SECTOR A, 575675 Sin Ming - Tel: 645602		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt di		

CLAIM NOT REGISTERED

This claim is not registered. Click [Register](#) to register this claim.
You need to register a claim if you want to link other related subfolders to it.

Progress			
CLQ00109 SST V1.0 INDIA INTERNATIONAL INSURANCE LIVE DB 17/			
Claim Item			
Claim No.....	MCT19060032	Claim Item No.	2.01
Claimant.....	SMG1328H-TPI		
Descr. of loss....	INJURY TO PAX IN SMG1328H		
print 1			Cause.
Claim Reserves			
Payment category	Reserve/Cur:SGD	Planned	
LOSS	3,000.00	0.00	
SURVEY FEE	0.00	0.00	
LIST OF CLAIM ITEMS			
Item	Claimant name	Description of 1	
1.01	SMG1328H-TPD	DAMAGE TO TPV SMG13	
2.01	SMG1328H-TPI	INJURY TO PAX IN SM	

Best Regards,

Mekavathanan
HOD
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6105 Fax: 6224 4174



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, June 17, 2019 9:19 AM
To: Motor Claim - III <motorclaim@iii.com.sg>; Anil Kumar <anil@htapartners.com.sg>; SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Pooi Chin Han Daniel <danielpooi@iii.com.sg>
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Dear Sir/Madam,

Kindly provides us claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 4 June 2019 11:26 AM
To: Anil Kumar <anil@htapartners.com.sg>; SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Pooi Chin Han Daniel <danielpooi@iii.com.sg>
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMG1328H and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Anil Kumar [<mailto:anil@htapartners.com.sg>]
Sent: 04 June, 2019 9:19 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: EM Auto <emautosolution@singnet.com.sg>; Tan Vincent (tanvin13@yahoo.com.sg) <tanvin13@yahoo.com.sg>
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Without Prejudice
Save As To Cost

Dear Gabriel,

We refer to your email dated even date..

Our client is agreeable to use **Mr Kenneth Kong from LKK Auto Consultants Pte Ltd** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle SMG1328H as follows:

Kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : **EM SOLUTION PTE LTD**
160 Sin Ming Autocity
#03-18/19
Singapore 575722

Contact Person : Mr Bernard at H/P: 91018302 (Important: Kindly contact Mr Bernard, prior to arranging your appointed surveyor going down to inspect our client's vehicle for the above matter)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,
Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212
Direct Fax: 63383536
Fax : 63383536

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 4 June 2019 9:04 AM
To: Anil Kumar <anil@htapartners.com.sg>
Cc: EM Auto <emautosolution@singnet.com.sg>; Tan Vincent (tanvin13@yahoo.com.sg)
<tanvin13@yahoo.com.sg>
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Anil Kumar [mailto:anil@htapartners.com.sg]

Sent: 03 June, 2019 4:19 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: EM Auto <emautosolution@singnet.com.sg>; Tan Vincent (tanvin13@yahoo.com.sg) <tanvin13@yahoo.com.sg>

Subject: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Without Prejudice

Save As To Cost

Dear Sir,

ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

We are instructed to notify you of the above-mentioned road traffic accident which involves our client's vehicle registration number **SMG1328H** and vehicle registration number **SHC8334Z** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212
Direct Fax: 63383536
Fax : 63383536

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 4 June 2019 11:26 AM
To: Anil Kumar; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Pooi Chin Han Daniel
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMG1328H and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee

(In)
KSC



61 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Anil Kumar [mailto:anil@htapartners.com.sg]
Sent: 04 June, 2019 9:19 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: EM Auto <emautosolution@singnet.com.sg>; Tan Vincent (tanvin13@yahoo.com.sg) <tanvin13@yahoo.com.sg>
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Without Prejudice
Save As To Cost

Dear Gabriel,

We refer to your email dated even date..

Our client is agreeable to use Mr Kenneth Kong from LKK Auto Consultants Pte Ltd from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle SMG1328H as follows:

Kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : **EM SOLUTION PTE LTD**
160 Sin Ming Autocity
#03-18/19
Singapore 575722

Contact Person : Mr Bernard at H/P: 91018302 (Important: Kindly contact Mr Bernard, prior to arranging your appointed surveyor going down to inspect our client's vehicle for the above matter)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,
Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212
Direct Fax: 63383536
Fax : 63383536

From: Motor Claim - III <motoreclaim@iii.com.sg>

Sent: Tuesday, 4 June 2019 9:04 AM

To: Anil Kumar <anil@htapartners.com.sg>

Cc: EM Auto <emautosolution@singnet.com.sg>; Tan Vincent (tanvin13@yahoo.com.sg)
<tanvin13@yahoo.com.sg>

Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @ TIME: 22:05 HRS ALONG PIE

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



61 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Anil Kumar [mailto:anil@htapartners.com.sg]
Sent: 03 June, 2019 4:19 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Ce: EM Auto <emautosolution@singnet.com.sg>; Tan Vincent (tanvin13@yahoo.com.sg)
<tanvin13@yahoo.com.sg>
Subject: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SHC8334Z & OUR REF: TCL.GCN.an.50361.19.em - ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

Without Prejudice

Save As To Cost

Dear Sir,

ACCIDENT INVOLVING SMG1328H & SHC8334Z ON 01/06/19 @TIME: 22:05 HRS ALONG PIE

We are instructed to notify you of the above-mentioned road traffic accident which involves our client's vehicle registration number **SMG1328H** and vehicle registration number **SHC8334Z** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212
Direct Fax: 63383536
Fax : 63383536

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5583Z
Vehicle Details	
Vehicle No.:	5MG1328H
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP6EAT SUNROOF
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	PE30732662
Chassis No.:	JM6CW1071F0120738
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,359.00
Original Registration Date:	30 Dec 2014
First Registration Date:	30 Dec 2014
Transfer Count:	1
Actual ARF Paid:	\$12,359.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2024
PARF Rebate Amount:	\$9,269.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,201.00
COE Rebate Amount:	\$40,046.00
Total Rebate Amount:	\$49,315.00

The information contained herein is correct as at 06 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/06/2019 11:10
Date Of Accident 01/06/2019 22:05
Exact Location Of Accident PIE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG1328H
Insured/Policyholder
Name Of Registered Owner CHEN SIYU
NRIC No S8535583Z
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98808405
Alternative Phone No OFFICE-98808405

Vehicle Particulars

Manufacturer MAZDA
Model 5

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5105501223(CLASSIC)
Cover Note Number

Driver

Name of Driver NG WEE LIAT
NRIC No S8507306J
Date Of Birth 16/03/1985
Occupation INDOOR
Date Of Driving Pass 06/03/2007
Driving Experience 12 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98808405
Fax Number
Contact Number
EMail Address NOEMAIL

Address BLK 449A BT BATOK WEST AVE 9 #06-60
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 7
Passenger 1
NAME: : --
GENDER: : MALE
Passenger 2
NAME: : --
GENDER: : MALE
Passenger 3
NAME: : --
GENDER: : MALE
Passenger 4
NAME: : --
GENDER: : MALE
Passenger 5
NAME: : --
GENDER: : FEMALE
Passenger 6
NAME: : --
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
POLICE STATION NAME [OTHER] BT BATOK NPC
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. POLICE REPORT NO. T/20190602/2031

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC8334Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name 2 PASSENGERS

Approximate Age

Injuries Sustain

Injured person in which vehicle? SMG1328H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 03/06/2019
 11:08 AM


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 03/06/2019
 11:08 AM

IDAG BUKIT BATOK (VAC)
 Reporting Centre Personne's Signature 2
 Name:
 NRIC/FIN No.:

PIE TOWARDS TUAS NEAR EXIT 12

[illegible]

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: 03/06/2019
11:00 AM

Driver's Signature
(If driver is not the policyholder)
Date & Time: 03/16/2011 1:00 PM

IDAC BUKIT BATOK (VAC)

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



**SINGAPORE
POLICE FORCE**



T/20190602/2031

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20190602/2031

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/06/2019 11:15	Vide Report No.:	Station Diary No.: 35
--	------------------	--------------------------

Informant's Particulars

Name of Informant: NG WEE LIAT			Address: APT BLK 449A BUKIT BATOK WEST AVENUE 9 #06-60 SINGAPORE 651449		
ID Type / ID No.: NRIC NO / S8507306J			Contact No.: Home/Office: Mobile: 98808405		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 34	Date of Birth: 16/03/1985	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: ENGINEER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/06/2019 22:05	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
Towards Tuas, near Exit 12				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC8334Z	Car				Seriously Damaged	1
SMG1328H	Car				Seriously Damaged	6



**SINGAPORE
POLICE FORCE**



T/20190602/2031

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20190602/2031

CONTINUATION OF REPORT

Brief Details.

On 01/06/2019 at about 2207hrs, I was driving (SMG1328H) along PIE towards Tuas, near Exit 12. The traffic started to slow down so I brake my car slowly. However, the car behind me did not stop in time and collided into the rear of my car. I have managed to exchange particulars with the driver of the car behind me (Nor Ziman Bin Mohamed Affindi, S8140359G, H/P: 83339438).

Two of my passengers are injured. They informed that they felt pain in their necks. I brought them to Ng Teng Fong General Hospital to get them checked. One of my passengers has already been discharged and has been given 8 days MC. The other passenger is hospitalized.

I wish to state that I have an in-car camera and have saved the footage from the incident.



**SINGAPORE
POLICE FORCE**



T/20190602/2031

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20190602/2031

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: Sgt 2 SITI NABILA BINTE RAZALI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/06/2019 11:15
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No: 65476172	Classification Of Case:
Authentication Stamp NP168	

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

04.06.2019

Chen Siyu

Not Authorized
L/Ly 8?
Perry

REPAIR ESTIMATE FOR MAZDA 5 - SMG 1328 H

1 pc.	rear bumper fascia	By	1,284.30	✓
2 pcs	rear bumper side retainers	42.20 D.S	84.40	✓
1 pc.	rear bumper reinforcement	By	236.80	✓
2 pcs	rear bumper reflectors	o/s cm	39.70	✓
2 pcs	tail lamps	591.60 S	1,183.20	X
1 pc.	tail gate	By	2,570.40	✓
1 pc.	tail gate rubber	cm	136.40	50 km
1 pc.	tail gate inner lock	nu	262.70	✓
1 pc.	tail gate emblem	nu	51.40	✓
1 pc.	tail gate "5" badge	nu	28.30	✓
1 pc.	tail gate "Skyactiv" badge	nu	32.60	✓
1 pc.	tail gate "Mazda" badge	nu	36.90	✓
1 pc.	tail gate outer garnish	nu	179.50	X
1 pc.	tail gate wiper motor		485.60	?
1 pc.	tail gate inner trim	nu	436.20	✓
1 pc.	spare tyre panel	By/Bu	988.70	✓
1 pc.	spare tyre cover		389.30	?
1 pc.	spare tool tray		298.10	?
1 pc.	rear end panel	By	462.60	✓
1 pc.	rear end panel top garnish	nu	89.60	✓
1 pc.	rear exhaust silencer		781.50	?
2 pcs	rear exhaust mountings	44.40	88.80	?
1 pc.	front bumper		1.00	?
2 pcs	front bumper fog lamps	0.10 S	0.20	X 680
2 pcs	front bumper fog lamp grilles	0.10 S	0.20	X 174
1 pc.	front bumper lower grille		0.10	? 700.30
2 pcs	front bumper side retainers	0.10	0.20	? 63.00
1 pcs	front bumper reinforcement		0.10	? 581.60
2 pcs	front bumper brackets	0.10	0.20	? 104.60
1 pc	front bumper inner foam		0.10	? 89.00
2 pcs	headlamps assy	0.10	0.20	? 3164
1 pc	front support panel		0.10	X 575
1 pc	front support panel top garnish		0.10	X
			10,189.20	
		Less 20%	2,037.84	
			8,151.36	

o/s ?

KV

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

04.06.2019

Chen Siyu

Not Authorized
U/Sing 81,400k
Running After Point 11 days

REPAIR ESTIMATE FOR MAZDA 5 - SMG 1328 H

1 pc.	rear bumper fascia	915.40	B ₁	1,284.30	✓
2 pcs	rear bumper side retainers		42.20	DIT 84.40	✓
1 pc.	rear bumper reinforcement	185.80	B ₁	236.80	✓
2 pcs	rear bumper reflectors		39.70	79.40	✓
2 pcs	tail lamps		591.60	Sm 1,183.20	X
1 pc.	tail gate	1559.00	B ₁	2,570.40	✓
1 pc.	tail gate rubber		Ad 161	136.40	506.20
1 pc.	tail gate inner lock		Ad	262.70	✓
1 pc.	tail gate emblem		Ad	51.40	✓
1 pc.	tail gate "5" badge		Ad	28.30	✓
1 pc.	tail gate "Skyactiv" badge		Ad	32.60	✓
1 pc.	tail gate "Mazda" badge		Ad	36.90	✓
1 pc.	tail gate outer garnish		Ad	179.50	X
1 pc.	tail gate wiper motor		mgcm	485.60	✓
1 pc.	tail gate inner trim		mgcm	436.20	✓
1 pc.	spare tyre panel	910.50	Ad 161	988.70	✓
1 pc.	spare tyre cover	295.80	Ad 161	389.30	✓
1 pc.	spare tool tray		Ad	298.10	✓
1 pc.	rear end panel		B ₁	462.60	✓
1 pc.	rear end panel top garnish		Ad	89.60	✓
1 pc.	rear exhaust silencer		B ₁	781.50	✓
2 pcs	rear exhaust mountings		DIT	44.40	✓
1 pc.	front bumper	1045.30	B ₁	1,208.00	✓
2 pcs	front bumper fog lamps		340.00	Sm 680.00	X
2 pcs	front bumper fog lamp grilles		87.00	Sm 174.00	X
1 pc.	front bumper lower grille	625.00	Ad	702.30	✓
2 pcs	front bumper side retainers		31.60	Sm 63.20	X
1 pcs	front bumper reinforcement		Ad	581.60	X
2 pcs	front bumper brackets		52.30	Ad 104.60	✓
1 pc	front bumper inner foam		cm	89.20	✓
1 pc	front bumper logo		Ad	55.60	✓
1 pc	front grille		mgcm	181.70	✓
2 pcs	headlamps assy	1411.40	mgcm	1,582.00	3,164.00
1 pc	front support panel		cm	575.00	✓
			17,765.90		
			Less 20%		3,553.18
					14,212.72

- 1 set reverse sensor
- 1 set number plates
- 1 pc rear windscreen sealant
- 1 set rear bumper clips
- 1 set rear end panel top garnish clips
- 1 set boot inner trim clips
- 1 set front bumper clips

<i>nd</i>	270.00	SN	<i>2001n</i>
<i>car/00</i>	120.00	SN	<i>901n</i>
<i>me</i>	60.00	SN	<i>401n</i>
<i>me</i>	45.00	SN	<i>—</i>
<i>me</i>	30.00	SN	<i>—</i>
<i>me</i>	40.00	SN	<i>—</i>
<i>me</i>	45.00	SN	<i>—</i>

- 1) Check electrical wirings
- 2) Repair damages and renew above parts.
- 3) Renew reverse sensors
- 4) Renew rear exhaust silencer
- 5) Remove and refit rear windscreen
- 6) Spray paint on affected portions.
- 7) Remove/refit air con parts, vacuum & top up gas.
- 8) Rust proofing on affected portions

60.00	<i>40*</i>
1,880.00	<i>1800</i>
80.00	<i>50</i>
100.00	<i>60</i>
150.00	<i>120</i>
1,880.00	<i>1320 1300</i>
150.00	<i>100</i>
120.00	<i>90</i>
<u>\$ 19,242.72</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before *or* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2019 14:39 Edit Reg		04 Jun 2019 00:00 Edit Adj Rpt	S\$11,400.00 Edit Estimates	S\$11,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Co. Reg. No.: -								
Main Claimant:	Co. Reg. No.: -								
Vehicle Reg. No.:	SMG1328H	Date of Loss:	01/06/2019 22:00 - :59 [53 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHC8334Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Em Solution Pte Ltd (HQ) BLK 17 SIN MING IND EST SECTOR A, 575675 Sin Ming - Tel: 64560226								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMG1328H

[SHC8334Z]

TP

-

Jun 1 2019 10:00PM

[-]

Em Solution Pte Ltd



































Upload Documents






















Upload Photos

Compose New Letter

View

View in Browser

Photos/Images				3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	17/06/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
34	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
35	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
36	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
37	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	17/06/19 09:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 08:47	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19009891/KVD3E2

Date: 28/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle
No : SMG1328H

Insured Vehicle No : SHC8334Z

Date of Loss: 01/06/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG1328H

Make & Model: MAZDA 5, 2.0 5 DR WAGON (A)

Engine No: PE30732662

Reg. Date: 30/12/2014 (Man. Year: 2014)

Chassis No: JM6CW1071F0120738

Colour: Metallic Grey

Odometer: 72653 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,822.72	10,509.80	4,312.92	29.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	3,760.00	660.00	14.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,242.72	14,269.80	4,972.92	25.84
Approved Total (Overridden) (S\$)		11,400.00		
(S\$)	19,242.72	11,400.00	7,842.72	40.76
+ GST 7.00/7.00% (S\$)	1,346.99	798.00	548.99	40.76
Nett Amount (S\$)	20,589.71	12,198.00	8,391.71	40.76

INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 04/06/2019 Inspected At:

Em Solution Pte Ltd (HQ)
160 SIN MING DRIVE #03-18/19
SIN MING AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 11.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Jun 2019)	
Parts:	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG1328H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Bent	1,284.30 FL	*915.40 FL
2	2		*REAR BUMPER SIDE RETAINERS	Distorted	84.40 FL	*84.40 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	236.80 FL	*185.80 FL
4	1		*REAR BUMPER REFLECTORS	O/S Cracked	79.40 FL	*39.70 FL
5	2		*TAIL LAMPS	Serviceable	1,183.20 FL	*- FL
6	1		*TAIL GATE	Bent	2,570.40 FL	*1,559.00 FL
7	1		*TAIL GATE RUBBER (\$136.40)(50%)	Dented / Cut	109.12 FS	*68.20 FS
8	1		*TAIL GATE INNER LOCK	Dented	262.70 FL	*262.70 FL
9	1		*TAIL GATE EMBLEM	Necessary	51.40 FL	*51.40 FL
10	1		*TAIL GATE 5 BADGE	Necessary	28.30 FL	*28.30 FL
11	1		*TAIL GATE SKYACTIV BADGE	Necessary	32.60 FL	*32.60 FL
12	1		*TAIL GATE MAZDA BADGE	Necessary	36.90 FL	*36.90 FL
13	1		*TAIL GATE OUTER GARNISH	Serviceable	179.50 FL	*- FL
14	1		*TAIL GATE WIPER MOTOR	Mtg Cracked	485.60 FL	*485.60 FL
15	1		*TAIL GATE INNER TRIM	Mtg Cracked	436.20 FL	*436.20 FL
16	1		*SPARE TYRE PANEL	Bent / Buckled	988.70 FL	*910.50 FL
17	1		*SPARE TYRE COVER	Dented / Distorted	389.30 FL	*295.80 FL
18	1		*SPARE TOOL TRAY	Dented	298.10 FL	*298.10 FL
19	1		*REAR END PANEL	Bent	462.60 FL	*462.60 FL
20	1		*REAR END PANEL TOP GARNISH	Dented	89.60 FL	*89.60 FL
21	1		*REAR EXHAUST SILENCER	Bent	781.50 FL	*781.50 FL
22	2		*REAR EXHAUST MOUNTINGS	Distorted	88.80 FL	*88.80 FL
23	1		*FRONT BUMPER	Buckled	1,208.00 FL	*1,045.30 FL
24	2		*FRONT BUMPER FOG LAMPS	Serviceable	680.00 FL	*- FL
25	2		*FRONT BUMPER FOG LAMP GRILLES	Serviceable	174.00 FL	*- FL
26	1		*FRONT BUMPER LOWER GRILLE	Dented	702.30 FL	*625.00 FL
27	2		*FRONT BUMPER SIDE RETAINERS	Serviceable	63.20 FL	*- FL
28	1		*FRONT BUMPER REINFORCEMENT	Repair	581.60 FL	*- FL
29	2		*FRONT BUMPER BRACKETS	Repair	104.60 FL	*- FL
30	1		*FRONT BUMPER INNER FOAM	Cracked	89.20 FL	*89.20 FL
31	1		*FRONT BUMPER LOGO	Necessary	55.60 FL	*55.60 FL
32	1		*FRONT GRILLE	Mtg Cracked	181.70 FL	*181.70 FL
33	2		*HEADLAMPS ASSY	Mtg Cracked	3,164.00 FL	*2,822.80 FL
34	1		*FRONT SUPPORT PANEL	Cracked	575.00 FL	*575.00 FL
35	1		*SET REVERSE SENSOR	Dented	270.00 FS	*200.00 FS
36	1		*SET NUMBER PLATES	Cracked / Dented	120.00 FS	*90.00 FS
37	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
38	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
39	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SET BOOT INNER TRIM CLIPS	Necessary	40.00 FS	*40.00 FS
41	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
						<small>F=Franchise part. S=SpcNett. L=ListItemDisc.</small>
					Sub Total (\$\$)	18,348.62 12,997.70
					- List Item Discount on L Items 20.00/20.00% (\$\$)	3,525.90 2,487.90
					Total Parts (\$\$)	14,822.72 10,509.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ELECTRICAL WIRINGS	New	60.00	40.00
2	REPAIR DAMAGES AND RENEW ABOVE PARTS	New	1,880.00	1,800.00
3	RENEW REVERSE SENSORS	New	80.00	50.00
4	RENEW REAR EXHAUST SILENCER	New	100.00	60.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	SPRAY PAINT ON AFFECTED PORTIONS	New	1,880.00	1,500.00
7	REMOVE / REFIT AIR CON PARTS, VACUUM & TOP UP GAS	New	150.00	100.00
8	RUST PROOFING ON AFFECTED PORTIONS	New	120.00	90.00
Gross Labour Cost (S\$)			4,420.00	3,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >