

ASS. REC. BY:

REF:

CF/FC1909900/K14312

Special Instruction:

Surveyor Kenneth

ASSIGNMENT (Office)

From (Person):

Joanne Yon

of

FCI

Date/Time:

04/6/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJN 1030P

Insured:

SHA 5197H

at Workshop m/s

LIM TAN MOTOR

Tel:

6452 0893 / 84845418

of

41K 176 S/M DRIVE #03-09/10/06 S/M Autocare

Policy No:

Claim No:

D19003644 NUTSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/6/14

CA / REV / REP. / REV 24 HRS

1wp.

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SJN 1030P CC4/11/17 (702465) KF43 DOR: 31/1/17

SHA 5197H

12/6@2:49pm Revised preli advice via email

17/6 \$367k.58 email & call sum (Red: 2393.25! 39%)

ASS. REC. BY:

REF PCL

ASSIGNMENT

From:

Date: 11.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SN 1030P

at Workshop n/s Lim Tan

of BIK 176 Sin Ming Drive #0 3-09

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

81784

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STN 1030P

Yr Regn:

08 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Esquire

C.C.

1986

Colour:

2. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading:

24918

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZRR80

0234592

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

4

mm

L/Bal.

7

mm

L/Bal.

4

mm

D.O.A.

1/6/19

D.O.I.

11/6/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Acc n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 18 JUN 2019

Date/Time, File Pass to?

18/6 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I. (\$) 3674.58

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee:

☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

3 + 115.50

Photos

Others

TOTAL

145

50

15

210

MOTOR SURVEY ASSIGNMENT

Date	03-06-2019	Our Ref No. D19003644MFSH
Accident Date	01-06-2019	Claim Type. Third Party
Insured Vehicle	SHA5197H	Third Party Vehicle. SJN1030P
Survey Location	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE	
Contact Person.	RICHARD ANG	
Contact No.	64520893/ 84845418	Fax No. 64589127
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

OUT

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIM TAN MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Your Ref: D19003644MFSH

Date: 12/06/2019

Our Ref: CS/FCI19009900/Ktd3


The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJN 1030PPlease be informed that we had conducted the inspection of the abovementioned vehicle
11/06/2019 at the premises of M/s Lim Tan Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,067.83</u>
Revised Estimate Amount	: S\$ <u>3,144.58</u>
"Check" Items Amount	: S\$ <u>420.20</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
rear portion.**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Steve

Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 12 June 2019 2:49 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003644MFSH/1
Attachments: PRELI ADVISED SJN 1030P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJN 1030P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 4 June 2019 2:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003644MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that the vehicle currently not in the workshop and repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 4 June 2019 2:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003644MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8364B

Vehicle Details

Vehicle No.: SJN1030P
Vehicle to be Exported: No
Intended Deregistration Date: 03 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: ESQUIRE 2.0XI A
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 3ZRB861277
Chassis No.: ZRR800234592
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$29,560.00
Original Registration Date: 18 Aug 2017
First Registration Date: 18 Aug 2017
Transfer Count: 0
Actual ARF Paid: \$33,384.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Aug 2027
PARF Rebate Amount: \$25,038.00

Intended COE Rebate Details

COE Expiry Date: 17 Aug 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$53,711.00
COE Rebate Amount: \$44,066.00
Total Rebate Amount: \$69,104.00

The information contained herein is correct as at 03 Jun 2019

OK



23674.58

SURVEYOR NAME :	
DATE OF SURVEY :	11 JUN 2019
TIME OF SURVEY :	

DATE : 3-Jun-19
DATE OF ACCIDENT : 1-Jun-19
THIRD PARTY REF : SHA5197H / MS FIRST CAPITAL

LOS ANGELES Consumers have notified the Registrar of the following:

- To remedy defective spring padding.
- To design a standard profile having "contour".
- To provide a new mattress for the "firm" model.
- To design a new "firm" model "Providence" base.
- To design a new "firm" model "Providence" base.
- To design a new "firm" model "Providence" base.
- To design a new "firm" model "Providence" base.

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19009900/Kld3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5197H	Veh. Inspected	SJN 1030P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003644MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	04/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESQUIRE (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZRR800234592	Colour	METALLIC PEARL WHITE	
Odometer	24918	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	4 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2019	Inspection Date	11/06/2019	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 1030P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	664.00	664.00
2	REAR BUMPER BRACKET @\$142.10	TO REPAIR SEE LABOUR	284.20	-
2	REAR BUMPER RETAINER @\$115.60	SERVICEABLE	231.20	-
1	REAR BUMPER REFLECTOR	SERVICEABLE	85.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	918.00	-
1	REAR END PANEL GARNISH	SERVICEABLE	258.00	-
1	TAILGATE	BENT	1,685.00	1,685.00
1	TAILGATE RUBBER	SERVICEABLE	356.00	-
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	498.00	-
1	TAILGATE EMBLEM	NECESSARY	57.10	57.10
1	SET REAR WINDSCREEN MOULDING	NECESSARY	160.00	160.00
	LESS 25% DISCOUNT		-1,299.27	-641.52
			3,897.83	1,924.58
SPECIAL NETT ITEMS				
1	TUBE REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	SET REAR BUMPER SENSOR (SN)	CRACKED	400.00	400.00
			440.00	440.00
LABOUR				
	TO PUTTY AND SPRAY PAINTING.		800.00	600.00
	TO REPLACE AND REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	TO TRANSFER TAILGATE FITTINGS.		80.00	60.00
	TO ANTI-RUST.		80.00	30.00
	LABOUR CHARGES INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET, REAR END PANEL AND TAILGATE LOCK.		650.00	500.00
			1,730.00	1,310.00
GRAND TOTAL			6,067.83	3,674.58
RECOMMENDED COST OF REPAIRS				3,674.58

Report Ref No. CS/FCI19009900/Ktd3n2



Report Ref No. CS/FC119009900/Ktd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.