

ASS. REC. BY:

REF:

CS/A1G190097743/1CSD30

Special Instruction:

SURVEYOR

Kenneth

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

A1G

Date/Time:

4/6/2019 @ 8:45am

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 5343Y

Insured:

at Workshop m/s

Motor Image

Tel:

9668 9313

of

In losing & fun psych

Policy No:

Claim No:

Sum Insured:

Excess:

800

Make of Veh:

D.O.A.

31/5/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Limen

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction



Estimate

SME 5343Y - X

24hr

\$3911.14 Carlim

(\$ 2,434.86 Red - 68%)

ASS. REC. BY:

REF: A/G/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.


D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 21 NOV 2019

Date/Time, File Pass to?

1) Typist

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend IS

Survey Fee:

Transportation:

S - RS - SI

: Photos

: Others

TOTAL

Report Format:

Lump Sum / I.B.J. (\$

3,911.14 p/p

700
11
211

SME5343Y - OD CLAIM - AIG INSURED - ARRANGE SURVEY - 04/06/2019...

From: Chin, Lee-Ying

To: assignments, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 6/4/2019 8:48:20 AM

Attachments:  SME5343Y OD ESTIMATE.PDF  SME5343Y - GIA REPORT - OD.PDF

Hi LKK,

Kindly assist to arrange survey with Motor Image.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Mohamed Isman [mailto:isman@motorimage.net]

Sent: Monday, June 03, 2019 5:56 PM

To: AIG SGP, Claims-Survey

Cc: TPY Insurance Team

Subject: [EXTERNAL] SME5343Y - OD CLAIM - AIG INSURED - ARRANGE SURVEY - 04/06/2019@1100HRS

Importance: High

This message is from an external sender; be cautious with links and attachments.

Hi Team,

Kindly assist to arrange survey for the above mentioned

04/06/2019 (Tuesday) @ 1100hrs

****Customer waiting****

Thank You.

Best Regards

Mohd Isman

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 9668 9313

Email: isman@motorimage.net

Website: www.tanchong.com : www.motorimage.net

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 25 October 2019 9:55 am
To: Mohamed Isman
Cc: SUR; Ooi Siow Hooi; Daniel Jude
Subject: RE: SME5343Y - OD CLAIM - AIG - FINALIZED

Dear All,

Confirmed final fig \$ 3,911.14 @ 3 days of repairs before excess \$ 800/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ooi Siow Hooi <hooi@motorimage.net>
Sent: Wednesday, 23 October 2019 2:53 pm
To: SUR <sur@lkkauto.com>
Subject: FW: SME5343Y - OD CLAIM - AIG - FINALIZED


Hi Claim Teams,

Attached for your reference and follow up.

*****Kindly reply to all for easier follow up*****

Thank You

Best Regards,
Siowhooi
Admin Assistant
Motor Image Enterprises Pte Ltd
19 Toa Payoh Lorong 8, Singapore 319255
Tel: +65-6703 8333 DID: +65-6703 8115
Fax: +65-6253 5535
Email: hooi@motorimage.net
Website: www.tanchong.com : www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 25 October 2019 9:55 am
To: Mohamed Isman
Cc: SUR; Ooi Siow Hooi; Daniel Jude
Subject: RE: SME5343Y - OD CLAIM - AIG - FINALIZED

Dear All,

Confirmed final fig \$ 3,911.14 @ 3 days of repairs before excess \$ 800/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ooi Siow Hooi <hooi@motorimage.net>
Sent: Wednesday, 23 October 2019 2:53 pm
To: SUR <sur@lkkauto.com>
Subject: FW: SME5343Y - OD CLAIM - AIG - FINALIZED

Hi Claim Teams,

Attached for your reference and follow up.

*****Kindly reply to all for easier follow up*****

Thank You

Best Regards,
Siowhooi
Admin Assistant
Motor Image Enterprises Pte Ltd
19 Toa Payoh Lorong 8, Singapore 319255
Tel: +65-6703 8333 DID: +65-6703 8115
Fax: +65-6253 5535
Email: hooi@motorimage.net
Website: www.tanchong.com : www.motorimage.net

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 June 2019 9:11 am
To: 'Mohamed Isman'
Subject: RE: SME 5343Y OD (AIG) DOA - 31/05/2019

Hi Isman,

Excess figure is \$ 800.00.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: ShirleyHiew@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, 6 June 2019 2:16 PM
To: 'Mohamed Isman' <isman@motorimage.net>
Subject: SME 5343Y OD (AIG) DOA - 31/05/2019

Hi Isman,

Please refer to the estimate re-marked by Kenneth.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: ShirleyHiew@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 6 June 2019 2:16 PM
To: 'Mohamed Isman'
Subject: SME 5343Y OD (AIG) DOA - 31/05/2019
Attachments: ESTIMATE.pdf

Hi Isman,

Please refer to the estimate re-marked by Kenneth.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: ShirleyHiew@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/06/2019 12:14
Date Of Accident	31/05/2019 10:45
Exact Location Of Accident	ORCHARD TURNTAKASHIMAYA CARPARK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME5343Y
Insured/Policyholder	
Name Of Registered Owner	TAI BENJAMIN YAT CHING
NRIC No	G5459900K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98992168
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	IMPREZA-2.0 5D I-S EYESIGHT AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL / LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800117538
Cover Note Number	

Driver

Name of Driver	LIN KERRI JANE
NRIC No	G5460293L
Date Of Birth	16/05/1974
Occupation	INDOOR
Date Of Driving Pass	06/07/2015
Driving Experience	3 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98992168
Fax Number	
Contact Number	
Email Address	KERRIJLIN@GMAIL.COM

Address	53 GRANGE ROAD, #16-07 SPRING GROVE
Postcode	249565
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED DOCUMENTS

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH2819X
Vehicle Make/Model/Colour	HONDA FREED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH TECK GUAN
NRIC/Passport Number	S1331590F
Contact Number	82828855
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS COMING OUT OF CARPARK EXIT TO TURN ONTO ORCHARD TURN. I ~~WAS~~ ACCELERATED SLIGHTLY TO TURN, BUT DID NOT SEE THE CAR TRAVELING ON ORCHARD TURN TO MY RIGHT. BY THE TIME HE ~~WAS~~ USED HIS HORN, I COULD NOT STOP IN TIME AND HIT HIS VEHICLE ON THE SIDE PANEL.

VEH A : SME 5343 Y

VEH B : SMH 2819 X

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

SIRAMC SketchPlanForm_V7

Kenneth
Driver's Signature
(If driver is not the policyholder)
Date & Time:

31 MAY 2019 1:45pm

[Signature]
Reporting Centre Personnel's Signature
Name: DANIEL JOSE
NRIC/ID No.: S9001518D

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers/agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

31 MAY 2019 1:45pm

Reporting Centre Personnel's Signature
Name: DANIEL JUDR
NIC/TIN No.: S90015180

INSURANCE CERT



SUBARU AUTO PROTECTOR PRIVATE VEHICLE

The abstract was described as the Cover title is hereby withdrawn (CANCELED) on the terms and conditions of the policy issued to the Publisher.

Vehicle No.	:	
Cover Note No.	:	1800117538
Endorsement No.	:	
Issued Date	:	01 Oct 2018

ABOUT THE COVER

Make/Model	SUBARU IMPREZA 2.0i-S EYESIGHT AWD CVT (4dr/5dr)			
Engine Capacity/Tonnage	1,995.00 CC	Sum Insured	Market Value	First Year of Registration : 2018
Driver Restriction	NA	Off Peak Car	No	Insuring with COE/PARF : Yes
Person or Classes of Persons Entitled to Drive*				

2) Any other person who is sitting in the Polystyrolator's seat or with proper permission.
The Police will instruct the Polystyrolator or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional cost of \$3,000 as "Young and Inexperienced Driver Expense" (YIDE) if You are or Your Authorized Driver (parent or guardian) is under the age of 21 and/or has less than 2 years' driving experience.

Age Condition	All Age Condition
Limitation as to use*	

This Policy does not cover use for fees or reward, gaming, tuition, driving test, voting, game-making, reliability test or speed testing. The coverage of goods other than services is conditioned with any trade in business. It can be any purchase in connection with Motor Trade.

Loss of Live Fishes: 180000

⁴ L'expressions rendentes inoperative (by Section 9 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 124) and Section 45 of the Road Transport Act, 1987 (Malaysia)), are not to be included under these headings.

EXCESS

Section 9
Fire - \$2,000,000; Theft - \$1,000,000; Flood Cover - \$500,000

Section 2
Property Coverage - Bill

© 2000 Blackwell Science Ltd *Journal of Internal Medicine* 247: 395–402

Named Driver and Excess (where applicable)
 Yai Kawanda Yai Chung - \$800 (Over Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Author Image Enterprises Pte Ltd. Add: 18 Loring R Tze Pannh, Singapore 371028 64172120

For all other AgSource Reporting Centers/AG Authorized Recorders, please contact our 24-hour accident emergency hotline at +65 3135 8222. Alternatively, you may refer to AG website www.ag.com.sg or AG 80 Motorway Exit Service points and download 'AG 80' from iTunes or Google Play.

IMPORTANT NOTES

High Purchase Company/Employer's Loan: MayBank

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
This hereby certifies that the Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 180), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Act, 1989 (Singapore). For Corporate Policies, this Cover Note is valid for 90 days from the commencement date of the period of insurance.

060810012
TAN CHONG CREDIT SUBARU-TEY
911 BUKIT TIMAH ROAD
SINGAPORE 580022

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORIZED REPRESENTATIVE Sub Chapter 200.100

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SME5343Y	MODEL : IMPREZA 5D 2.0I-S EYESIGHT AWD CVT
REF NO:INS/IC/CHI/0236/2019	YEAR: 03-OCT-2018
ENGINE NO: FB20YE58245	CHASSIS NO: JF1GT7KL5JG045954
DOA: 31/05/2019	TOA: 1045HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER,FRT PANEL & BONNET	\$1250.00 <i>500</i>
2.	RESPRAY FRONT BUMPER,FRT PANEL & BONNET	\$1000.00 <i>400</i>
3.	REMOVE & REFIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR <i>nn</i>	\$171.00 <i>X</i>
4.	MECHANICAL REPAIRS – ALTERNATOR,COMPRESSOR,STEERING PUMP <i>nn</i>	\$171.00 <i>X</i>
5.	FAULT DIAGNOSTIC <i>nn</i>	\$235.00 <i>X</i>
6.	TO CONDUCT BOTH FRONT LIGHTING TEST	\$28.00 <i>✓</i>
7.	SUNDRIES	\$100.00 <i>20</i>
8.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$125.00 <i>✓</i>
9.		
10.		
Total Labour		\$3080.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	<i>Kenneth</i>
HP / EMAIL:	<i>969106631</i>
BEFORE PAINT:	<i>Yes</i>
DAYS GIVEN:	<i>03 days</i>

Authorised
Penny Bepary

9/19/20

I, the Auto Consultants, hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Estimate

Date 06 / 01 / 2019

001 / 002

Name	QUOTATION FOR SME5343Y	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G14
		Body Model	GT7BKBL
		Vin-Code	JF1GTTNLSJG045954

Part Number	Part Code Name	Part Code	Q'ty	Price
57702FL300	BUMPER FACE-FRONT ✓	FIG-590 57704	1	Bu 468.00 ✓
57711FL0109P	BACK BEAM COMPLETE-FRONT	FIG-590 57711	1	1 348.00 X
57705FL020	ENERGY ABSORBER-FRONT BUMPER ✓	FIG-590 57705	1	cm 60.20 ✓
57705FL001	ENERGY ABSORBER-UPPER ✓	FIG-590 57705B	1	Bu 65.90 ✓
57705FL070	ENERGY ABSORBER-LOWER ✓	FIG-590 57705C	1	cm 38.00 ✓
57731FL150	COVER-UPPER	FIG-590 57730	1	Sm 22.70 X
57707FL060	BRACKET-BUMPER,FRONT LOWER ✓	FIG-590 57707AE	1	Sm 36.00 ✓ X
57735FL000	SEAL-FRONT BUMPER ✓	FIG-590 57735A	1	1 21.60 —
57731FL120	COVER-FRONT BUMPER ✓	FIG-590 57731	1	Bu 10.80 ✓
57707FL000	BRACKET-FRONT BUMPER CORNER,RIGHT	FIG-590 57707AF	1	11 38.00 ✓
57707FL010	BRACKET-FRONT BUMPER CORNER,LEFT	FIG-590 57707AG	1	Sm 38.00 X
57707FL020	BRACKET-FRONT BUMPER SIDE,RIGHT	FIG-590 57707F	1	11 21.60 ✓
57707FL030	BRACKET-FRONT BUMPER SIDE,LEFT	FIG-590 57707G	1	11 21.60 ✓ X
57731FL040	COVER-FOG LIGHT,RIGHT ✓	FIG-590 84953N	1	11 64.80 ✓
57731FL050	COVER-FOG LIGHT,LEFT ✓	FIG-590 84953O	1	11 64.80 ✓
53029FL0819P	PANEL COMPLETE-RADIATOR	FIG-505 53010	1	Sm 376.80 X
		Page-Total		1,690.80

Memo

Grand Total

9,066.90

Tel

Estimate

Date 06 / 01 / 2019

002 / 002

Name	QUOTATION FOR SME5343Y	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G14
		Body Model	GT7BKBL
		Vin-Code	JF1GT7YKL5JG045954

Part Number	Part Code Name	Part Code	Q'ty	Price
91123FL020	MOLDING-FRONT GRILLE RIGHT	FIG-911 91123C	1	Sen 108.00
91123FL030	MOLDING-FRONT GRILLE LEFT ✓	FIG-911 91123D	Sen 1	cm 108.00
91123FL050	MOLDING-FRONT GRILLER ✓	FIG-911 91123F	1	cm 129.80
91122FL000	FRONT GRILLE-BASE ✓	FIG-911 91122B	1	cm 108.00
93013VA090	ORNAMENT ✓	FIG-919 91174	1	Sen 64.80
84002FL100	LAMP ASSEMBLY-HEAD RIGHT ✓	FIG-840 84001A	1	mgm 2,520.00
84002FL110	LAMP ASSEMBLY-HEAD LEFT	FIG-840 84001B	1	Sen 2,520.00
84501AJ060	FOG LIGHT ASSEMBLY-FRONT	FIG-845 84501B	2	Sen 544.00
57229FLD109P	HOOD COMPLETE-FRONT	FIG-550 57220	1	re 1,072.80
90815FL410	INSULATOR-FRONT HOOD	FIG-956 90815B	1	Sen 64.80
86636FL020TQ	COVER ASSEMBLY-LAMP WASHER NOZ ZLE RIGHT	FIG-877 86636NA ✓	1	my 54.00
86636FL000	NOZZLE-LAMP WASHER,RIGHT	FIG-877 86636N	1	Sen 82.10
		Page-Total		7,376.10
		Sub-Total		9,066.90
		Total		9,066.90
		Tax		0.00
		Grand Total		9,066.90

Memo

Grand Total
9,066.90

12,346/-

--

Tel



Motor Image Enterprises Pte Ltd
19 Lorong 8 Tua Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SME-5343-Y

Surveyor: _____

DESCRIPTION	PART NO	AMOUNT
1 COVER ASSEMBLY. LAMP. WASH/W	86636FL03046 MS	\$57.00 ✓ A
2 NOZZLE LAMP. WASH/W	86636FL010 CRA	\$82.10 ✓ A
3 AIR. G10B	73233FL010 CRA	\$18.00 ✓ A
4 front Number plate	WM001 BT	\$45.00 ✓ A14
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		

MotorImage

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0236/2019
DATE : 04-JUN-2019

ALG ASIA PACIFIC INSURANCE PTE LTD
78 SHEENTON WAY
#07-16 ALG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : TAI BENJAMIN YAT CHING
ADDRESS : 53 GRANGE ROAD
#16-07 SPRING GROVE
S(249565)
TELEPHONE NO : 9185 9827

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1800117538
VEHICLE NO : SME5343Y
MODEL CODE : GT7BREL
MODEL/YEAR : IMPREZA 5D 2.0I-S EYESIGHT AND CVT
ENGINE NO : F520Y58245
CHASSIS NO : JF1GT7RL5JG045954
MILEAGE : 3634 KM
DATE IN : 04/06/2019
LIABILITY : 0.00
EXCESS CLAUSE : 800.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 31/05/2019

Print Date : 04/10/2019
Print Time : 15:30:44

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TDA PATCH
SINGAPORE 319235

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNE5343Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OCCLAIM	CONDUCT BODWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG DATE:31/05/2019 TIME:1045HRS LOCATION:ORCHARD TURN, TAKASHIMAYA CARPARK EXIT		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER, FRONT PANEL & BONNET	500.00	500.00
4	ZZ/003	RESPRAY FRONT BUMPER & FRT PANEL	400.00	400.00
5	ZZ/004	TO CONDUCT BOTH FRONT LIGHTING TEST	28.00	28.00
6	ZZ/005	SUNDRIES	20.00	20.00
7	ZZ/006	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	125.00	125.00
TOTAL LABOUR CHARGES			1073.00	1073.00

MYTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNE5343Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 BUMPER PUNCHING F	57702FL300				468.00 OK
2 ENR ABSORB FL UPR	57705FL001				65.90 OK
3 ENR ABSORB FOAM STD	57705FL020				60.20 OK
4 ENR ABSORB LMR F STD	57705FL070				38.00 OK
5 BRKT CORNER F PHIRH	57707FL000				36.00 OK
6 BRKT SD F RH	57707FL020				21.60 OK
7 COVER FOG F STD RH	57731FL040				64.80 OK
8 COVER FOG F STD LH	57731FL050				64.80 OK
9 COVER HOOK F STD	57731FL120				10.80 OK
10 SEALING BUMPER F PHI	57735FL000				21.60 OK
11 AIR GUIDE LH (SUPP)	73233FL010			CM	18.00 OK ✓
12 LAMP ASSY HEAD	84002FL100				2520.00 OK
13 NOZZLE H L WASHER LH (SUPP)	86636FL010			CM	82.10 OK ✓
14 NOZZLE COVER ASSYRH	86636FL020TQ				54.00 OK
15 NOZZLE COVER ASSYLH (SUPP)	86636FL030W6			MT	54.00 OK ✓
16 GRILLE F BASE PHI	91122FL000				108.00 OK
17 MOLDING WG FLT PHI	91123FL020				108.00 OK ✓
18 MOLDING RING PAINTPHI	91123FL050				129.60 OK ✓
19 ORNAMENT F SIX	93013VA090				64.80 OK ✓
20 FRONT NUMBER PLATE	W4001		B7	45.00	OK ✓
SUB TOTAL		0.00	0.00	45.00	3990.20
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	1197.06
GRAND TOTAL		0.00	0.00	45.00	2793.14
OVERALL TOTAL		2838.14			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYEH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SRE5343Y

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	45.00
S/LIST ITEM	3990.20
LESS 30 %	-1197.06
S/LIST AMOUNT	2793.14
TOTAL LABOUR CHARGES	1073.00
TOTAL SPARE PARTS CHARGES	2838.14
TOTAL CHARGES	3911.14
LESS EXCESS	800.00
TOTAL	3111.14
ADD 7 % GST	217.78
GRAND TOTAL	3328.92



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137
 Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L507025

**For cash sales, payment will be
 endorsed on this invoice and no
 separate receipt will be issued.**

DATE REC'D: 04-Jun-2019

SERVICE ADVISOR: H001

JOB No.: L502289

MILEAGE: 3634

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: IMPREZA 5D 2.0I-S EYESIGHT AWD CVT
ENGINE No.: FB20YE58245
CHASSIS No.: 1F1GT7KL5JG045954
REGISTRATION No.: SME5343Y

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	ODCLAI CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM) AGAINST SME5343Y AIG INSURED	
2	REMARK CONDUCT OD CLAIM AIG DATE:31/05/2019 TIME:1045HRS LOCATION:ORCHARD TURN,TAKASHIMAYA CARPARK EXIT	
3	INS01 FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
4	INS02 IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
5	INS03 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
6	INS04 SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
7	INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
8	INS06 THE OWNER IS REQUIRED.	
9	INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
10	INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
11	INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
12	REMARK REPAIR/REPLACE FRT BUMPER,FRT PANEL & BONNET	500.00
13	REMARK RESPRAY FRT BUMPER & FRT PANEL	400.00
14	REMARK TO CONDUCT BOTH FRT LIGHTING TEST	28.00
15	REMARK SUNDRIES	20.00
16	REMARK REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	125.00
	TOTAL(LABOUR)	1,073.00
1	BUMPER PUNCHING F	327.60

Certified True Copy



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel (65) 64170100/101 Fax (65) 62535535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel (65) 64764776 Fax (65) 64791137
 Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L507025

For cash sales, payment will be
 endorsed on this invoice and no
 separate receipt will be issued.

DATE REC'D: 04-Jun-2019

SERVICE ADVISOR: HOOI

JOB No.: L502289

MILEAGE: 3634

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING, S(079120)
TELEPHONE: 91007211
MODEL: IMPREZA 5D 2.0I-S EYESIGHT AWD CVT
ENGINE No.: FB20YE58245
CHASSIS No.: JF1GT7KL5JG045954
REGISTRATION No.: SME5343Y

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
2	57702FL300(Qty : 1 @ 468.00 each(Discount 30.00%)) ENR ABSORB PL UPR	46.13
3	57705FL001(Qty : 1 @ 65.90 each(Discount 30.00%)) ENR ABSORB FOAM STD	42.14
4	57705FL020(Qty : 1 @ 60.20 each(Discount 30.00%)) ENR ABSORB LWR F STD	26.60
5	57705FL070(Qty : 1 @ 38.00 each(Discount 30.00%)) BRKT CORNER F FHIRH	25.20
6	57707FL000(Qty : 1 @ 36.00 each(Discount 30.00%)) BRKT SD F RH	15.12
7	57707FL020(Qty : 1 @ 21.60 each(Discount 30.00%)) COVER FOG F STD RH	45.36
8	57731FL040(Qty : 1 @ 64.80 each(Discount 30.00%)) COVER FOG F STD LH	45.36
9	57731FL050(Qty : 1 @ 64.80 each(Discount 30.00%)) COVER HOOK F STD	7.56
10	57731FL120(Qty : 1 @ 10.80 each(Discount 30.00%)) SEALING BUMPER F FHI	15.12
11	57735FL000(Qty : 1 @ 21.60 each(Discount 30.00%)) AIR GUIDE LH	12.60
12	73233FL010(Qty : 1 @ 18.00 each(Discount 30.00%)) LAMP ASSY HEAD	1,764.00
13	84002FL100(Qty : 1 @ 2520.00 each(Discount 30.00%)) NOZZLE H L WASHERLH	57.47
14	86636FL010(Qty : 1 @ 82.10 each(Discount 30.00%)) NOZZLE COVER ASSYRH	37.80
15	86636FL020TQ(Qty : 1 @ 54.00 each(Discount 30.00%)) NOZZLE COVER ASSYLH	37.80
	86636FL030W6(Qty : 1 @ 54.00 each(Discount 30.00%))	

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L507025

For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.

DATE REC'D: 04-Jun-2019

SERVICE ADVISOR: HOOI

JOB No.: L502289

MILEAGE: 3634

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING, S(079120)
TELEPHONE: 91007211
MODEL: IMPREZA 5D 2.0I-S EYESIGHT AWD CVT
ENGINE No.: FB20YE58245
CHASSIS No.: JF1GT7KL5JG045954
REGISTRATION No.: SME5343Y

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
16	GRILLE F BASE FHI 91122FL000(Qty : 1 @ 108.00 each(Discount 30.00%))	75.60
17	MOLDING WG PLT FHI 91123FL020(Qty : 1 @ 108.00 each(Discount 30.00%))	75.60
18	MOLDING RNG PAINTFHI 91123FL050(Qty : 1 @ 129.60 each(Discount 30.00%))	90.72
19	ORNAMENT F SIX 93013VA090(Qty : 1 @ 64.80 each(Discount 30.00%))	45.36
20	FRONT NUMBER PLATE WM001(Qty : 1 @ 45.00 each)	45.00
TOTAL(SPARE PARTS)		2,838.14
less INSURANCE EXCESS		800.00

Subtotal 3,111.14
GST(7%) 217.78
TOTAL \$3,328.92

DATE : 19-Nov-2019

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Ceiling ...



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 310255
T (65) 6417 0333 F (65) 6252 5655
W www.motorimage.net

Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured: TAI BENJAMIN YAT CHING
Address of Insured: 53 GRANGE ROAD #16-07 SPRING GROVE S(249565)
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP
Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225
Place of Accident: ORCHARD TURN, TAKASHIMAYA CARPARK EXIT
Date of Accident: 31/05/2019 Vehicle No: SME5343Y
Policy No: 1800117538 Claim No: _____

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of AIG ASIA PACIFIC INSURANCE PTE LTD settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.
I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:



Company's Chop & Signature

DANIEL A JUDE

Name

10/06/2019

Date

INSURED:

G5459900K

IC No. & Signature/Company's Chop

TAI BENJAMIN YAT CHING

Name

10/06/2019

Date

MotorImage

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jun 2019		06 Jun 2019 11:41 Edit Adj Rpt	S\$3,911.14 Edit Estimates	S\$3,911.14 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TAI BENJAMIN YAT CHING, ID: G5459900K								
Vehicle Reg. No.:	SME5343Y	Date of Loss:	31/05/2019 10:00 - :59 [7 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 7344342413SG	Policy/Cover Note No.:	1800117538 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/06/2019]								
Driver/Custodian:	LIN KERRI JANE (45 / Female), NRIC: G5460293L, Tel: +6598992168 Email: KERRIJLIN@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (06/06/2019): SME5343Y / OD / 31/05/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME5343Y (7344342413SG)
OD
May 31 2019 10:00AM
[TAI BENJAMIN YAT CHING]
Motor Image Enterprises Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
----------------------------------	-------------------------------	------------------------------------	------------------------------	------------------------------	---

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	06/06/19 14:11	General View		Load JPG	☒	
2	06/06/19 14:11	General View		Load JPG	☒	
3	06/06/19 14:11	General View		Load JPG	☒	
4	06/06/19 14:11	General View		Load JPG	☒	
5	06/06/19 14:11	General View		Load JPG	☒	
6	06/06/19 14:11	General View		Load JPG	☒	
7	06/06/19 14:11	General View		Load JPG	☒	
8	06/06/19 14:11	General View		Load JPG	☒	
9	06/06/19 14:11	General View		Load JPG	☒	
10	06/06/19 14:11	General View		Load JPG	☒	
11	06/06/19 14:11	General View		Load JPG	☒	
12	06/06/19 14:11	General View		Load JPG	☒	
13	06/06/19 14:11	General View		Load JPG	☒	
14	06/06/19 14:11	General View		Load JPG	☒	
15	06/06/19 14:11	General View		Load JPG	☒	
16	06/06/19 14:11	General View		Load JPG	☒	
17	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
18	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
19	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
20	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
21	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
22	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
23	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
24	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
25	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
26	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
27	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
28	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
29	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
30	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
31	25/10/19 10:18	Reinspection Photo		Load JPG	☒	
32	25/10/19 10:18	Reinspection Photo		Load JPG	☒	

Documentation					1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	06/06/19 14:10	SME 5343Y GIA.pdf		Load PDF		
2	06/06/19 14:10	DRIVING & CI.pdf		Load PDF		
3	06/06/19 14:10	ESTIMATE.pdf		Load PDF		
4	25/10/19 10:06	ESTIMATE & SUPP MARKED.pdf		Load PDF		
5	02/12/19 14:40	Workshop Invoice		Load PDF		
6	02/12/19 14:40	Discharge Voucher		Load PDF		
7	02/12/19 14:40	Supplementary		Load PDF		

Linked Accident Report Documents

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	03/06/19 16:22	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	03/06/19 15:21	Accident Photo	 Load JPG	☒
2	03/06/19 15:21	Accident Photo	 Load JPG	☒
3	03/06/19 15:21	Accident Photo	 Load JPG	☒
4	03/06/19 15:21	Accident Photo	 Load JPG	☒
5	03/06/19 15:21	Accident Photo	 Load JPG	☒
6	03/06/19 15:21	Accident Photo	 Load JPG	☒
7	03/06/19 15:21	Accident Photo	 Load JPG	☒
8	03/06/19 15:21	Accident Photo	 Load JPG	☒
9	03/06/19 15:21	Accident Photo	 Load JPG	☒
10	03/06/19 15:21	Accident Photo	 Load JPG	☒
11	03/06/19 15:21	Accident Photo	 Load JPG	☒
12	03/06/19 15:21	Accident Photo	 Load JPG	☒
13	03/06/19 15:21	Accident Photo	 Load JPG	☒
14	03/06/19 15:21	Accident Photo	 Load JPG	☒
15	03/06/19 15:21	Accident Photo	 Load JPG	☒
16	03/06/19 15:21	Accident Photo	 Load JPG	☒
17	03/06/19 15:21	Accident Photo	 Load JPG	☒
18	03/06/19 15:21	Accident Photo	 Load JPG	☒
19	03/06/19 15:21	Accident Photo	 Load JPG	☒
20	03/06/19 15:21	Accident Photo	 Load JPG	☒
21	03/06/19 15:21	Accident Photo	 Load JPG	☒
22	03/06/19 15:21	Accident Photo	 Load JPG	☒
23	03/06/19 15:21	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	03/06/19 16:22	Accident Sketch Plan	 Load JPG	☒
2	03/06/19 16:22	Accident Sketch Plan	 Load JPG	☒
3	03/06/19 16:22	OWNER NRIC AND LICENSE	 Load JPG	☒
4	03/06/19 16:22	DRIVER NRIC AND LICENSE	 Load JPG	☒
5	03/06/19 16:22	INSURANCE CERT	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19009943/KSD3E2

Date: 02/12/2019

REFERENCE

Insured/Claimant: TAI BENJAMIN YAT CHING

Policy No: 1800117538

Date of Loss: 31/05/2019

Nature of Claim: OD

Claim No: 7344342413SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME5343Y

Make & Model: SUBARU IMPREZA, 2.0 5D I-S EYESIGHT AWD
CVT (A)

Engine No: FB20YE58245

Reg. Date: 03/10/2018 (Man. Year: 2018)

Chassis No: JF1GT7KL5JG045954

Colour: Metallic Blue

Odometer: 3634 km

Engine Capacity: 1995 cc

Market Value/New Car Price: S\$93,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17

Rear Tyre Size: 205/50 R17

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,599.70	2,858.14	3,741.56	56.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,053.00	1,927.00	64.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,579.70	3,911.14	5,668.56	59.17
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	8,779.70	3,111.14	5,668.56	64.56
+ GST 7.00/7.00% (S\$)	614.58	217.78	396.80	64.56
Nett Amount (S\$)	9,394.28	3,328.92	6,065.36	64.56

INSPECTION

Date of Assignment: 06/06/2019

Date Inspected: 04/06/2019 Inspected At:

Motor Image Enterprises Pte Ltd (Toa Payoh)

19 Lorong 8 Toa Payoh

Singapore 319255

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	Necessary	100.00 FS	*20.00 FS
2	1	*BUMPER FACE-FRONT	Buckled	468.00 FL	*468.00 FL
3	1	*BACK BEAM COMPLETE-FRONT	Repair	346.00 FL	*- FL
4	1	*ENERGY ABSORBER-FRONT BUMPER	Cracked	60.20 FL	*60.20 FL
5	1	*ENERGY ABSORBER-UPPER	Buckled	65.90 FL	*65.90 FL
6	1	*ENERGY ABSORBER-LOWER	Cracked	38.00 FL	*38.00 FL
7	1	*COVER-UPPER	Serviceable	22.70 FL	*- FL
8	1	*BRACKET-BUMPER, FRONT LOWER	Serviceable	36.00 FL	*- FL
9	1	*SEAL-FRONT BUMPER	Necessary	21.60 FL	*21.60 FL
10	1	*COVER-FRONT BUMPER	Missing	10.80 FL	*10.80 FL
11	1	*BRACKET-FRONT BUMPER CORNER, RIGHT	Distorted	36.00 FL	*36.00 FL
12	1	*BRACKET-FRONT BUMPER CORNER, LEFT	Serviceable	36.00 FL	*- FL
13	1	*BRACKET-FRONT BUMPER SIDE, RIGHT	Distorted	21.60 FL	*21.60 FL
14	1	*BRACKET-FRONT BUMPER SIDE, LEFT	Serviceable	21.60 FL	*- FL
15	1	*COVER-FOG LIGHT, RIGHT	Missing	64.80 FL	*64.80 FL
16	1	*COVER-FOG LIGHT, LEFT	Missing	64.80 FL	*64.80 FL
17	1	*PANEL COMPLETE-RADIATOR	Serviceable	376.80 FL	*- FL
18	1	*MOLDING-FRONT GRILLE RIGHT	Scratched	108.00 FL	*108.00 FL
19	1	*MOLDING-FRONT GRILLE LEFT	Serviceable	108.00 FL	*- FL
20	1	*MOLDING-FRONT GRILLER	Cracked	129.60 FL	*129.60 FL
21	1	*FRONT GRILLE-BASE	Cracked	108.00 FL	*108.00 FL
22	1	*ORNAMENT	Scratched	64.80 FL	*64.80 FL
23	1	*LAMP ASSEMBLY-HEAD RIGHT	Mtg Cracked	2,520.00 FL	*2,520.00 FL
24	1	*LAMP ASSEMBLY-HEAD LEFT	Serviceable	2,520.00 FL	*- FL
25	2	*FOG LIGHT ASSEMBLY-FRONT	Serviceable	544.00 FL	*- FL
26	1	*HOOD COMPLETE-FRONT	Repair	1,072.80 FL	*- FL
27	1	*INSULATOR-FRONT HOOD	Serviceable	64.80 FL	*- FL
28	1	*COVER ASSEMBLY-LAMP WASHER NOZZLE, RIGHT	Missing	54.00 FL	*54.00 FL
29	1	*NOZZLE-LAMP WASHER, RIGHT	Serviceable	82.10 FL	*- FL
30	1	*AIR GUIDE LH	Cracked	18.00 FL	*18.00 FL
31	1	*NOZZLE H L WASHER LH	Cracked	82.10 FL	*82.10 FL
32	1	*NOZZLE COVER ASSYLH	Missing	54.00 FL	*54.00 FL
33	1	*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 9,366.00 4,055.20
 - List Item Discount on L Items 30.00/30.00% (\$\$) 2,766.30 1,197.06

Total Parts (\$\$) 6,599.70 2,858.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE FRONT BUMPER, FRT PANEL & BONNET	New	1,250.00	500.00
2	RESPRAY FRONT BUMPER, FRT PANEL & BONNET	New	1,000.00	400.00
3	REMOVE & REFIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR	New	171.00	0.00
4	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	New	171.00	0.00
5	FAULT DIAGNOSTIC	New	235.00	0.00
6	TO CONDUCT BOTH FRONT LIGHTING TEST	New	28.00	28.00
7	REMOVE / REFIX FRT HEADLAMP WASHER & PIPING	New	125.00	125.00
Gross Labour Cost (\$\$)			2,980.00	1,053.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >