



Date of Accident : 06 June 2019

GST Regn. No. : M2-8922054-2

Date : 06 June 2019

Estimate To Repair SJV9176H - KIA Cerato Forte Koup 1.6 AT SX AB
Chassis No : KNAFW611MA5203304

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>Deep cut</i>	\$ 735.00
02	1 pc	front bumper side retainer RH <i>17</i>	\$ 32.00
03	8 ps	front bumper clip @ \$3.50 <i>new</i>	\$ 28.00
04	1 pc	front fender RH <i>DD / 3rd</i>	\$ 278.00
05	1 pc	front mudflap RH <i>cut</i>	\$ 50.00
06	1 pc	front door RH <i>DD / 3rd</i>	\$ 890.00
07	1 pc	front door outer moulding <i>new</i>	\$ 54.00
08	1 pc	rear fender RH <i>DD / 3rd</i>	\$ 750.00
09	1 pc	rear fender quarter glass weatherstrip <i>new</i>	\$ 112.00
10	1 pc	rear bumper <i>Deep cut</i>	\$ 780.00
11	1 pc	rear bumper side retainer RH <i>17</i>	\$ 32.00
12	8 ps	rear bumper clip @ \$3.50 <i>new</i>	\$ 28.00
13	1 pc	front shock absorber RH <i>17</i>	\$ 380.00
14	1 pc	front lower arm RH <i>17</i>	\$ 273.00
15	1 pc	headlamp RH <i>cut</i>	\$ 477.00
			\$ 4,899.00
		Less 10 %	\$ 489.90
			\$ 4,409.10
		<u>SPECIAL NETT ITEMS</u>	
16	1 pc	rear fender quarter glass sealant <i>new</i>	\$ 6.00
17	2 ps	wheel rim (RHF & RHR) @ \$450.00 <i>cut</i>	\$ 900.00
18	2 ps	tyre (RHF & RHR) @ \$350.00 <i>new</i>	\$ 700.00
			\$ 1,606.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of door fittings and perform water seepage test.	\$ 80.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00
03		To remove and refit rear fender quarter glass RH.	\$ 80.00
04		To transfer of tyre, rim and on wheel balancing.	\$ 160.00
05		To check steering geometry and computer wheel alignment.	\$ 80.00
06		To check electrical lighting concerned.	\$ 50.00
07		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ <i>17</i> 120.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SMA8223L
Date of Accident : 06 June 2019

Miss Gwee Shu Hui

Date : 06 June 2019

Estimate To Repair SJV9176H - KIA Cerato Forte Koup 1.6 AT SX AB
Chassis No : KNAFW611MA5203304

S/No	Quantity	Description	Amount
09		<u>LABOUR & MISC. CHARGES</u>	
		Putty and spray painting of the affected portion.	\$ 1,500.00
			\$ 3,170.00
		Total	\$ 9,185.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1100

68498
5479