

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5807X**AAD1906-007***Not Authorised
L1 Reg. @ 3250/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5807X

VF1ABL15AUC282208

RENAULT

LATITUDE

1.6.19

AIG

3/8/2015

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Di</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08 X
1	HEADLAMP RH	\$	<i>SL</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84
1	TOW COVER FRT	\$	<i>SL</i> 28.61
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79
1	BONNET	\$	<i>N</i> 1,941.63
1	BONNET INSULATOR	\$	<i>SL</i> 405.73
1	BONNET STRUT LH	\$	<i>SL</i> 88.61
1	BONNET STRUT RH	\$	<i>SL</i> 88.61
1	BONNET HINGE LH	\$	<i>N</i> 348.31
1	BONNET HINGE RH	\$	<i>N</i> 348.31
1	BONNET LOCK	\$	<i>N</i> 305.48
1	BONNET CABLE	\$	<i>SL</i> 119.19

Trans-cab Auto Services Pte Ltd**AAD1906-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5807X

1	BONNET CABLE COVER	\$	161.03	} X
1	BONNET SEAL OUTER	\$	92.36	
1	BONNET SEAL INNER	\$	157.28	
1	DOOR PANEL FRT RH	\$	2,844.66	
1	DOOR MIRROR ASSY RH	\$	1,483.40	
1	DOOR MIRROR GLASS RH	\$	148.20	
1	DOOR MIRROR BACK COVER RH	\$	218.46	
1	LOWER ARM RH L70Y	\$	685.76	
1	KNUCKLE ARM RH L70Y	\$	846.98	
1	ABSORBER FRT RH L70Y	\$	360.54	
1	DRIVESHAFT RH	\$	1,747.45	
1	STABILIZER BAR FRT	\$	604.65	
1	WIPER RESERVOIR MOTOR	\$	270.06	
1	WIPER RESERVOIR	\$	348.25	
1	WIPER RESERVOIR NECK	\$	136.11	
1	DOOR HARNESS WIRE RH	\$	2,670.00	
TOTAL		\$	27,137.40	
10%		\$	2,713.74	
		\$	24,423.66	

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	60sn	} X
1	FRONT DOOR STICKER 'Classic'	\$	80.00	15sn	
1	BUMPER CLIP FRT	\$	66.00	—	
1	BUMPER BRACKET CLIP FRT RH	\$	12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00		
1	WHEELARCH CLIP FRT RH	\$	30.50		
1	FRONT RIGHT TYRE	\$	300.00		
1	FRONT RIGHT TYRE RIM	\$	380.00		
1SET	Front licence plate with holder	\$	80.00		
1SET	RADIATOR GRILLE SCREW	\$	16.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00		
1	WINDSCREEN SEALANT	\$	253.80		
1	FRONT WINDSCREEN MOULDING	\$	120.00		

Trans-cab Auto Services Pte Ltd**AAD1906-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5807X

1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 <i>X</i>
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30 <i>X</i>
2	BONNET STRUT L70Y	\$	<i>nn</i> 88.61 <i>X</i>
2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31 <i>X</i>
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85 <i>X</i>

TOTAL \$ 1,882.88**TOTAL PARTS \$ 26,306.54****LABOUR**

Putty and spray painting of the affected portion. \$ 6,000.00 *4401*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 6,000.00 *4001*

To rust-proofing of the affected areas. \$ 170.00 *301*

To transfer of front windscreen fittings and conduct water seepage test. \$ *nn* 170.00 *X*

To transfer of front fender fittings, attachment and perform water seepage test. \$ *nn* 380.00 *X*

To check steering geometry and computer wheel alignment \$ *nn* 220.00 *X*

To dismantle and refit front end suspension, undercarriage parts, final checking and testing. \$ *nn* 380.00 *X*

To transfer of front bumper fittings, attachment and perform water seepage test. \$ *nn* 380.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ *nn* 380.00 *X*

Trans-cab Auto Services Pte Ltd**AAD1906-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5807X

To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>

TOTAL	\$	15,940.00
--------------	-----------	------------------

Over All Total	\$	42,246.54
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~**20 DAYS**~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: