

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

LIM THIAM YONG
c/o 46 Lenton Plain
Singapore 786548

Not Notified
61 Rm @ 4550h
Running After Paint
6 days

Date: 1/6/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : HONDA VEZEL / SKW 7836 H		
1 pc	rear boot lid <i>1100.90</i>	<i>By</i> 1,264.90
1 pc	rear boot lock <i>198.50</i>	<i>By</i> 316.20
1 pc	rear boot outer garnish <i>399.20</i>	<i>ngc m</i> 564.70
1 pc	rear boot inner trim	<i>Ln</i> 515.40
1 pc	rear boot emblem "VEZEL"	<i>Ln</i> 67.50
1 pc	rear boot emblem "LOGO"	<i>Ln</i> 62.80
1 pc	rear boot lamp <i>380.60</i>	<i>ngc m</i> 675.20
1 pc	rear tail lamp	<i>Ln</i> 598.70
1 pc	rear boot lock catch	<i>Ln</i> 48.10
1 pc	rear bumper <i>508.50</i>	<i>Ln</i> 895.70
2 pcs	rear bumper side cover <i>115.70</i>	<i>OLSSA X @</i> 437.60
2 pcs	rear bumper side retainer	<i>@</i> 64.40
1 pc	rear wheel arch protector <i>245.80</i>	<i>Ln</i> 128.80
2 pcs	rear bumper reflector <i>151</i>	<i>Ln</i> 419.40
1 pc	rear end inner panel	<i>Ln</i> 633.40
1 pc	rear end outer panel	<i>Ln</i> 577.60
1 pc	rear end panel garnish	<i>Ln</i> 549.70
1 pc	remote lock sensor <i>180</i>	<i>Ln</i> 473.20
1 pc	rear bumper lower dust cover	<i>Ln</i> 350.80
1 pc	remote lock buzzer	<i>Ln</i> 315.60
		<i>Ln</i> 215.40
		sub-total 9,548.30
		less 20% 1,909.66
		sub-total 7,638.64
1 pc	windscreen glass sealant	<i>Ln</i> 60.00
1 pc	rear bumper body kit set	<i>Ln</i> 1,080.00
	reverse sensor	<i>Ln</i> 400.00
		sub-total 9,178.64
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	1,100.00
	To check wiring system.	60.00
	To apply putty & spray painting on affected areas.	1,100.00
	To apply rust proofing on affected areas.	150.00
	To apply water proof sealant on affected areas.	100.00
	To remove rear windscreen glass to enable repair.	140.00
	total	11,828.64