

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

LIM THIAM YONG
c/o 46 Lentor Plain
Singapore 786548

Not Authaised
 11 Sep 87
 Murray Allen Paine
 6 day

Date : 1/6/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : HONDA VEZEL / SKW 7836 H	
1 pc	rear boot lid	1,264.90
1 pc	rear boot lock	316.20
1 pc	rear boot outer garnish	564.70
1 pc	rear boot inner trim	515.40
1 pc	rear boot emblem "VEZEL"	67.50
1 pc	rear boot emblem "LOGO"	62.80
1 pc	rear boot lamp	675.20
1 pc	rear tail lamp	598.70
1 pc	rear boot lock catch	48.10
1 pc	rear bumper	895.70
2 pcs	rear bumper side cover	875.20
2 pcs	rear bumper side retainer	128.80
1 pc	rear wheel arch protector	419.40
2 pcs	rear bumper reflector	633.40
1 pc	rear end inner panel	577.60
1 pc	rear end outer panel	549.70
1 pc	rear end panel garnish	473.20
1 pc	remote lock sensor	350.80
1 pc	rear bumper lower dust cover	315.60
1 pc	remote lock buzzer	215.40
	sub-total	9,548.30
	less 20%	1,909.66
	sub-total	7,638.64
1 pc	windscreen glass sealant	60.00
1 pc	rear bumper body kit set	1,080.00
	reverse sensor	400.00
	sub-total	9,178.64
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	1,100.00
	To check wiring system.	60.00
	To apply putty & spray painting on affected areas.	1,100.00
	To apply rust proofing on affected areas.	150.00
	To apply water proof sealant on affected areas.	100.00
	To remove rear windscreen glass to enable repair.	140.00
	total	11,828.64