



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 4125 G

Parts	(a) Cost / List Price Items	\$	3,192.48
	Plus/Less 25%	\$	798.12
	Total of Cost / List	\$	2,394.36
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	2,240.00
Total		\$	4,634.36

Not Authorized
Running B&P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Henneth</u>
Company	:	<u>LKK</u>
Survey conducted on	:	<u>6/6/19</u> at _____
<u>Remarks By Surveyor</u>		
(a)	The repair of this vehicle is <u>authorized</u> / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>04</u> day(s)
(c)	Resurvey	: Required / Not Required <u>Not Required</u>
(d)	Excess	:\$ _____
(e)	Signature of surveyor	: <u>Sc</u> Date: <u>6/6/19</u>



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLN 4125 G**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU603556696**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$497.50		7
2	Rear bumper clip	10	\$40.00		7
3	Rear bumper side retainer RH	1	\$112.70		X
4	Rear bumper lower garnish RH	1	\$149.70		X
5	RH rear hub cab	1	\$195.65		—
6	RH rear door	1	\$1,181.75		X
7	RH rear door hinge top	1	\$78.34		X
8	RH rear door hinge bottom	1	\$78.34		X
9	RH rear door lock	1	\$411.70		X
10	RH rear door checker	1	\$156.79		X
11	RH rear door weatherstrip	1	\$178.40		X
12	RHR door glass outer moulding	1	\$111.61		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

