

11/11  
6/6 (THURS)

KK



**ESTEEM  
PERFORMANCE**

**ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

**Repair Estimates**

SLN 4125 G

Finalised

Parts (a) Cost / List Price Items

Plus/Less 25%

Total of Cost / List

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

Total Parts Cost

Labour

Total

\$ 195.65 3,192.48

\$ 42.91 798.12

\$ 146.74 2,394.36

\$ 1315.00 2,240.00

\$ 1461.74 4,634.36

The above total will be subjected to 7% G.S.T.

Not Authorized

Runny Bepain

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Kenneth

LKLC

6/6/19

at

Sc

Date:

6/6/19

**ESTEEM  
PERFORMANCE****ESTEEM PERFORMANCE PTE LTD**Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sgSpare Parts

Vehicle No. : **SLN 4125 G** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA PRIUS** Year Manufacture : **2017**  
Chassis No : **JTDKB3FU603556696** Engine No. :  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$497.50		X
2	Rear bumper clip	10	\$40.00		X
3	Rear bumper side retainer RH	1	\$112.70		X
4	Rear bumper lower garnish RH	1	\$149.70		X
5	RH rear hub cap	1	\$195.65		—
6	RH rear door	1	\$1,181.75		X
7	RH rear door hinge top	1	\$78.34		X
8	RH rear door hinge bottom	1	\$78.34		X
9	RH rear door lock	1	\$411.70		X
10	RH rear door checker	1	\$156.79		X
11	RH rear door weatherstrip	1	\$178.40		X
12	RHR door glass outer moulding	1	\$111.61		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N

10/5/15





Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: [www.esteemperf.com.sg](http://www.esteemperf.com.sg)

Vehicle No. : SLN 4125 G  
Make & Model : TOYOTA PRIUS

Submit By : Carmen Lim  
Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1315