

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: <u>P18</u>	\$5 <u>1548.95</u> + 2 days) Reduction: <u>\$26,495.45</u> 95		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: <u>7/11/2020</u> Confirm with: <u>WAT YIN</u>	Email ☐ Call ☐	
Final Liability: <u># 100</u>	(Agreed / Assessed) BOLA S/N No.: <u>37</u>	If NO or B 28. Ass. Lia: <u>01 rear ended TP</u>	
Repair Cost: <u>(W/loss)</u>	\$5 <u>1657.76</u>		
Loss of Rental (LOR)	\$5 <u>453.60</u> 1 4 days) x \$113.40		
Loss of Use (LOU)	\$5 <u>15</u> x days)		
Loss of Income (LOI)	\$5 <u>160.00</u> (5 40 x 4 days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
GLA/CTA Search	\$5 <u>-</u>		
Medical	\$5 <u>-</u>	1) Claim status: <u>Normal/Reject/Private Settle</u>	
Disbursement	\$5 <u>-</u>	2) Report Format: <u>TP</u>	
Legal Cost	\$5 <u>-</u>	3) Survey fee: <u>\$600.</u>	
Total:	\$5 <u>2000.96</u>	Global Sum \$5:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
Payee 1:	\$5 <u>2000.96</u>	Name 1:	<u>Trans Carz Auto Services Pte Ltd</u>
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1 File peris to

PIP \$1548.93 (Red: \$76,975.43 / 951.7)

* 2 repair days + 1 PPS + 1 PH = 4 days

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Veh No: S140 329L Yr Regn: 05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pro c.c. 1798Colour: White / Red A/C: Insured / Std / NI / NASp. Reading: 4938 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK 83FU X 03 08 0453Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 1/6/19

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 4/6/19

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. \$ _____

Fees:

Others:

TOTAL

Trans-cab Auto Services Pte Ltd

AAD1906-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 329L

Not Authored
Resony B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD 329L

JTDKB3FUX03080453

TOYOTA

PRIUS

1.6.2019

III

24/5/2019

PART**LIST**

1	1 REAR BUMPER	\$	cm / Bu	458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	NL	318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	SL	14.70	X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	Red / Bu	552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	0.1	112.70	✓
6	1 REAR BUMPER SIDE RETAINER RH	\$	SL	112.70	X
7	1 REAR TAILGATE	\$	H	1,547.27	} X
8	1 REAR TAILGATE OUTER GARNISH	\$	SL	905.10	
9	1 COVER, REAR COMBINATION LAMP, RH	\$	SL	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	SL	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	SL	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	SL	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	SL	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	SL	51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	SL	365.20	
16	1 REAR END PANEL	\$	H	602.10	
17	1 TAILLAMP LOWER RH	\$	SL H	548.40	} X
18	1 TAILLAMP UPPER RH	\$	SL	557.90	
19	1 REAR BUMPER SIDE RH	\$	SL	232.00	
20	1 REAR BUMPER SIDE LH	\$	int/m	232.00	
21	1 TAILLAMP LOWER LH	\$	NL	548.40	
22	1 TAILLAMP UPPER LH	\$	NL	557.90	
23	1 PAN, REAR FLOOR	\$	H	572.10	
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	H	77.00	
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	H	192.90	
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	H	77.00	
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	H	192.90	
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	H	290.50	

Trans-cab Auto Services Pte Ltd

AAD1906-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 329L

29	1 REAR FENDER LH	\$	<i>R</i>	817.50	<i>X</i>
30	1 REAR FENDER RH	\$	<i>R</i>	817.50	<i>X</i>
		\$		11,305.97	
25%		\$		2,826.49	
		\$		8,479.48	

Special Nett

1	1SET PARKING AID	\$	<i>R</i>	700.00	<i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>R</i>	22.00	<i>✓</i>
3	2 REAR WINDSCREEN SELANT	\$	<i>R</i>	80.00	<i>X</i>
4	1 WINDSCREEN MOULDING	\$	<i>R</i>	100.00	
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>R</i>	100.00	
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>R</i>	47.00	
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>R</i>	52.90	
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>R</i>	53.50	
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>R</i>	80.00	
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>R</i>	80.00	
11	1 REAR BUMPER PROTECTOR	\$	<i>R</i>	100.00	<i>for</i>

TOTAL \$ 1,415.40**TOTAL PARTS \$ 9,894.88****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>R</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>

Trans-cab Auto Services Pte Ltd

AAD1906-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 329L

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To repair and realign rear exhaust pipe.	\$	~ 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	~ 170.00 X

TOTAL \$ 10,150.00**Over All Total \$ 28,524.36****(PART-BY-PART) Repair Days****20-DAYS***2 days*

LXK Auto Consultants hereby notify the Repairer of the following:

- To survey before start spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey to be a "Without Prejudice" basis
- No direct modification is allowed
- Discrepancy items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD329L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS SDR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C15208
Chassis No.:	JTDKB3FUX03080453
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	24 May 2019
First Registration Date:	24 May 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 May 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	23 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,309.00
COE Rebate Amount:	\$17,847.00
Total Rebate Amount:	\$28,532.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jun 2019

OK

Print Received Message

This mail is associated with :

***SHD329L (MCT19060002)
[SHB6202P]**

TP

TRANS-CAB SERVICES PTE LTD

Jun 1 2019 1:00AM

[COMFORT TRANSPORTATION PTE LTD]

Trans-cab Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/12/2019 10:58 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2270.94) - SHD329L - Claim Handler: Sherini Pillai

Approved:2270.94.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jun 2019 Edit Reg		04 Jun 2019 00:00 Edit Adj Rpt	S\$1,548.92 Edit Estimates	S\$1,548.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD329L	Date of Loss:	01/06/2019 01:00 - :59 [8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19060002	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHB6202P	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (10/12/2019): Alert - Adj Mandate Approved (S\$2270.94) - SHD329L - Claim Handler: Sherini Pillai... - III_SG (21/06/2019): Alert - Adj Mandate Approved (S\$0.00) - SHD329L - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD329L (MCT19060002)
[SHB6202P]
TP
TRANS-CAB SERVICES PTE LTD
Jun 1 2019 1:00AM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/12/19 13:28	General View		Load JPG	☒
2	06/12/19 13:28	General View		Load JPG	☒
3	06/12/19 13:28	General View		Load JPG	☒
4	06/12/19 13:28	General View		Load JPG	☒
5	06/12/19 13:28	General View		Load JPG	☒
6	06/12/19 13:28	General View		Load JPG	☒
7	06/12/19 13:28	General View		Load JPG	☒
8	06/12/19 13:28	General View		Load JPG	☒
9	06/12/19 13:28	General View		Load JPG	☒
10	06/12/19 13:28	General View		Load JPG	☒
11	06/12/19 13:28	General View		Load JPG	☒
12	06/12/19 13:28	General View		Load JPG	☒
13	06/12/19 13:28	General View		Load JPG	☒
14	06/12/19 13:28	General View		Load JPG	☒
15	06/12/19 13:28	Reinspection Photo		Load JPG	☒
16	06/12/19 13:28	Reinspection Photo		Load JPG	☒
17	06/12/19 13:28	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/06/19 19:29	TP ESTIMATE- MARKED		Load PDF	
2	06/06/19 19:29	TP GIA REPORT		Load PDF	
3	05/12/19 16:29	WORKSHOP INVOICE		Load PDF	
4	05/12/19 16:29	RENTAL RECEIPT		Load PDF	
5	05/12/19 16:29	RENTAL MILEAGE		Load PDF	
6	05/12/19 16:29	LOD		Load PDF	
7	04/02/20 10:11	AUTHORISATION TO ACT FORM		Load PDF	
8	04/02/20 10:11	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	07/06/19 09:06	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19009991/KGS3Q2

Date: 04/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SHD329L Insured Vehicle No: SHB6202P
 Vehicle No: SHD329L
 Date of Loss: 01/06/2019 Nature of Claim: TP Claim No: MCT19060002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD329L
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR2C15208
 Reg. Date: 24/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FUX03080453
 Colour: Metallic White/Red Odometer: 4938 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Goodyear 9 mm Rear Left Side: Goodyear 9 mm
 Front Right Side: Goodyear 9 mm Rear Right Side: Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,894.88	1,078.92	8,815.96	89.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,150.00	470.00	9,680.00	95.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,044.88	1,548.92	18,495.96	92.27
+ GST 7.00/7.00% (S\$)	1,403.14	108.42	1,294.72	92.27
Nett Amount (S\$)	21,448.02	1,657.34	19,790.68	92.27
+ Loss of Use (4.0 x S\$40.00/day) (S\$)		160.00		
+ Car Rental (4.0 x S\$113.40/day) (S\$)		453.60		
Nett Liability (S\$)		2,270.94		

INSPECTION

Date of Assignment: 04/06/2019
 Date Inspected: 04/06/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD329L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked/Buckled	458.60 FL	*458.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Serviceable	318.80 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*- FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Dented/Buckled	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Distorted	112.70 FL	*112.70 FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
7	1		*REAR TAILGATE	Repair	1,547.27 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	905.10 FL	*- FL
9	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
11	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	93.60 FL	*- FL
12	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	93.60 FL	*- FL
13	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
14	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	51.20 FL	*- FL
15	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
16	1		*REAR END PANEL	Repair	602.10 FL	*- FL
17	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
18	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
19	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
20	1		*REAR BUMPER SIDE LH	Mtg Cracked	232.00 FL	*232.00 FL
21	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
22	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
23	1		*PAN,REAR FLOOR	Repair	572.10 FL	*- FL
24	1		*EXTENSION,REAR FLOOR SIDE PANEL,RH	Repair	77.00 FL	*- FL
25	1		*EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH	Repair	192.90 FL	*- FL
26	1		*EXTENSION,REAR FLOOR SIDE PANEL,LH	Repair	77.00 FL	*- FL
27	1		*EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH	Repair	192.90 FL	*- FL
28	1		*PANEL,QUARTER WHEEL HOUSE,OUTER LH	Repair	290.50 FL	*- FL
29	1		*REAR FENDER LH	Repair	817.50 FL	*- FL
30	1		*REAR FENDER RH	Repair	817.50 FL	*- FL
31	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
32	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
33	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
35	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
36	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
37	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
38	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
39	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
40	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
41	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					12,721.37	1,417.90
- List Item Discount on L Items 25.00/25.00% (S\$)					2,826.49	338.98
Total Parts (S\$)					9,894.88	1,078.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			10,150.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >