

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 329L**AAD1906-005**

Not Authorised
Assuming Blupaint

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 329L

JTDKB3FUX03080453

TOYOTA

PRIUS

1.6.2019

III

24/5/2019

PART**LIST**

1	1 REAR BUMPER	\$	<i>cm / Bu</i>	458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$		318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	<i>SL</i>	14.70	X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>Red / Bu</i>	552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>D.I</i>	112.70	✓
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i>	112.70	X
7	1 REAR TAILGATE	\$	<i>W</i>	1,547.27	} X
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>SL</i>	905.10	
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i>	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i>	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>SL</i>	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>SL</i>	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i>	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>SL</i>	51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i>	365.20	
16	1 REAR END PANEL	\$	<i>W</i>	602.10	
17	1 TAILLAMP LOWER RH	\$	<i>SL</i>	548.40	} X
18	1 TAILLAMP UPPER RH	\$	<i>SL</i>	557.90	
19	1 REAR BUMPER SIDE RH	\$	<i>SL</i>	232.00	
20	1 REAR BUMPER SIDE LH	\$	<i>my m</i>	232.00	✓
21	1 TAILLAMP LOWER LH	\$		548.40	?
22	1 TAILLAMP UPPER LH	\$		557.90	?
23	1 PAN, REAR FLOOR	\$	<i>W</i>	572.10	} X
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	<i>W</i>	77.00	
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	<i>W</i>	192.90	
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	<i>W</i>	77.00	
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	<i>W</i>	192.90	
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>W</i>	290.50	✓

Trans-cab Auto Services Pte Ltd**AAD1906-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 329L

29	1 REAR FENDER LH	\$	<i>R</i>	817.50	X
30	1 REAR FENDER RH	\$	<i>R</i>	817.50	X
		\$		11,305.97	
25%		\$		2,826.49	
		\$		8,479.48	

Special Nett

1	1SET PARKING AID	\$	<i>Sn</i>	700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>me</i>	22.00	✓
3	2 REAR WINDSCREEN SELANT	\$	<i>ra</i>	80.00	} X
4	1 WINDSCREEN MOULDING	\$	<i>ra</i>	100.00	
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>ra</i>	100.00	
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>ra</i>	47.00	
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>ra</i>	52.90	
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>ra</i>	53.50	} X
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>ra</i>	80.00	
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>ra</i>	80.00	
11	1 REAR BUMPER PROTECTOR	\$	<i>me</i>	100.00	<i>40/ra</i>

TOTAL \$ 1,415.40**TOTAL PARTS \$ 9,894.88****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	<i>220/</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>200/</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>ra</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>50/</i>

Trans-cab Auto Services Pte Ltd**AAD1906-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 329L

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na 170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00 X
To repair and realign rear exhaust pipe.	\$	na 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	na 170.00 X

TOTAL \$ 10,150.00**Over All Total \$ 28,524.36****(PART-BY-PART) Repair Days**~~20 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: