

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

not Approval
Late
10/6/19

L/SS
The price is 1192
Hdy.

PA9956M Toyota Regius

No	Qty	Parts Description		Estimated Parts Price
1	1	Rear bumper assy	Des	\$ 1,260.00 —
2	1	Rear bumper right bracket	11	\$ 86.00 X
3	1	Rear bumper inner beam	11	\$ 287.00 X
4	1	Rear tailgate assy	11	\$ 1,862.00 X
5	1	Rear right taillamp	385.20 Scu	\$ 785.00 —
6	1	Rear right taillamp lower panel	cu)	\$ 120.00 —
7	1	Rear right fender panel assy	11	\$ 6,800.00 X
8	1	Rear right fender glass assy	11	\$ 850.00 X
				\$ 12,050.00
Less 25%				\$ 3,012.50
				\$ 9,037.50

Special Nett Items

1	10	Rear bumper clips	11	\$ 50.00 —
2	1	Rear right fender panel sealant	11	\$ 80.00 X
3	1	Rear right fender glass sealant	11	\$ 80.00 X
4	1	Rear right wheel rim	11	\$ 450.00 X
5	1	Rear right tyre	11	\$ 350.00 X
				\$ 1,010.00

Total Parts

\$ 10,047.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

PA9956M Toyota Regius

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts.	\$ 1,600.00	500
2	To putty and spray painting rear right portion.	\$ 1,600.00	400
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear inner trim to facilitate the repair.	\$ 150.00	60
5	To apply anti rust proofing to rear right affected area.	\$ 1120.00	X
6	To balance rear right wheel.	\$ 17 50.00	X
7	To conduct wheel alignment.	\$ 17 120.00	X
8	To remove and install rear right fender glass to facilitate the repair.	\$ 17 140.00	X
9	Towing service.	\$ 17 100.00	X
Total labour :		\$ 3,930.00	

Total parts : \$ 10,047.50

Total labour : \$ 3,930.00

Total repair cost : \$ 13,977.50