

CP MOTORS PTE LTD160 Sin Ming Drive #05-05 Sin Ming Auto City
575722

Tel No. : 64571357 Fax No. : 64575357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000118

Date : 04/06/2019

Vehicle Num. : SKD301E

Make/Model : BMW 535i Gran Turismo-2011

Chassis/Eng# : WBASN22000C194527

Accident Date : 03/06/2019

Claim No. :

Reference : T/P Claim Against India

Policy No. : MT/00638477

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Front Bumper		1,562.10
2.	1 pc	Front Bumper Logo		91.25
3.	2 pcs	Front Bumper Grille	160.00	320.00
4.	1 pc	Front Bumper Reinforcement		830.20
5.	1 pc	Front Bumper Tow Cover		57.60
6.	1 pc	Front bumper Lower Grille		96.50
7.	2 pcs	Front Bumper Sponge	76.30	152.60
8.	1 pc	Right Front Bumper Nozzle Cover		67.60
9.	2 pcs	Front Bumper Sensor	336.85	673.70
10.	1 pc	Front Number Plate Garnish		79.75
11.	2 pcs	Headlamp	2,949.65	5,899.30
12.	2 pcs	Headlamp Panel	222.25	444.50
13.	1 pc	Front Air Cowling		425.20
14.	1 pc	Front Support Panel Side Garnish LH		205.20
15.	1 pc	Front Support Panel Side Garnish RH		205.20
16.	2 pcs	Front Support Panel Rod	194.65	389.30
17.	1 pc	Air Con Condenser		1,074.25
18.	1 pc	Oil Cooler		944.60
19.	1 pc	Boot Cover		2,625.25
20.	1 pc	Boot Cover Garnish		855.26
21.	1 pc	Boot Cover Emblem		74.10
22.	1 pc	Boot Cover Logo		91.25
23.	1 pc	Boot Cover Emblem		74.10
24.	1 pc	Boot Cover Weather Strip		90.50

CONTINUE / ...

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
575722

Tel No. : 64571357 Fax No. : 64575357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000118

Date : 04/06/2019

Vehicle Num. : SKD301E

Make/Model : BMW 535i Gran Turismo-2011

Chassis/Eng# : WBASN22000C194527

Accident Date : 03/06/2019

Claim No. :

Reference : T/P Claim Against India

Policy No. : MT/00638477

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1 pc	Rear Bumper		2,979.00 ✓
26.	2 pcs	Rear Bumper Reflector	56.80	113.60 ✓
27.	1 pc	Rear Bumper Reinforcement		967.76 ✓
28.	1 pc	Rear Bumper Lower Skirt		273.65 ✓
29.	1 pc	Rear Bumper Inner Lining		333.25 ✓
30.	1 pc	Rear Bumper Tow Cover		82.55 ✓
31.	3 pcs	Rear Bumper Sensor	336.85	1,010.55 ✓
32.	1 pc	Rear Bumper Lower Cover		189.70 ✓
33.	1 pc	Rear Bumper Side Retainer		192.15 ✓
34.	1 pc	Rear Air Matic Cover		234.50 ✓
35.	1 pc	Rear Silencer		1,378.95 ✓
36.	2 pcs	Rear Silencer Heat Shield	345.30	690.60 ✓
37.	1 pc	Sun Roof Roller Blind		1,650.25 ✓
38.	10 pcs	Clip	12.00	120.00 ✓
List TotalS\$:				27,545.82
5.00% Discount S\$:				1,377.29
				26,168.53
1.	1 pc	SPECIAL NETT ITEMS : Front Number Plate		45.00 ✓
Special Nett Total S\$:				45.00
LABOUR :				
Focus Headlamp				60.00 30%

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
575722

Tel No. : 64571357 Fax No. : 64575357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000118

Date : 04/06/2019

Vehicle Num. : SKD301E

Make/Model : BMW 535i Gran Turismo-2011

Chassis/Eng# : WBASN22000C194527

Accident Date : 03/06/2019

Claim No. :

Reference : T/P Claim Against India

Policy No. : MT/00638477

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

Remove/Refix air con condenser, pipe vacuum & top up gas

Transfer Boot Cover Mechanism

Programming, Coding & Resetting

To Install Parking Sensor To New Bumper

Apply Body Sealant To Body Joint

To straighten bonnet cover, front support panel, right/

left front chassis, boot cover hinges, rear end panel,

luggage boot floor panel, replace headlamp panel,

include replacement of parts.

Spray paint on bonnet cover, front support panel,

front bumper, boot cover, rear end panel, luggage boot

floor panel & rear bumper.

Labour charge to replace roller blind.

Labour Total S\$:

160.00

200.00

500.00

200.00

100.00

1,600.00

1,800.00

1,200.00

5,820.00

E. & O.E.

Total S\$:

32,033.53

=====

for CP MOTORS PTE LTD