

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 10 Jun 2019

**Preliminary Advice**

Vehicle No	: YQ744B	Accident Date	: 21/05/2019
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN191681900
Assignment Date	: 06/06/2019	Excess	: S\$500.00
Date of Inspection	: 7/6/2019	Est. Duration of Repair	: 7
Inspection At	: GOLDBELL ENGINEERING PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,522.60
Revised Amount	:S\$	12,300.95
Check Items (Estimated)	:S\$	1,731.65
Total	:S\$	14,032.60
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	26,608.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,392.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :