

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 31 December 2019 11:34 AM
To: Chua, Gek Tiang Ruth; SUR; assignments
Cc: jyue@yusentravel.com.sg
Subject: RE: Recommended survey for SLS1906M - CMTD1902451/RUC
Attachments: SLS1906 PHOTO.pdf

Dear Ruth,

Sorry for the late reply.

According to our surveyor, impact area was at front right of TP vehicle.

Several parts were found damage upon dismantling of the front bumper as a result of the contact.

Please refer to the attached of photos of below parts.

*FRONT BUMPER	refer photo: 8 & 9
*FRONT BUMPER LOWER BLACK GARNISH	refer photo: 16 & 17
*FRONT BUMPER FOG LAMP O/S	refer photo: 50 & 51
*FRONT BUMPER LED LAMP O/S	refer photo: 47 & 48
*FRONT BUMPER FOG LAMP GARNISH O/S	refer photo: 53 & 54
*HEADLAMP ASSY O/S	refer photo: 44 & 45
*FRONT SUPPORT PANEL	refer photo: 34 & 35

Best Wishes for Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 13 December 2019 4:55 PM
To: Chua, Gek Tiang Ruth <ruth.chua@sompo.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: jyue@yusentravel.com.sg
Subject: RE: Recommended survey for SLS1906M - CMTD1902451/RUC

Dear Ruth,

Thank you for the email.

We will check and revert to you.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chua, Gek Tiang Ruth <ruth.chua@sompo.com.sg>

Sent: Friday, 13 December 2019 4:51 PM

To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: jyue@yusentravel.com.sg

Subject: Recommended survey for SLS1906M - CMTD1902451/RUC

LKK ref: CS/SMO19010002/UQD3N2

Sompo ref: CMTD1902451/RUC

Dear LKK

Please advise the rationale for the parts recommended for repairs for TP vehicle SLS1906M.

The parts are enclosed as below.

We have copied insured in the email for this matter.

- *FRONT BUMPER
- *FRONT BUMPER LOWER BLACK GARNISH
- *FRONT BUMPER FOG LAMP O/S
- *FRONT BUMPER LED LAMP O/S
- *FRONT BUMPER FOG LAMP GARNISH O/S
- *HEADLAMP ASSY O/S
- *FRONT SUPPORT PANEL

Thank you.

Best Regards

Ruth Chua

Claims Division

D: 6329 5153 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom

disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.