

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

10-Jun-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6256 D

1 pc	Rear bumper o/s reflector @ \$46.00	X	500	\$	46.00
				Less 10%	\$ 4.60
					<u>\$ 41.40</u>

S/NETT

1 pc	Rear o/s fender sticker	—		\$	60.00
------	-------------------------	---	--	----	-------

Sundry

\$ ~~50.00~~
20

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

\$ ~~200~~
550.00

To putty and spray painting on rear bumper, rear o/s fender

\$ ~~360~~
400.00

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ X 4
\$ 1,221.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

LKK & Co. Consultants hence notify the Repairer as following:

- To advise the estimate of repair painting
- To advise the estimate of repair during resurvey
- To advise the estimate of repair on the off
- To advise the estimate of repair on the "on-site" basis
- To advise the estimate of repair on the "on-site" basis
- To advise the estimate of repair on the "on-site" basis

Acknowledged by Repairer
Signature:
Date:

Ka hwa 16/6/19

10/6/19 1700hrs.

2 hrs.

4/3

After Repair p lth

14/6/19

total 144 \$ 640 / 2 hrs