

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-Jun-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6256 D

1 pc	Rear bumper o/s reflector @ \$46.00	X	\$	46.00
		Less 10%	\$	4.60
			\$	41.40

S/NETT

1 pc	Rear o/s fender sticker	✓	\$	60.00
	Sundry		\$	50.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	550.00 200
	To putty and spray painting on rear bumper, rear o/s fender		\$	400.00 260
	To apply rustproofing on the repaired and replaced panels.		\$	120.00 X
			\$	1,221.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Lun 16/6/19

10/6/19 1700hrs.

2 hrs

4/5

After Repair p lth

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: