

Cecilia

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0578/2018
DATE : 17-DEC-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAN YA LI
ADDRESS : 937 BUKIT TIMAH ROAD
#03-35
S(589646)
TELEPHONE NO : 96773911

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC3255B
VEHICLE NO : SLV5251B
MODEL CODE : JDRNRRET32EWAF---A
MODEL/YEAR : NISSAN X-TRAIL FACELIFT MY2017
ENGINE NO : MR20146612C
CHASSIS NO : JN1JANT3220010464
MILEAGE : 1 KM
DATE IN : 17/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 14/12/2018

20/08/19

PAID

0/5

PAID

#140 X04

= \$560 tax

= \$599.20

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	240.00 /
2 RRSCH	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	.00
3 RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH FRONT	480.00	.00
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	.00
5 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	103.00 /
6 ZZ/001	REPAIR AND RENEW RH FRONT FENDER,RH FRONT DOOR	1200.00	780.00 /
7 ZZ/002	S/PAINT RH FRONT FENDER,RH FRONT DOOR	750.00	500.00 /
8 ZZ/003	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING RH FRONT	15.00	15.00 /
9 ZZ/004	RENEW RH FRONT TYRE 225/55R19 B/S H/L422		
	TOTAL LABOUR CHARGES	3208.00	1638.00

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	225/55R19HL422PLUS B/S TYRE RH FRONT	225/55R19HL422			400.00	X
2	SUNDRIES	NPN			100.00	X
3	MOULDING RH FRONT DOOR	80282-4CA0A	100.70			X
4	MLDG ASSY-FR DOOR RH	80820-4CL0A	157.00			X
5	TAPE-FR DOOR,RH	80818-4CA0B	18.00			X
6	DOOR-FRONT RH	H010M-4CBMA	1032.90			X
7	GROMMET \$2.50 EA 02	76848-JG00A	5.00			OK ✓
8	CLIP ARC \$2.50 EA X 03	01553-10641	7.50			OK ✓
9	CLIP ARC \$2.50 EA X 02	76847-JG00A	5.00			OK ✓
10	CLIP ARC \$2.50 EA X 04	63848-35F00	10.00			OK ✓
11	CLIP ARC \$3.00 EA X 02	76882-JG10A	6.00			OK ✓
12	GROMMET FENDER \$4.50 EA X 06	76881-JG00A	27.00			OK ✓
13	MOULDING ASSY-FRONT ARC RH	63860-4CE1A	170.00			OK ✓
14	MOUL-FR DOOR,RH	80876-6FR0A	183.90			X
15	FENDER-FRONT RH	F3100-4CCMA	583.40			X
16	ORNAMENT-ROAD	40342-BR02A			32.90	X
17	WHEEL-ROAD AL RH FRONT	D0300-4CB3A			1681.50	OK ✓
18	INSULATOR-STRUT	54320-4CL0B	90.30			X
19	STOPPER ASSY	54325-00Q0B			74.20	X
20	BUMPER ASSY-BOU	54050-4CL0B			38.20	X
21	SPACER	54034-4BA0A			17.60	X
22	SEAT SUSPENSION LOWER	54035-4BA0A	23.30			X
23	STRUT KIT-FRONT	E4302-4CE1C			365.00	X
24	MEMBER COMPL	54400-4CB1C			488.60	X
25	STAY ASSY-FRONT	544C4-EN10B			60.40	X

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 ROD-STABILIZER	54618-1AA0E	32.30		X
27 LINK COMPL,RH	54500-4CA0A	224.50		X
28 SPDL-KNUCKLE,RH	40014-4CE0A		481.80	X
29 HUB ASSY-ROAD W	40202-4BA0A		272.20	X
30 SHAFT ASSY-FRONT RH	39100-4BB1B		966.20	X
SUB TOTAL		230.50	0.00	1681.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		46.10	0.00	0.00
GRAND TOTAL		184.40	0.00	1681.50
OVERALL TOTAL		1865.90		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLV5251B

NETT ITEM	230.50
LESS 20.00%)	-46.10
NETT AMOUNT	184.40
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	1681.50
LESS .00%)	0.00
SPECIAL NETT AMOUNT	1681.50
TOTAL LABOUR CHARGES	1638.00
TOTAL SPARE PARTS CHARGES	1865.90
TOTAL CHARGES	3503.90
ADD 7 % GST	245.27
GRAND TOTAL	3749.17

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0578/2018
DATE : 17-DEC-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAN YA LI
ADDRESS : 937 BUKIT TIMAH ROAD
#03-35
S(589646)
TELEPHONE NO : 96773911

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHC3255B
VEHICLE NO : SLV5251B
MODEL CODE : JDRHRRT32EWAF---A
MODEL/YEAR : NISSAN X-TRAIL FACELIFT MY2017
ENGINE NO : MR20146612C
CHASSIS NO : JN1JANT32E0010464
MILEAGE : 1 KM
DATE IN : 17/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 14/12/2018

10146
18/12/18

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT ~~WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

LKK

APR 11/01/19
132
11/11/19

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	/
2 RRSCH	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	? X 17
3 RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH FRONT	480.00	? X 17
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	X 17
5 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	/
6 II/001	REPAIR AND RENEW RH FRONT FENDER, RH FRONT DOOR	1200.00	780
7 II/002	S/PAINT RH FRONT FENDER, RH FRONT DOOR	750.00	500
8 II/003	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING RH FRONT	15.00	/
9 II/004	RENEW RH FRONT TYRE 225/55R19 B/S H/L422		
	TOTAL LABOUR CHARGES	3208.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 225/55R19HL422PLUS B/S TYRE RH FRONT X	225/55R19HL422			400.00	X SUC
2 SUNDRIES ?	NPH			100.00	? XNC
3 MOULDING RH FRONT DOOR	80282-4CA0A	100.70	X SUC		
4 MLDG ASSY-FR DOOR RH	80820-4CL0A	157.00	X SUC		
5 TAPE-FR DOOR, RH	80818-4CA0B	18.00	X SUC		
6 DOOR-FRONT RH	H010N-4CBMA	1032.90	repair		
7 GROMMET \$2.50 EA 02	76848-JG00A	5.00	repair		
8 CLIP ARC \$2.50 EA X 03	01553-10641	7.50	repair		
9 CLIP ARC \$2.50 EA X 02	76847-JG00A	5.00	repair		
10 CLIP ARC \$2.50 EA X 04	63848-35P00	10.00	repair		
11 CLIP ARC \$3.00 EA X 02	76882-JG10A	6.00	repair		
12 GROMMET FENDER \$4.50 EA X 06	76881-JG00A	27.00	repair		
13 MOULDING ASSY-FRONT ARC RH	63860-4CE1A	170.00	repair		
14 MOUL-FR DOOR, RH	80876-6FR0A	183.90	X SUC		
15 FENDER-FRONT RH	F3100-4CCMA	583.40	repair		
16 ORNAMENT-ROAD	40342-BR02A			32.90	X SUC
17 WHEEL-ROAD AL RH FRONT	D0300-4CB3A			1681.50	repair
18 INSULATOR-STRUT	54320-4CL0B	90.30	X SUC		
19 STOPPER ASSY	54325-00Q0B			74.20	? ?
20 BUMPER ASSY-BOU	54050-4CL0B			38.20	? ?
21 SPACER	54034-4BA0A			17.60	? ?
22 SEAT SUSPENSION LOWER	54035-4BA0A	23.30	?		X SUC
23 STRUT KIT-FRONT	E4302-4CE1C			365.00	? ?
24 MEMBER COMPL	54400-4CB1C			488.60	? ?
25 STAY ASSY-FRONT	544C4-EN10B			60.40	? ?

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAN W/S/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5251B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 ROD-STABILIZER	54618-1AAGE	32.30	?	} <i>X</i> <i>SVC</i>
27 LINK COMPL,RH	54500-4CA0A	224.50	?	
28 SPDL-FNUCKLE,RH	40014-4CE0A			
29 HUB ASSY-ROAD W	40202-4BA0A			
30 SHAFT ASSY-FRONT RH	39100-4BD1B			
SUB TOTAL		2676.80	0.00	4978.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		535.36	0.00	0.00
GRAND TOTAL		2141.44	0.00	4978.60
OVERALL TOTAL		7120.04		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV5251B

TOTAL LABOUR CHARGES	3208.00
TOTAL SPARE PARTS CHARGES	7120.04
GRAND TOTAL	10328.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	: Perma - Hp 90010068
SURVEYED DATE	: 11/01/19 @ 1111
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00 5 days
LIABILITY	: 0.00
REMARKS	:

Resuy b4 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.