

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road
159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



Steve (LKK) WL M/L 10/6/19, 12.00 pm
4 days
p/p, Rery bef spray
8322 8813

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 4193
Date Estimated : 03/06/2019
Prepared By : Melody Teoh Man Lin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Chong Hoi Sun
174C Edgedale Plains
#10-181

Singapore 823174

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ7105D	VF3LRHNYWHS127913	20/07/2017	308SW ALL16	0

DESCRIPTION

TO CONDUCT TP CLAIM AGAINST SGW3607B (AXA) - DOA:
02/06/2019

VALUE

0.00

LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN END PANEL,
REAR BUMPER, BUMPER REINFORCEMENT & ALL AFFECTED
AREAS

500 / 2,000.00

LABOUR TO PUTTY & RESPRAY PAINT ON END PANEL, REAR
BUMPER & ALL AFFECTED AREAS

500 / 2,000.00

TO REMOVE & REINSTALL REAR BUMPER REVERSE SENSORS,
CONDUCT DISTANCE SETTINGS (NETT)

120.00

TUFF KOTE, ANTI RUST PRESERVATIONS, BODY CAVITY
PRESERVATIONS (PER PANEL \$60 NETT)

120.00

TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT
CODES, RESTORE ALL PROGRAMME MODULE (NETT)

600.00

SUNDRIES

30 / 100.00

Total Labour 1: 4,940.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611608880	REAR BUMPER - W/OUT SENSOR	1	650.00	10.00	585.00
9677378480	RR BPR REINFORCEMENT	1	225.00	10.00	202.50
98009970XT	RR BUMPER SKIRT	1	210.00	10.00	189.00
1611616480	RR BUMPER SIDE BRACKET SET	1	60.00	10.00	54.00
1611616580	RR BUMPER FIXING STIFFENER SET	1	80.00	10.00	72.00
9800981980	RR BUMPER CENTRAL BRACKET	1	80.00	10.00	72.00
1611616780	RR BUMPER BRACKET SUPERIEUR	1	59.00	10.00	53.10
1611616380	SUPPORT - SET OF 4PCS RR BPR SENSOR	1	103.00	10.00	92.70
1608321780	SENSOR-OBSTACLE DETECTION FRT/REAR	1	99.00	10.00	89.10

Total Parts : 1,409.40

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : BP 4193
Date Estimated : 03/06/2019
Prepared By : Melody Teoh Man Lin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ7105D	VF3LRHNYWHS127913	20/07/2017	308SW ALL16	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp	Date	Labour 1	:	4,940.00
		Parts	:	1,409.40
		Labour 2	:	0.00
		Excess	:	0.00
		Total GST @ 7%	:	444.46
		Grand Total	:	6,793.86

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

AUTOFRANCE

(A Division of Vantage Automotive Limited)
Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Service Booking: 6477 7377
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300

**PEUGEOT**

Finalized
SERVICE TAX INVOICE
RE-PRINT

REPAIR ORDER NO. BP 115020	Date IN 24/06/2019 Payment Term 30 Days From Invoice Customer Service Advisor Melody Teoh Man Lin	Invoice Number Invoice Date ?? Invoice By Katherine Chong Fui Poh	Page No. 1 of 1
--------------------------------------	---	---	------------------------

CUSTOMER INFORMATION	INVOICE TO 77
Chong Hoi Sun 174C Edgedale Plains #10-181 Singapore 823174	Axa Insurance Pte Ltd No. 8 Shenton Way #24-01 Axa Tower Singapore 068811

REGISTRATION No. SLQ7105D	CHASSIS No. VF3LRHNYWHS127913	STOCK No. 210147	REGISTRATION DATE 20/07/2017	MODEL 308SW ALL16	MILEAGE 41854
-------------------------------------	---	----------------------------	--	-----------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM - AXA AGAINST SGW3607B. DOA.02/06/2019	0	0.00	0.00
	LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN END PANEL, REAR BUMPER, BUMPER REINFORCEMENT & ALL AFFECTED AREAS	1	0.00	500.00
	LABOUR TO PUTTY & RESPRAY PAINT ON END PANEL, REAR BUMPER & ALL AFFECTED AREAS	1	0.00	500.00
	TO REMOVE & REINSTALL REAR BUMPER REVERSE SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	1	0.00	120.00
	TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE (NETT)	2	0.00	600.00
	SUNDRIES	1	0.00	30.00
Sub-Total :				1,750.00

CODE	DESCRIPTION	UNITS	DISC %	NETT
1611608880	REAR BUMPER - W/OUT SENSOR	1	10.00	585.00
1611616380	SUPPORT - SET OF 4PCS RR BPR SENSOR	1	10.00	92.70
Sub-Total :				677.70

Attending CSO : Melody Teoh
Should you require further explanation, please reach me at 92782710

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$ 2,427.70
Labour Charges	1,750.00	Less Insurance Excess	S\$ 0.00
Parts Charges	677.70	GST @ 7%	S\$ 169.94
Lubricant/Misc	0.00	Invoice Total Amounts	S\$ 2,597.64
		Less Deposit/Voucher	S\$ 0.00

Computer generated invoice. No signature is required.	Amount Payable	S\$ 2,597.64
---	----------------	---------------------

All amounts are in Singapore Dollars.
Work was carried out subject to the Company's Terms and Conditions of Service.
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.
For credit purchases, interest @1% per month will be debited on overdue amounts.

