

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

Steve (LKK) WL M/L 10/6/19, 12.00 pm
4 days
8322 8813
P/P, Rery bef spray

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 4193	Page No. : 1 of 2
Date Estimated : 03/06/2019	
Prepared By : Melody Teoh Man Lin	

- ESTIMATE REPAIR FOR - Chong Hoi Sun 174C Edgedale Plains #10-181 Singapore 823174	- ACCOUNT - 2000 CASH - Sale service .
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ7105D	VF3LRHNYWHS127913	20/07/2017	308SW ALL16	0

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM AGAINST SGW3607B (AXA) - DOA: 02/06/2019	0.00
LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN END PANEL, REAR BUMPER, BUMPER REINFORCEMENT & ALL AFFECTED AREAS	500 2,000.00
LABOUR TO PUTTY & RESPRAY PAINT ON END PANEL, REAR BUMPER & ALL AFFECTED AREAS	500 2,000.00
TO REMOVE & REINSTALL REAR BUMPER REVERSE SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	120.00
TUFF KOTE, ANTI RUST PRESERVATIONS, BODY CAVITY PRESERVATIONS (PER PANEL \$60 NETT)	120.00
TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE (NETT)	600.00
SUNDRIES	30 100.00
Total Labour 1:	4,940.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611608880	REAR BUMPER - W/OUT SENSOR	1	650.00	10.00	585.00
9677378480	RR BPR REINFORCEMENT	1	225.00	10.00	202.50
98009970XT	RR BUMPER SKIRT	1	210.00	10.00	189.00
1611616480	RR BUMPER SIDE BRACKET SET	1	60.00	10.00	54.00
1611616580	RR BUMPER FIXING STIFFENER SET	1	80.00	10.00	72.00
9800981980	RR BUMPER CENTRAL BRACKET	1	80.00	10.00	72.00
1611616780	RR BUMPER BRACKET SUPERIEUR	1	59.00	10.00	53.10
1611616380	SUPPORT - SET OF 4PCS RR BPR SENSOR	1	103.00	10.00	92.70
1608321780	SENSOR-OBSTACLE DETECTION FRT/REAR	1	99.00	10.00	89.10
Total Parts :					1,409.40

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BP 4193**
Date Estimated : **03/06/2019**
Prepared By : **Melody Teoh Man Lin**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ7105D	VF3LRHNYWHS127913	20/07/2017	308SW ALL16	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp

Date

Labour 1	:	4,940.00
Parts	:	1,409.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	444.46
Grand Total	:	6,793.86

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.