



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

NG SENG WEE EUGENE

06/06/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA

Vivian

Accident date: 04/06/2019

Estimated repair cost for vehicle no: SJZ5593S BMW 320i 2.0 A '10

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Fender <i>Dented</i>		\$648.35 ✓
2	1	Front R/H Fender Cowling <i>3 items</i>		\$113.05 ✗
3	1	Front R/H Fender Cowling Clip		\$113.05 ✗
4	1	Front R/H Head Lamp <i>lt</i>		\$2,013.75 ✓
5	1	Front R/H Head Lamp Lower Bracket <i>item</i>		\$71.95 ✗
6	1	Front Bumper <i>Deformed</i>		\$943.45 ✓
7	10	Front Bumper Clip <i>item</i>	\$6.50	\$65.00 30
8	2	Front Bumper Side Retainer <i>item</i>	\$28.00	\$56.00 ✓
9	1	Front R/H Rim <i>lt</i>		\$850.00 ✓
10	1	Front R/H Tyre <i>Not item</i>		\$350.00 ✗
11	1	Front R/H Lower Arm <i>2</i>		\$202.75 ✗
12	1	Front R/H Knuckle Arm <i>item</i>		\$380.95 ✗
13	1	Front R/H Knuckle Arm Bearing <i>item</i>		\$465.75 ✗
14	1	Front R/H Shock Absorber		\$391.90 ✗
15	1	Front R/H Stabilizer Bar		\$92.50 ✗

Subtotal :- \$6,758.45

4541.55

4087.39

Labour charges

To remove & refit front R/H undercarriage

\$380.00 X

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Towing fee

\$100.00 X

Tuff kote

\$150.00 X

Panel beating

910 . ~~\$1,400.00~~ 400

Spray painting

~~\$1,400.00~~ 400

Subtotal :- \$3,680.00

Total:- \$10,438.45

total 4997.39.

L/S 4K.
04 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4K