

Ashu

Section A - Accident Details	
Registration Number	SHF303A
Case Reference Number	TAX/06/19/2003
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	WAN YAU KUEN
Type of Accident	Head to Rear
Accident Date and Time	1/6/2019 7:20 PM
Accident Reported Date and Time	3/6/2019 8:54 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101799
Special Instruction to ARC, if any	OUR VEHICLE REAR PORTION DAMAGED
Prepared Date and Time	4/6/2019 11:03 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

P/P \$2662.18 / 4 days.

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$1,494.00	\$300.00
Total Spare Part Cost	\$5,981.37	\$1,605.30
Total Other Cost	\$1,456.88	\$356.88
TOTAL COST	\$9,946.25	\$2,662.18 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	04/06/2019 11:47 AM	04/06/2019 12:54 PM
Signature		
Remarks	p/p repair, photo before paint.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1906-0166	Invoice Number	
Quotation Date	14.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
Total Labour	\$1,014.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,494.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
Total Other Costs	\$1,456.88	\$356.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63655592
Estimator Telephone Number 68662523
Accident Reporting Number 68662672

Date Generated : 17/06/2019

User ID : PohSuan

52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	
52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace	
52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X hu
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	
52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	
52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	
52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X hu
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X hu
58165470 30	COVER, FRONT FLOOR UNDER, RH	0.00	\$427.30	0.00	\$0.00	Replace	Check	X hu
58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X hu
66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X hu
58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	X hu
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X hu
67005474 40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X hu
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	X hu
56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X hu
75571470 10	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$29.70	0.00	\$0.00	Replace	Not Given	X hu
75575470 51	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X hu
75574470 40	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X hu
75573471 10	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X hu
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X hu
75403480 10	EMBLEM SUB-ASSY REAR	0.00	\$46.30	0.00	\$0.00	Replace	Not Given	X hu
75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	
75442471 30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	
	STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X hu
81581470 10	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	
61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Check	X hu
Total			\$7,507.10		\$1,605.30			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1605.30
+ 400.00
+ 656.88

2662.18