



CHUA SOON TECK ANDY

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

06/06/2019

TP Eng.
Jiale.

Accident date: 04/06/2019

Estimated repair cost for vehicle no: SGJ758L TOYOTA WISH 1.8 A '06

CHASSIS: ZNE100313988

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid <i>Dented</i>		\$1,315.20 1270
2	2	Rear Boot Lid Hinge <i>3 new</i>	\$141.40	\$282.80 x
3	2	Rear Boot Lid Shock Absorber <i>3 new</i>	\$371.85	\$743.70 +
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$51.10 -
5	1	Rear Boot Lid Centre Chrome Moulding <i>3 new</i>		\$274.45 x
6	4	Rear Boot Lid Centre Chrome Moulding Clip <i>new</i>	\$6.50	\$39.00 x
7	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 +
8	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$374.45 -
9	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$381.90 -
10	1	Rear Boot Lid Inner Trim Board <i>crushed</i>		\$781.45 48
11	1	Rear Boot Lid Windscreen Top Seal <i>new</i>		\$125.00 ✓
12	2	Rear Boot Lid Windscreen Side Moulding <i>new</i>	\$65.00	\$130.00 ✓
13	1	Rear Boot Lid Camera (Special Nett) <i>new</i>		\$550.00 +
14	2	Rear Tail Lamp <i>crushed</i>	\$387.40	\$774.80 ✓
15	4	Rear Tail Lamp Clip <i>over</i>	\$8.00	\$32.00 -20
16	1	Rear Bumper <i>behind</i>		\$625.20 545
17	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30
18	2	Rear Bumper Bracket <i>new</i>	\$88.60	\$177.20 x
19	2	Rear Bumper Side Retainer <i>new</i>	\$132.10	\$264.20 112
20	2	Rear Bumper Side Reflector <i>new</i>	\$141.45	\$282.90 x
21	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00 200
22	1	Rear L/H Fender <i>new</i>		\$972.45 x
23	2	Rear Fender Air Duct <i>new</i>	\$100.40	\$200.80 x
24	2	Rear Fender Inner Trim Board <i>new</i>	\$471.45	\$942.90 471.4
25	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 30
26	1	Rear End Panel Outer <i>Dented</i>		\$519.80 ✓
27	1	Rear End Panel Inner <i>Dented</i>		\$780.50 4
28	1	Rear End Panel Top Garnish <i>behind</i>		\$374.45 -

29	1	Rear Floor Panel <i>Repis</i>		\$980.30	<i>x</i>
30	2	Rear Floor Panel Top Cover <i>HEM</i>	\$282.10	\$564.20	<i>x</i>
31	1	Rear Floor Panel Inner Garnish <i>Not Nec</i>		\$291.40	<i>x</i>
32	1	Rear Floor Panel & End Panel Sealant <i>Not nec</i>		\$450.00	<i>x</i>
33	1	Rear Exhaust <i>Best</i>		\$961.20	<i>✓</i>
34	2	Rear Exhaust Mounting <i>HEM</i>	\$67.60	\$135.20	<i>x</i>
35	1	Rear Centre Exhaust - <i>Not Nec</i>		\$1,714.20	<i>x</i>
36	1	Rear Spare Tyre Bracket <i>HEM</i>		\$194.85	<i>x</i>

7122.15
5341.61

SN: 200 Subtotal:- \$16,873.60

Labour charges

To remove & refit cushion		\$280.00 <i>60</i>
To remove & refit reverse sensor		\$100.00 <i>30</i>
To remove & refit camera		\$180.00 <i>50</i>
To remove & refit rear windscreen		\$120.00 <i>✓</i>
Gum		\$50.00 <i>✓</i>
To remove & refit rear & centre exhaust	<i>2350</i>	\$380.00 <i>80</i>
To check wiring		\$100.00 <i>30</i>
Tuff kote		\$150.00 <i>60</i>
Panel beating		\$1,200.00 <i>1000</i>
Spray painting		\$1,200.00 <i>850</i>

Subtotal:- \$3,760.00

Total:- \$20,633.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 7891.61
4/5: 6.3K
06hys
(6.3K)