

Steve (LKK)
8322 8813

LML p/p 7/6/19, 11.15 am
p/p 8 days
Ry bek spray

SERVICE ESTIMATE

84713 - C00001 SL: SERVICE SALES - PC
Mr Lam Yong Wei (Lin Yonghui)
29A Mackerrow Road

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 06/06/2019

WIP No. : 18172

Veh.In/Out:

*Tel.No. : Mobile: 98771831

Reg.No. : E21M

Reg.date : 09/06/2016

Mileage : 0

Chassis No: SALWA2KE8GA590182

Singapore 358593

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Lam Yong Wei (Lin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, 1700	0	7200.00	0		7,200.00	\$ 6000
	REAR BOOTLID, REAR LH FENDER, ETC						
800	TO PUTTY SPRAYPAINT ON 1700	0	4000.00	0		4,000.00	\$ 3000
	REAR BUMPER, REAR LH FENDER, REAR BOOTLID, ETC						
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00	\$ /
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	\$ /
802	TO REPLACE REAR LH QTR GLASS	0	600.00	0		600.00	\$ / 300
0080	TO INSTALL REAR LH QTR GLASS F (sole filh)	0	280.00	0		280.00	\$ /
802	TO REMOVE & REFIT BOOTLID PART	0	500.00	0		500.00	\$ /
802	TO REMOVE & REFIT INTERIOR PAR	0	2400.00	0		2,400.00	\$ 1200
280	TO CHECK WIRING INLCUDE	0	486.00	0		486.00	\$ /
	RESETTING OF ALL ELECTRICAL MODULES						

TAILGATE - LESS HING	1.0 EA	3929.50			3,929.50	\$
WINDSCREEN REAR RRS3	1.0 EA	2204.50			2,204.50	\$
D PRIMER GLASS & P	1.0 EA	37.40			37.40	\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

84713 - C00001 SL: SERVICE SALES - PC
 Mr Lam Yong Wei (Lin Yonghui)
 29A Mackerrow Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 06/06/2019

WIP No. . : 18172

Veh.In/Out:

*Tel.No. . : Mobile: 98771831

Reg.No. . : E21M

Reg.date. : 09/06/2016

Mileage . : 0

Chassis No: SALWA2KE8GA590182

Singapore 358593

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Lam Yong Wei (Lin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	ADHESIVE AND SEALER / <i>n/c</i>	2.0 EA	136.10			272.20	S
	LLR045014/BADGE 'RAN' / <i>n/c</i>	1.0 EA	197.10			197.10	S
	BADGE 'ROVER' REAR R / <i>n/c</i>	1.0 EA	184.10			184.10	S
	BADGE OVAL REAR RR3 / <i>n/c</i>	1.0 EA	91.70			91.70	S
	LLR048876/NAME PLATE X ?	1.0 EA	193.90			193.90	S
	NAME PLATE - PLASTIC ?	1.0 EA	179.40			179.40	S
	BUMPER COVER REAR RR / <i>BR</i>	1.0 EA	1919.80			1,919.80	S
	BRACKET - BUMPER MOU ?	1.0 EA	213.10			213.10	S
	BUMPER INSERT REAR R X ?	1.0 EA	391.80			391.80	S
	BUMPER INSERT REAR L ?	1.0 EA	391.80			391.80	S
	BRACKET - BUMPER MOU ?	1.0 EA	162.20			162.20	S
	BRACKET - BUMPER MOU ?	1.0 EA	197.50			197.50	S
	PANEL - BODY SIDE - / <i>BD</i>	1.0 EA	3016.70			3,016.70	S
	LH FINISHER - PILLAR / <i>BR</i>	1.0 EA	246.60			246.60	S
	QTR GLASS LH RRS3 / <i>n/c</i>	1.0 EA	873.00			873.00	S
	ADHESIVE SEALER FL2 / <i>n/c</i>	1.0 EA	549.10			549.10	S
	BODY PANEL SEALANT X / <i>n/c</i>	1.0 EA	883.20			883.20	S

Gross Total. 33,080.60

Labour Total 16,946.00
 Parts Total 16,134.60
 Package Total 0.00

Net..... 33,080.60

GST @ 7.0% 2,315.64

Total..... 35,396.25

Paid..... 0.00

Please Pay.. 35,396.25

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated