

# Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **Lonpac Insurance Bhd**  
101 Thomson Road,  
#18-01 United Square,  
S'pore 307591

Estimate billl : TT 37 / 19 / TP / WT

Registration No : SDP5255S

Attn : Attention : Motor Claims Third Party Department  
Tel : Tel : 62507388  
Fax : Fax : 62532058

Make model : BMW

Mileage : Date : 06 / 06 / 2019

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SGW4212A AND SDP5255S ALONG  
AMK AVENUE 3 (ESSO STATION) ON 02 JUNE 2019 AT ABOUT 1955 HRS.**

1pc	Rear bumper		\$	CM	1,823.00	✓
2pcs	Rear bumper parktronic sensor (Centre)	(Each \$324.00)	\$	SM	648.00	X
4pcs	Rear bumper parktronic sensor seal ring	(Each \$15.00)	\$	RM	60.00	2
1pc	Rear bumper strike moulding		\$	CM	110.00	✓
1pc	Rear bumper towing cover		\$	RM	93.00	✓
1pc	Rear bumper lip		\$	CM	438.00	✓
1pc	Rear bumper frame centre bracket (Top)		\$	h	61.00	X
1pc	Rear bumper frame centre bracket (Bottom)		\$	n	122.00	X
2pcs	Rear bumper side bracket	(Each \$78.00)	\$	R	156.00	X
1pc	Rear bumper reinforcement		\$	n	632.00	X
1pc	Rear bumper under dust covering (Centre)		\$	SM	86.00	X
1pc	Rear bumper under dust covering (RH)		\$	R	98.00	X
Sub A total :			\$		4,327.00	
Less 10% discount :			\$		432.70	
A total :			\$		3,894.30	
Total amount of Page 1 :			\$		3,894.30	

Tropical Tech Automobile Services

( Authorised Signature )  
William Tan

Not Withstand  
L/R B?  
Primary After Pain  
2-3days

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535  
Tel : 6481 7773 / 6481 1403 Fax : 6484 4978  
E-mail : tasc303@singnet.com.sg

M / s : **Lonpac Insurance Bhd**  
101 Thomson Road,  
#18-01 United Square,  
S'pore 307591

Estimate billl : TT 37 / 19 / TP / WT

Registration No : SDP5255S

Attn : Attention : Motor Claims Third Party Department  
Tel : Tel : 62507388  
Fax : Fax : 62532058

Make model : BMW

Mileage : Date : 06 / 06 / 2019

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SGW4212A AND SDP5255S ALONG  
AMK AVENUE 3 (ESSO STATION) ON 02 JUNE 2019 AT ABOUT 1955 HRS.**

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper parktronic sensor, rear bumper parktronic sensor seal ring, rear bumper strike moulding, rear bumper towing cover, rear bumper lip, rear bumper frame centre bracket (Top), rear bumper frame centre bracket (Bottom), rear bumper side bracket, rear bumper reinforcement, rear bumper under dust covering (Centre), rear bumper under dust covering (RH).

\$ 1,500.00 *3001*

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

Diagnostic on rear bumper parktronic sensor fault error by HHT

\$ 120.00 *601*

Tuff kote rear damaged portion.

\$ 150.00 *nn 150.00 X*

Putty / primer application, spray painting on rear boot, rear bumper, rear bumper parktronic sensor, rear bumper towing cover, rear bumper lip, rear bumper reinforcement.

\$ 1,200.00 *5001*

Balance amount brought from Page 1 :

\$ 3,894.30

**Grand final amount :**

**\$ 6,864.30**

Tropical Tech Automobile Services

  
( Authorised Signature )  
William Tan