

205 Braddell Road S(579701) <u>ACCIDENT REPAIR ESTIMATES</u>

Our Ref:			
Type of Claim :	TP	Vehicle No.	SJE7691P
		Make & Model	HONDA CROSSROAD 1.8L
		Year of Manufacture	2008 /EXP. 2023
		Chassis No.	RT11007731
Ins Company :	AIG VS AXA	Engine No.	i
Excess :		Policy No.	3
Date of Accident :	28/05/2019	Time of Accident	:
Suggested Days of Repair :		In-house Vehicle Asse	essor
Repair Estimates		Case Owner	PATRICK
		Signature	
Parts (a) Cost / List Price Items	\$ 1,663.60	0-1-11	
Plus/Less 15%	\$ 249.54	Contact No 63837890 – Rohani	63837466 - Patrick
Total of Cost / List	\$ 1,414.06	braddell_cr@sparkcarca	are.com braddell_cr@sparkcarcare.com
		63837730 - Brenda I	Ng
(b) Nett Price Items	\$ -	braddell_cr@sparkcarca	are.com
Less	<u> </u>	63837362 - Andrew	63837656 - Ngo
Total of Nett Item		braddell_operation@spa	arecarcare.cc braddell_operation@sparec
	. ar aa	63838115 - William \	
(c) Special Nett Items	\$ 35.00	braddell operation@spa	
Total Parts Cost (Appendix A)	\$ 1,449.06		not without
Labour (Appendix B)	\$ 1,250.00		Nor Whair
Total Repair Cost	\$ 2,699.06		1 1104 12.
The above total will be subjected	d to 7% G.S.T.		
		4	
Name of Surveyor		Kenson	
Company		14.111.9	
Survey conducted on		/////// at	
Remarks By Surveyor			
(a) The repair of this vehicle i	is amberized / is not aut	horized until further notice.	
(b) Recommended Days of F	Repair :	<i>O Z</i> day(s)	
(c) Resurvey	: Required / N	ot Required	
(d) Excess	:\$		
(e) Signature of surveyor		De Date	14/6/18

Spark Car Care ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No		SJE7691P	Case Owner	PATRICK
Make & Model		HONDA CROSSROAD	Year Manufacture	2008 /EXP. 2023
Chassis No	:	RT11007731	Engine No	L13A4054292
Sales Order	*		Supplier	-
Order By			Type of Claim	: TP

FRONT BUMPER			Cost Price	List Price	Nett Price		S/N	Disposition By Surveyor
TRONT BOWFER	1	\$	1,308.60					7
FRONT NUMBER PLATE W/CASING	1				Pu	\$	35.00	_
RADIATOR GRILLE	1	\$	190.00					×
RADIATOR GRILLE GARNISH (M	1	\$	165.00					_
0	1							
0	1							
0	1							
0	1							
0								
0								
0								
0								
0								
0			LKK Au	o Consultants he	nce notify			
						\dashv		
0		_	To displa	v damaged pages	painting	+		
			Parts pric	es are subject to conf	rmation	+		
			No illegal	modification/a - With	out Prejudice basis	+		
			• Suppleme	ntary item(s) must be	resurveyed and	+		
			is subject	to final approval from	nsurance Company	+		
		-	Acknowledg	ed by Repairer		+		
		-	Date:			+		
)		_				1		
		-						
	-					_		
		_						
)	1					_		
	RADIATOR GRILLE GARNISH O O O O O O O O O O O O O	RADIATOR GRILLE GARNISH 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0	RADIATOR GRILLE GARNISH 0	RADIATOR GRILLE GARNISH 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 1 0 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	RADIATOR GRILLE GARNISH 1	RADIATOR GRILLE GARNISH 0	RADIATOR GRILLE GARNISH 0	RADIATOR GRILLE GARNISH 1

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No.		SJE7691P	Case Owner		PATRICK	
Make & Model	:	HONDA CROSSROAD 1.8L	Year of Manufacture	:_	2008 /EXP. 2023	

S/No	Labour Description	Esimated	Adjusted
		Price	Price
		7 1100	11100
1	TO PANEL BEAT ON FRONT AFFECTED AREAS, REPLACE	\$600.00	2001
	DAMAGE PARTS AND REALIGNMENT	,,,,,,,	
2	TO PUTTY,RESPRAY ON FRONT BUMPER,PANEL AND	\$600.00	2001
-	AFFECTED AREAS		
3	CHECK LIGHTING AND WIRING	\$50.00	15/
-			
1			
+			
+			- H
+			
+			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.