

205 Braddell Road S(579701)

,	ACCIDENT RE	PAIR ESTIMATES	
Our Ref:			
Ins Company : AIG	TP VS AXA 05/2019 \$ 1,663.60 \$ 249.54 \$ 1,414.06 \$ - \$ 35.00 \$ 1,449.06 \$ 1,250.00	Vehicle No. : : : : : : : : : : : : : : : : : : :	PATRICK 63837466 - Patrick braddell cr@sparkcarcare.co m 63837656 - Ngo rcare.cc braddell operation@spareca
Total Repair Cost			
The above total will be subjected to			
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is a (b) Recommended Days of Rep	:	orized until further notice.	

: Required / Not Required

Date: _

(e) Signature of surveyor

(d) Excess

(c) Resurvey

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	:	SJE7691P	Case Owner :	PATRICK
Make & Model	:	HONDA CROSSROAD	Year Manufacture :	2008 /EXP. 2023
Chassis No	:	RT11007731	Engine No :	L13A4054292
Sales Order	:		Supplier :	
Order Bv			Type of Claim	TP

S/No	Part Description	ΩТΥ		Cost Price	List Price	ı	lett rice		S/N	Disposition By Surveyor
1	FRONT BUMPER	1	\$	1,308.60						
2	FRONT NUMBER PLATE W/CASING	1						\$	35.00	
3	RADIATOR GRILLE	1	\$	190.00						
4	RADIATOR GRILLE GARNISH	1	\$	165.00						
5	0	1								
6	0	1								
7	0	1								
8	0	1								
9	0	1								
10	0	1								
11	0	1					***************************************			
12	0	1								
13	0	1								
14	0	1								
15	0	1								
16	0	1							***************************************	
17	0	1								
18	0	1							****************	
19	0	1								
20	0	1		***************************************						
21	0	1								
22	0	1								
23	0	1								
24	0	2								
	0	1								
	0	1	·							
	0	1								
	0	1								
	0	1						†		
30		1	\vdash							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

06/06/2019 4:10 PM

Spark Car Care ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No.		SJE7691P	Case Owner	:	PATRICK	
Make & Model	:	HONDA CROSSROAD 1.8L	Year of Manufacture		2008 /EXP. 2023	

	real of Manufacture : 20					
S/No	Labour Description	Esimated Price	Adjusted Price			
1	TO PANEL BEAT ON FRONT AFFECTED AREAS, REPLACE	\$600.00				
	DAMAGE PARTS AND REALIGNMENT					
2	TO PUTTY,RESPRAY ON FRONT BUMPER,PANEL AND	\$600.00				
	AFFECTED AREAS					
3	CHECK LIGHTING AND WIRING	\$50.00				
		\$50.00				

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.