

7/2/2019

ASS. REC. BY:

REF:

CS/SMO/9010058/Jqd302

Special Instruction:

Surveyor: Hwei Jie

Meitimen

ASSIGNMENT (Office)

From (Person): Chen Shu Hui Agnes

of

SMO

Date/Time:

7/6/19 @ 10.20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 60422

Insured:

FBL 7603C

at Workshop m/s

SMR2T

Tel:

68662628

of

60 woodlands Ind. Park E4 #

Policy No:

DI8MTMCO1003452

Claim No:

CMTD1902733

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10.43am @ 7/6/19

Person Contacted:

Shenli

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SHD 60422 - CS/EQT/6021000 / 16/342	20A: 2/1/2016
12/6/19 @ 4:41pm	revised to Agnes Chan via Meitimen.	
	Hwei Jie Finalised Final Prg. \$2878.75, 4 days	
	CR'd \$ 6080.78, 68%.	

(08/11/13)

REF SMO

ASS. REC. BY: Hue Jc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD6042Z Yr Regn: 19 Nov 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: maroon A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU503579483Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or vestHake

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 4/6/19 D.O.I. 7/6/19Survey held at SumitDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

06/19/2013

RECEIVED 20 JUN 2019

FBL 7603C

Date/Time, File Pass to?

☐ : Preli. Report1) 20/6/2019☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 390

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

11

361

Report Format : Web TPLump Sum / I.B.I: (\$) 2878.75

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2019		07 Jun 2019 10:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	NOR ZIMAN BIN MOHAMED AFFINDI , ID: S8140359G			
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K			
Vehicle Reg. No.:	SHD6042Z	Date of Loss:	04/06/2019 09:00 - :59	
Claim Type:	TP / CMTD1902733	Policy/Cover Note No.:	D18MTMC01003452 (TP, Fire & Theft)	
Vehicle Reg. No. (Insured):	FBL7603C	Policy No. (Claimant):		
		Excess:		
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/06/2019]			
Adj Asg. Remarks:	WS: SHANTI 6866 2671/2 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 13 Jun 2019

Preliminary Advice

Insured Vehicle No	: FBL7603C	Accident Date	: 04/06/2019
TP Vehicle No	: SHD6042Z	Assignment Date	: 07/06/2019
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 4.00
Date of Inspection	: 07/06/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,561.70
Revised Amount	:S\$	1,998.30
Check Items (Estimated)	:S\$	3,256.00
Total	:S\$	5,254.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHD6042Z
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8285773
Chassis No.:	JTDKB3FU503579483
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,880.00
Total Rebate Amount:	\$31,630.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/06/2019 11:50
Date Of Accident	04/06/2019 09:20
Exact Location Of Accident	MARSILING RISE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD6042Z
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D19093197MFSH
Cover Note Number	
Driver	
Name of Driver	JAMIL BIN JAMALI
NRIC No	S1125094G
Date Of Birth	10/01/1955
Occupation	OUTDOOR
Date Of Driving Pass	11/06/1982
Driving Experience	36 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG MARSILING RISE, THERE WAS A PASSENGER FLAGGING FOR MY TAXI AT THE BUS STOP. UPON SEEING THIS, I CHANGE MY LANE AND SLOWED DOWN TO PICK THE PASSENGER UP. AFTER I STOPPED MY VEHICLE INFRONT OF THE FLAGGING PASSENGER, SUDDENLY I FELT AN IMPACT AT MY REAR RIGHT AND FROM THE RIGHT SIDE MIRROR I SAW A MOTORCYCLIST COLLIDED ONTO MY TAXI AND FELL ONTO THE ROAD. I QUICKLY ALIGHT FROM MY TAXI AND CHECK ON THE MOTORCYCLIST & HE QUICKLY GET UP AND WE EXCHANGE PARTICULARS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBL7603C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MOHAMED NOR JIHAD BIN MOHAMED SUHAIMI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMED NOR JIHAD BIN MOHAMED SUHAIMI

Approximate Age

Injuries Sustain

ABRASION

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number : TAX/06/19/2013
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6042Z

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7190-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompoo Insurance Singapore Pte. Ltd
 Accident Date and Time : 04/06/2019 01:20 AM
 Vehicle Age(In Months) : 18

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace ▾	nee
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	1	63.90	Replace ▾	ms
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace ▾	DEP
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give ▾	uu
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace ▾	nee
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Check ▾	uu
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Check ▾	uu
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give ▾	uu
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give ▾	uu
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.1	10	2.60	26.00	25.00	19.50	Replace	0	0	Not Give ▾	uu
Total Spare Part Cost									5,698.53	Surveyor Total 1,128.30				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									5,698.53	Final Sur Total 1,128.30				

SMRT Recommendation												Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			CLIP , FLOOR UNDER COVER , NO.2	10	3.20	32.00	25.00	24.00	Replace	0	0	Not Give	nn	
One Time Key In	Main			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	1	137.00	137.00	25.00	102.75	Replace	0	0	Check	nn	
One Time Key In	Main			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	1,173.90	25.00	880.43	Replace	0	0	Check	BT	
One Time Key In	Main			SUPPORT, EXHAUST PIPE NO.5	2	41.10	82.20	25.00	61.65	Replace	0	0	Check	}	
One Time Key In	Main			SUPPORT, EXHAUST PIPE NO.4	1	41.10	41.10	25.00	30.83	Replace	0	0	Check		
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check		
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check		
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Check		
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Check		
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair		
One Time Key In	Main			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Check	nn	
One Time Key In	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	nn	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	DEF	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	hec	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	nec	

Total Spare Part Cost 5,698.53

Surveyor Total 1,128.30

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 5,698.53

Final Sur Total 1,128.30

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	hec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	hec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace ▾	DRF
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check ▾	nn
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	hec
Total Spare Part Cost									5,698.53	Surveyor Total		1,128.30		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									5,698.53	Final Sur Total		1,128.30		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	50	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
4	Main	TO RESPRAY REAR PANEL	180.00	0	
5	Main	TO RESPRAY REAR FENDER RH	378.00	200	
Total:			1,476.00	450.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
Total:			1,476.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	120.00	0	
6	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
9	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
Total:			940.00	20.00	

Summary

1056170

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,698.53	1,128.30
Total Labour Cost	845.00	400.00
Total Spray Painting	1,476.00	450.00
Other	940.00	20.00
Overall Total	8,959.53	1,998.30
Lump Sum Repair Option		
Lump Sum Total	0.00	1,998.30
Surveyor Approved Amount		1,998.30
No of Repair Days*	6	4
Remarks	-	p/p repair, photo before paint.

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Hwee Jie

Signature


14/6/19

Save

Clear

Survey Date

07/06/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Section A - Accident Details

Registration Number	SHD6042Z
Case Reference Number	TAX/06/19/2013
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	JAMIL BIN JAMALI
Type of Accident	Head to Rear
Accident Date and Time	4/6/2019 9:20 AM
Accident Reported Date and Time	4/6/2019 11:26 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101832
Special Instruction to ARC, if any	EXHAUST DROPPED (REAR RIGHT DAMAGE)
Prepared Date and Time	7/6/2019 9:05 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

P/P \$2878.75 4 days.

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,476.00	\$450.00
Total Spare Part Cost	\$6,578.96	\$2,008.75
Total Other Cost	\$940.00	\$20.00
TOTAL COST	\$9,839.96	\$2,878.75 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / Sampo
ARC / Surveyor Sign Off Date	07/06/2019 11:03 AM	07/06/2019 2:13 PM
Signature		
Remarks	SUP = 0 DAYS	p/p repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0241	Invoice Number	
Quotation Date	17.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$50.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
Total Other Costs	\$940.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace ✓
		52591470 50	SEAL, RR BUMPER, RH	1.00	\$85.20	25.00	\$63.90	Replace	Replace ✓
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace ✓
		52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given X
		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace ✓
		81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Check X
		58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 83885592
Estimator Telephone Number: 88662622
Accident Reporting Number: 88662672

Date Generated : 19/05/2019

User ID : PohSuan

6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
5839947030	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
9046717026A0	CLIP, FLOOR UNDER COVER, NO.1	0.00	\$2.60	0.00	\$0.00	Replace	Not Given	X
9046717027C0	CLIP, FLOOR UNDER COVER, NO.2	0.00	\$3.20	0.00	\$0.00	Replace	Not Given	X
5832747040	EXHAUST HEAT SHIELD INSULATOR, MAIN	0.00	\$137.00	0.00	\$0.00	Replace	Check	X
1743037730	PIPE ASSY, EXHAUST, TAIL	0.00	\$1,173.90	0.00	\$0.00	Replace	Check	X
1756522040	SUPPORT, EXHAUST PIPE NO.5	0.00	\$41.10	0.00	\$0.00	Replace	Check	X
1756528010	SUPPORT, EXHAUST PIPE NO.4	0.00	\$41.10	0.00	\$0.00	Replace	Check	X
5830747090	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	X
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
5831147130	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Check	X
8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Check	X
6180147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	R
6294047010	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
6563747060	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	/
5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	/
5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace	/
5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace	/
5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	/
5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	X
5256547900	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	/
5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/
Total			\$7,107.10		\$1,128.32			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		1743037730	PIPE ASSY, EXHAUST, TAIL	1.00	\$1,173.90	25.00	\$880.43	Replace	Replace
Total					1,173.90		880.43		

2008.75
+ 400.00
+ 470.00

2878.75

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	74X/06/19/2013	Date of Collection	8/6/19
Vehicle No	SHD 6042 Z	Date of Request	11/6/19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	178182183	Pipe Assy Exhaust Tail		1173.90

BT

<<<Please submit photographs for damaged parts>>>

I, (Name)

CHIA

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission


























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		07 Jun 2019 10:28 Edit Adj Rpt	S\$2,878.75 Edit Estimates	S\$2,878.75 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: NOR ZIMAN BIN MOHAMED AFFINDI , ID: S8140359G									
Main Claimant: SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K									
Vehicle Reg. No.: SHD6042Z		Date of Loss: 04/06/2019 09:00 - :59 [17 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1902733		Policy/Cover Note No.: D18MTMC01003452 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): FBL7603C		Policy No. (Claimant):							
		Excess:							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 18/06/2019]									
Adj Asg. Remarks: WS: SHANTI 6866 2671/2 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD6042Z (CMTD1902733)**
[FBL7603C]
TP
SMRT TAXIS PTE LTD
Jun 4 2019 9:00AM
[NOR ZIMAN BIN MOHAMED AFFINDI]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 16:41	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
12	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
13	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
14	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
15	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
16	20/06/19 10:37	General View	 Load JPG	<input checked="" type="checkbox"/>
17	20/06/19 10:37	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
18	20/06/19 10:37	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
19	20/06/19 10:37	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
20	20/06/19 10:37	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
21	20/06/19 10:37	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
22	20/06/19 10:37	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	07/06/19 10:26	TP - SAS	 Load PDF	<input type="checkbox"/>
2	07/06/19 10:26	TP - ACK+ASSIGN LKK	 Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19010058/JQD3E2

Date: 01/07/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01003452

Claimant Vehicle No : SHD6042Z

Insured Vehicle No : FBL7603C

Date of Loss: 04/06/2019

Nature of Claim: TP

Claim No: CMTD1902733

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6042Z

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR8285773

Reg. Date: 19/12/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU503579483

Colour: Maroon

Odometer: 0 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,300.70	2,008.75	5,291.95	72.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,261.00	870.00	2,391.00	73.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	10,561.70	2,878.75	7,682.95	72.74

INSPECTION

Date of Assignment: 07/06/2019

Date Inspected: 07/06/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2019)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6042Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RETAINER, RR BUMPER, RH (DISC 25%)	Necessary	112.70 F	*84.53 F
2	1		*SEAL, RR BUMPER, RH (DISC 25%)	Missing	85.20 F	*63.90 F
3	1		*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.73 F
4	3		*PAD, RR BUMPER, CTR (DISC 25%)	Necessary	6.60 F	*4.95 F
5	1		*PIPE ASSY, EXHAUST, TAIL (DISC 25%)	Bent	1,173.90 F	*880.43 F
6	1		*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
7	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) (10PCS)	Necessary	15.00 F	*11.25 F
8	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	Necessary	7.60 F	*5.70 F
9	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	Necessary	7.60 F	*5.70 F
10	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	Necessary	7.60 F	*5.70 F
11	1		*FILLER, RR BUMPER, RH (DISC 25%)	Deformed	119.90 F	*89.93 F
12	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
13	1		*COVER, GUARD RR BUMPER	Not Necessary	14.80 F	*- F
14	1		*LENS & BODY ASSY, RR BUMPER, RH	Not Necessary	486.80 F	*- F
15	1		*COVER, REAR FLOOR UNDER, RH	Not Necessary	169.50 F	*- F
16	1		*COVER, REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
17	1		*COVER, REAR FLOOR UNDER, LH	Not Necessary	234.30 F	*- F
18	10		*CLIP, FLOOR UNDER COVER, NO.1	Not Necessary	26.00 F	*- F
19	10		*CLIP, FLOOR UNDER COVER, NO.2	Not Necessary	32.00 F	*- F
20	1		*EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	Not Necessary	137.00 F	*- F
21	2		*SUPPORT, EXHAUST PIPE NO.5	Not Necessary	82.20 F	*- F
22	1		*SUPPORT EXHAUST PIPE NO.4	Not Necessary	41.10 F	*- F
23	1		*END PANEL SUBASSY, BODY LOWER BACK	Not Necessary	629.80 F	*- F
24	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
25	1		*SPARE TYRE PANEL, PAN, REAR FLOOR	Not Necessary	564.80 F	*- F
26	1		*LENS & BODY, REAR COMBINATION LAMP, RH	Not Necessary	438.10 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*DUCT ASSY, QUARTER VENT, RH & LH	Not Necessary	65.00 F	*- F
28	1		*LINER, REAR FENDER, RH	Not Necessary	135.80 F	*- F
29	2		*SEAL, RR BUMPER ARM, RH & LH	Not Necessary	22.00 F	*- F
30	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
31	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
32	1		*PANEL SUB-ASSY, FENDER REAR RH	Repair	824.80 F	*- F
F=Franchise part.				Total Parts (S\$)	7,300.70	2,008.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	1,476.00	450.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
6	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
7	TO REMOVE AND REFIT WIRE HARDESS	New	120.00	0.00
8	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
10	TO WASH AND VACUUM	New	60.00	0.00
11	TO REMOVE & REFIT EXHAUST	New	120.00	0.00
Gross Labour Cost (S\$)			3,261.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >