

ASS. REC. BY:

REF:

CS/C7719010065/B/d301

Special Instruction:

Surveyor: Mr hm

ASSIGNMENT (Office)

Meinmen

From (Person): Tan Kah Leong

of

CTI

Date/Time: 6/6/19 @ 9.20am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 7867T

Insured:

GBD255L

at Workshop m/s

Team Auto pro

Tel:

62581955

of

385 Sin Ming Drive #01-02

Policy No:

DMCVSN3018481900

Claim No:

SNM19D202476C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/6/19

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11:30 am 3/6/19

Person Contacted:

Adele

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Fohmote

Insp: 160 Sin Ming Drive #01-14

SLP 7867T-X

GBD255L-CC6/C7I17016823/Rub352

JUA: 28/8/2007

(08/11/13)

ASS. REC. BY:

REF

CTI

ASSIGNMENT

Denise

From: _____ Date: 4.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 7867Tat Workshop m/s Jeam Autoproof 160 Sin Ming Drive, #01-14

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP 7867T Yr Regn: 13/6/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mitsubishi Attrage C.C. 1193Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 52763 T/Radio: Insured / Std / NI / NAEng/No: 3A92UGB5616C/No: MMBSTA13AH006284Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 185/55/15R: 185/55/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 3/6/19 D.O.I. 4/6/19Survey held at Jeam AutoproDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 8,000/- - 9,000/-
	LTm
	Pls see my remarks
	Confirm
	MV 55,000/2
	PV 41,083/2
	NV 13,917/2
	45 5400/2, 6 days
	(Red: 10373.50 / 65%)
	12/6 TCCM lin
	10/6/19

RECEIVED 16 JUL 2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 6

1) 15/7 Typist

☒ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 5400/-

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2019		06 Jun 2019 09:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TAN SHAO QI, EDISON, ID: S8934259G		
Vehicle Reg. No.:	SLP7867T	Date of Loss:	03/06/2019 16:00 - :59
Claim Type:	TP / SNM19D202476C02	Policy/Cover Note No.:	DMCVSN3018481900
Vehicle Reg. No. (Insured):	GBD255L	Policy No. (Claimant):	10843525
		Excess:	S\$0.00
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4259G
Vehicle Details	
Vehicle No.:	SLP7867T
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	3A92UGB5616
Chassis No.:	MMBSTA13AHH006284
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,053.00
Original Registration Date:	19 Jun 2017
First Registration Date:	19 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$37,333.00
Total Rebate Amount:	\$41,083.00

The information contained herein is correct as at 07 Jun 2019

OK

Dep 6710/yr
559/mth

MV 55,000/2
PV 41,083/2
NV 13,917/2

lin
7/6/19

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

[SELL YOUR CAR](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



1.8 iV 1800cc 50 AC/100km/h
Finance 2 Years, War of 10000
Down Monthly From \$638
GV Credit Pte Ltd


[Browse by Category](#)
[Sort by Reg. Date](#)
[20 results/page](#)

14 vehicles

Mitsubishi Attrage

20 results/page

Image	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Attrage	Any	Any	2017	Any	Any	Any	All
	Mitsubishi Attrage 1.2A	-	N.A	21-Dec-2017	1,193 cc	-	Sedan	SOLD
Extended Warranty Available! Immaculately Maintained By 1 Careful Owner! Flexible Loan Schemes Available! View To Believe Condition! Buy From Trustworthy Dealer And We Will Workout A Win Win Package F...								
Car Times Automobile Pte Ltd								
Posted: 23-Mar-2019 Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi								
	Mitsubishi Attrage 1.2A	\$53,800	\$6,040 /yr	01-Dec-2017	1,193 cc	29,000 km	Sedan	Available
1 Owner! AA Trust Certified Quality Pre-Owned Vehicle! Upgraded Steering Wheel With Speed Lock, Auto Lock And Cruise Control! Strut Bar And Anti-Rolling Bar, Front And Rear Lower Bars With Spring Buff...								
AA Trust Automotive								
Posted: 29-May-2019 Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi								
	Mitsubishi Attrage 1.2A (OPC)	-	N.A	09-Nov-2017	1,193 cc	-	Sedan	SOLD
New Arrival! Most Valued Buy! Almost Like Brand New! Beautiful White Unit With Pristine Condition! Peace Of Mind! Serviced Regularly. Still Under Agent 5 Years Warranty And Engine 10 Years Warranty! 1...								
Posted: 16-Apr-2019 Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi								
	Mitsubishi Attrage 1.2A	\$52,900	\$5,990 /yr	02-Nov-2017	1,193 cc	20,000 km	Sedan	Available
Selling On Behalf Of Private Owner, Please Call To Arrange Before Viewing!								
Posted: 15-May-2019 Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi								
	COE Bidding Results	Find out more about the latest results of our Certificate of Entitlement (COE). Find out more!						
	Mitsubishi Attrage 1.2A	\$55,800	\$6,500 /yr	17-Aug-2017	1,193 cc	21,500 km	Sedan	Available
Budget Value At It Best! Super 1.2 Fuel Saver With High Specs! DVD Player With Reverse Camera! Full Loan Available! Monthly \$600!								
Posted: 01-Jun-2019 Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi								
	Mitsubishi Attrage 1.2A	\$55,800	\$6,530 /yr	04-Aug-2017	1,193 cc	32,905 km	Sedan	Available
Confirm Non Grab/Gojek/Leasing Car! Serviced At C&C With Proof, Last Done Jan 19. Amazing Low Mileage Done 32905km. Totally Like Brand New. 1 Owner. Road Tax Till Aug 19. 100% Accident Free. Call Now!								
Lake View Credit Pte Ltd								
Posted: 02-Jun-2019 Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi								
	Mitsubishi Attrage 1.2A	\$55,800	\$6,710 /yr	18-May-2017	1,193 cc	23,000 km	Sedan	Available
Promotional Interest Rates Starting From 2.28%! 100% Loan Available! Trade Loan Welcome! High Trade-In! Full Agent Serviced! 10 Years Engine Warranty! Excellent Condition! No Repair Needed! High Fuel ...								
Autotruster Traders Pte Ltd								
Posted: 07-Jun-2019 Tags: 2017 Mitsubishi Attrage, 2017 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2019 19:05
Date Of Accident	03/06/2019 16:45
Exact Location Of Accident	SLIP ROAD TO CTE/SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP7867T
Insured/Policyholder	
Name Of Registered Owner	TAN SHAO QI, EDISON
NRIC No	S8934259G
Email Address	EDISON.TAN15@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92737447
Alternative Phone No	Office-92737447

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10843525
Cover Note Number	NA

Driver

Name of Driver	TAN SHAO QI, EDISON
NRIC No	S8934259G
Date Of Birth	15/09/1989
Occupation	INDOOR
Date Of Driving Pass	27/05/2009
Driving Experience	10 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92737447

Fax Number	
Contact Number	
EMail Address	EDISON.TAN15@GMAIL.COM
Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : JACLYN ZHONG QINNI Gender: : Female
Passenger 2	Name: : LIM SOH HUA Gender: : Female
Passenger 3	Name: : KARA TAN XIN XIN Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, I VEHICLE 'A' WAS TRAVELLING ON THE STATED VENUE. I WAS TRAVELLING STRAIGHT IN MY LANE, THE VEHICLE IN FRONT JAMMED BRAKE. I IMMEDIATELY APPLIED MY BRAKE AND CAME TO A COMPLETE STOP. MOMENTS LATER, I FELT AN IMPACT ON MY VEHICLE REAR. SHORTLY I GOT DOWN AND NOTICED VEHICLE 'B' HAD COLLIDED AGAINST MY STATIONARY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD0255L
Vehicle Make/Model/Colour	HYUNDAI GRACE H100

Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	UNKNOWN
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


DETAILS OF INJURED PERSON 1

Name	JACLYN ZHONG QINNI
Approximate Age	
Injuries Sustain	BODILY INJURIES
Injured person in which vehicle?	SLP7867T
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLAN

CTE/SLE V.A) SLD7867T
V.B) GIBD255L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' was travelling on the
stated venue. I was travelling straight in my lane, the vehicle
in front jammed brake, I immediately applied my brake
and came to a complete stop. Moments later, I
felt an impact on my vehicle rear. Shortly I got
down and noticed vehicle 'B' had collided against
my stationary vehicle rear portion.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' was travelling on the
 stated venue. I was travelling straight in my lane, the vehicle
 in front jammed brake, I immediately applied my brake
 and came to a complete stop. Moments later, I
 felt an impact on my vehicle rear shortly I got
 down and noticed vehicle 'B' had collided against
 my stationary vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/ID No:

SJE :	_____	Vehicle Nos :	SLP 7867T
Date of Survey :	_____	Model :	MITSUBISHI ATTRAGE
Date of ReSurvey:	After-Paint:	Year :	_____
Contacts :	_____	Chassis No :	_____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:	_____	Working Day:	_____
----------------	-------	---------------------	-------


Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 934.00	\$ 934.00	BT✓
2	Bootlid logo	1	\$ 76.00	\$ 76.00	} NEC✓
3	Bootlid emblem 'Attrage'	1	\$ 68.00	\$ 68.00	
4	Bootlid chrome moulding	1	\$ 440.00	\$ 440.00	
5	Bootlid emblem 'C&C'	1	\$ 68.00	\$ 68.00	
6	Bootlid lock assy	1	\$ 275.00	\$ 275.00	BT✓
7	Bootlid striker	1	\$ 85.00	\$ 85.00	BT✓
8	Bootlid weatherstrip	1	\$ 215.00	\$ 215.00	CUT✓
9	Bootlid lock switch	1	\$ 192.00	\$ 192.00	?
10	Rear bumper	1	\$ 680.00	\$ 680.00	PD✓
11	Rear bumper side retainer	2	\$ 75.00	\$ 150.00	NEC
12	Rear bumper reflector	1	\$ 42.00	\$ 42.00	?
13	Rear bumper bracket	2	\$ 48.50	\$ 97.00	NEC✓
14	Rear end panel	1	\$ 560.00	\$ 560.00	DD✓
15	Rear end panel top garnish	1	\$ 165.00	\$ 165.00	DL✓
16	Rear end panel air vent	1	\$ 123.00	\$ 123.00	?
17	Rear end panel air vent cover	1	\$ 94.00	\$ 94.00	?
18	Spare tyre panel	1	\$ 1,210.00	\$ 1,210.00	?
19	Spare tyre panel top board	1	\$ 270.00	\$ 270.00	BR✓
20	Spare tyre panel insulator	1	\$ 300.00	\$ 300.00	?
21	Taillamp	2	\$ 395.00	\$ 790.00	BR✓
22	Taillamp panel	2	\$ 185.00	\$ 370.00	?
23	Rear fender RH	2	\$ 945.00	\$ 1,890.00	✓
24	Rear fender inner trim	2	\$ 260.00	\$ 520.00	?
25	Rear windscreen moulding	1	\$ 151.00	\$ 151.00	NEC✓
26	Rear windscreen clips	1	\$ 50.00	\$ 50.00	?
Parts Sub Total :				\$ 9,815.00	
10% Discount				\$ 981.50	
PARTS TOTAL :				\$ 8,833.50	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ 60.00	NNX
2	Bootlid spoiler	1	\$ 520.00	\$ 520.00	NNX
3	Bootlid chrome moulding clips	1	\$ 50.00	\$ 30.00	NNX
4	Taillamp clips	2	\$ 50.00	\$ 60.00	NECV
5	Taillamp seal	2	\$ 80.00	\$ 160.00	NNX
6	Taillamp base panel sealant	2	\$ 100.00	\$ 200.00	?
7	Rear bumper clips	1	\$ 50.00	\$ 30.00	NECV
8	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00	NECV
9	Rear end panel sealant	1	\$ 100.00	\$ 60.00	NECV
10	Rear fender inner trim clips	2	\$ 50.00	\$ 100.00	?
11	Rear fender sealant RH	2	\$ 100.00	\$ 60.00	NECV
12	Reverse sensor with module	2	\$ 200.00	\$ 200.00	DL✓
13	Reverse camera	1	\$ 350.00	\$ 350.00	NNX

14	Rear windscreen primer and cleaner	1	\$	80.00	\$	80.00	NNX
SPECIAL NETT TOTAL :					\$	2,420.00	

Nos.	LABOUR	S\$		
1	R&R bootlid component	\$	60.00 100.00	✓
2	R&R rear windscreen	\$	150.00 200.00	✓
3	R&R fuel filler tank	\$	280.00	NNX
4	R&R upholstery	\$	100.00	?
5	R&R reverse sensor	\$	60.00 100.00	✓
6	To disconnect wire harness to facilitate repair, reconnect and check function	\$	50.00 80.00	
7	Panel beat	\$	700.00 1,800.00	
8	Rust proofing	\$	120.00 200.00	✓
9	Spray painting	\$	1,000.00 1,600.00	✓
10	Conduct water leakage test	\$	60.00	NNX
LABOUR TOTAL :		\$	4,520.00	

PARTS TOTAL : \$ 8,833.50
SPECIAL NETT TOTAL : \$ 2,420.00
LABOUR TOTAL : \$ 4,520.00
GRAND TOTAL : \$ 15,773.50



? photo
Lump sum repair
Repair days 6
Lim Teow Guan
97361577
4/6/19
1500hrs

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SLP 7867T**

Model : **MITSUBISHI ATTRAGE**

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 934.00	\$ 934.00 ✓
2	Bootlid logo	1	\$ 76.00	\$ 55.00 76.00
3	Bootlid emblem 'Attrage'	1	\$ 68.00	\$ 50.00 68.00
4	Bootlid chrome moulding	1	\$ 440.00	\$ 300.00 440.00
5	Bootlid emblem 'C&C'	1	\$ 68.00	\$ 68.00 ✓
6	Bootlid lock assy	1	\$ 275.00	\$ 275.00 ✓
7	Bootlid striker	1	\$ 85.00	\$ 30.00 85.00
8	Bootlid weatherstrip	1	\$ 215.00	\$ 192.00 215.00
9	Bootlid lock switch	1	\$ 192.00	\$ 192.00
10	Rear bumper	1	\$ 680.00	\$ 680.00 ✓
11	Rear bumper side retainer	2	\$ 65.00 75.00	\$ 130.00 150.00
12	Rear bumper reflector	1	\$ 42.00	\$ 42.00 ✓
13	Rear bumper bracket	2	\$ 48.50	\$ 97.00 ✓
14	Rear end panel	1	\$ 402.00 560.00	\$ 402.00 560.00
15	Rear end panel top garnish	1	\$ 165.00	\$ 165.00 ✓
16	Rear end panel air vent	1	\$ 123.00	\$ 123.00
17	Rear end panel air vent cover	1	\$ 94.00	\$ 94.00
18	Spare tyre panel	1	\$ 1,210.00	\$ 1,210.00
19	Spare tyre panel top board	1	\$ 185.00 270.00	\$ 185.00 270.00
20	Spare tyre panel insulator	1	\$ 150.00 300.00	\$ 150.00 300.00
21	Taillamp	2	\$ 395.00	\$ 790.00 ✓
22	Taillamp panel	2	\$ 185.00	\$ 370.00 ✓
23	Rear fender	2	\$ 945.00	\$ 1,890.00
24	Rear fender inner trim	2	\$ 260.00	\$ 520.00
25	Rear windscreen moulding	1	\$ 151.00	\$ 151.00 ✓
26	Rear windscreen clips	1	\$ 50.00	\$ 30.00 50.00
27 Rear bumper cover x 2 @ 49.00 \$ 200.00				Parts Sub Total : \$ 9,815.00
(inner corner guard) 98.00 ✓ DL & MIS				Discount \$ 981.50
				PARTS TOTAL : \$ 8,833.50

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ 60.00
2	Bootlid spoiler	1	\$ 520.00	\$ 520.00
3	Bootlid chrome moulding clips	1	\$ 50.00	\$ 30.00 50.00
4	Taillamp clips	2	\$ 50.00	\$ 60.00 100.00
5	Taillamp seal	2	\$ 80.00	\$ 160.00
6	Taillamp base panel sealant	2	\$ 100.00	\$ 200.00
7	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
8	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00
9	Rear end panel sealant	1	\$ 100.00	\$ 60.00 100.00
10	Rear fender inner trim clips	2	\$ 50.00	\$ 100.00
11	Rear fender sealant	2	\$ 100.00	\$ 60.00 200.00
12	Reverse sensor with module	2	\$ 200.00	\$ 200 400.00
13	Reverse Camera	1	\$ 350.00	\$ 350.00

14	Rear windscreen primer and cleaner	1	\$	80.00	\$	80.00	NNX
SPECIAL NETT TOTAL :					\$	2,420.00	

Nos.	LABOUR				S\$		
1	R&R bootlid component				\$ 60.00	100.00	✓
2	R&R rear windscreen				\$ 150.00	200.00	✓ NN
3	R&R fuel filler tank				\$	280.00	NNX
4	R&R upholstery				\$ 50	100.00	? ✓
5	R&R reverse sensor				\$ 60.00	100.00	✓
6	To disconnect wire harness to facilitate repair, reconnect and check function				\$ 50.00	80.00	100
7	Panel beat	1110	for spare	150.00 + 100	\$ 700.00	1,800.00	250
8	Rust proofing		for spare tyre panel + 200.00	and fender	\$ 120.00	200.00	✓
9	Spray painting				\$ 1000.00	1,600.00	✓ 120
10	Conduct water leakage test				\$	60.00	NNX
LABOUR TOTAL :					\$	4,520.00	

PARTS TOTAL : \$ 8,833.50
SPECIAL NETT TOTAL : \$ 2,420.00
LABOUR TOTAL : \$ 4,520.00
GRAND TOTAL : \$ 15,773.50

169973 50

[Signature]
12/6/19.

? photo
Lump sum repair
Repair days 6

Lim Teow Guan
97361577
4/6/19
1500hrs

Resurvey on 6/6/19
1550 hrs
hrs

Insurance Consultants hence notify
the insurer of the following:
• Survey before/after spray painting
• Damaged part(s) during resurvey
• Items are subject to confirmation
• Survey is on a "Without Prejudice" basis
• Modification(s) is allowed
• Any item(s) must be resurveyed and
• No final approval from Insurance Company
Approved by Repairer

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2019		06 Jun 2019 09:20 Edit Adj Rpt	S\$5,400.00 Edit Estimates	S\$5,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	TAN SHAO QI, EDISON , ID: S8934259G								
Vehicle Reg. No.:	SLP7867T	Date of Loss:	03/06/2019 16:00 - :59 [23 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202476C02	Policy/Cover Note No.:	DMCVSN3018481900						
Vehicle Reg. No. (Insured):	GBD255L	Policy No. (Claimant):	10843525						
		Excess:	S\$0.00						
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 17/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP7867T (SNM19D202476C02)
[GBD255L]
TP
TAN SHAO QI, EDISON
Jun 3 2019 4:00PM
[-]
Team Autopro Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	15/07/19 09:49	General View							Load JPG	☒
2	15/07/19 09:49	General View							Load JPG	☒
3	15/07/19 09:49	General View							Load JPG	☒
4	15/07/19 09:49	General View							Load JPG	☒
5	15/07/19 09:49	General View							Load JPG	☒
6	15/07/19 09:49	General View							Load JPG	☒
7	15/07/19 09:49	General View							Load JPG	☒
8	15/07/19 09:49	General View							Load JPG	☒
9	15/07/19 09:49	General View							Load JPG	☒
10	15/07/19 09:49	General View							Load JPG	☒
11	15/07/19 09:49	General View							Load JPG	☒
12	15/07/19 09:49	General View							Load JPG	☒
13	15/07/19 09:49	General View							Load JPG	☒
14	15/07/19 09:49	General View							Load JPG	☒
15	15/07/19 09:49	General View							Load JPG	☒
16	15/07/19 09:49	General View							Load JPG	☒
17	15/07/19 09:49	General View							Load JPG	☒
18	15/07/19 09:49	General View							Load JPG	☒
19	15/07/19 09:49	General View							Load JPG	☒
20	15/07/19 09:49	General View							Load JPG	☒
21	15/07/19 09:49	General View							Load JPG	☒
22	15/07/19 09:49	General View							Load JPG	☒
23	15/07/19 09:49	General View							Load JPG	☒
24	15/07/19 09:49	General View							Load JPG	☒
25	15/07/19 09:49	General View							Load JPG	☒
26	15/07/19 09:49	General View							Load JPG	☒
27	15/07/19 09:49	General View							Load JPG	☒
28	15/07/19 09:49	General View							Load JPG	☒
29	15/07/19 09:49	General View							Load JPG	☒
30	15/07/19 09:49	General View							Load JPG	☒
31	15/07/19 09:49	General View							Load JPG	☒
32	15/07/19 10:09	Reinspection Photo							Load JPG	☒
33	15/07/19 10:09	Reinspection Photo							Load JPG	☒

Linked Accident Report Documents

			View View in Browser
Assessment Reports			1 per page
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail Print
1	04/06/19 19:28	Accident Statement	Load HTM
Photos/Images			3 per page
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail Print
1	04/06/19 19:23	Accident Photo	Load JPG
2	04/06/19 19:23	Accident Photo	Load JPG
3	04/06/19 19:23	Accident Photo	Load JPG
4	04/06/19 19:23	Accident Photo	Load JPG
5	04/06/19 19:23	Accident Photo	Load JPG
6	04/06/19 19:23	Identification Card	Load JPG
Documentation			1 per page
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail Print
1	04/06/19 19:22	Sketch Plan	Load JPG

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010065/BTD3E2

Date: 19/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3018481900

Claimant Vehicle
No : SLP7867TInsured Vehicle
No : GBD255L

Date of Loss: 03/06/2019

Nature of Claim: TP

Claim
No: SNM19D202476C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP7867T

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UGB5616

Reg. Date: 19/06/2017 (Man. Year: 2017)

Chassis No: MMBSTA13AHH006284

Colour: Grey

Odometer: 52763 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,433.50	4,104.20	7,329.30	64.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	2,650.00	1,870.00	41.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,953.50	6,754.20	9,199.30	57.66
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	15,953.50	5,400.00	10,553.50	66.15

INSPECTION

Date of Assignment: 06/06/2019

Date Inspected: 04/06/2019 Inspected At:

Team Autopro Pte Ltd (Sin Ming)
385 Sin Ming Drive, #01-02 Vicom
Inspection Centre
Singapore 575718

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jul 2019)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7867T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	934.00 FL	*934.00 FL
2	1		*BOOTLID LOGO	Necessary	76.00 FL	*55.00 FL
3	1		*BOOTLID EMBLEM ATTRAGE	Necessary	68.00 FL	*50.00 FL
4	1		*BOOTLID CHROME MOULDING	Necessary	440.00 FL	*300.00 FL
5	1		*BOOTLID EMBLEM C&C	Necessary	68.00 FL	*68.00 FL
6	1		*BOOTLID LOCK ASSY	Bent	275.00 FL	*275.00 FL
7	1		*BOOTLID STRIKER	Bent	85.00 FL	*30.00 FL
8	1		*BOOTLID WEATHERSTRIP	Cut	215.00 FL	*192.00 FL
9	1		*BOOTLID LOCK SWITCH	Not Necessary	192.00 FL	*- FL
10	1		*REAR BUMPER	Dented	680.00 FL	*680.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	150.00 FL	*130.00 FL
12	1		*REAR BUMPER REFLECTOR	Broken	42.00 FL	*42.00 FL
13	2		*REAR BUMPER BRACKET	Necessary	97.00 FL	*97.00 FL
14	1		*REAR END PANEL	Dented	560.00 FL	*402.00 FL
15	1		*REAR END PANEL TOP GARNISH	Dislodged	165.00 FL	*165.00 FL
16	1		*REAR END PANEL AIR VENT	Not Necessary	123.00 FL	*- FL
17	1		*REAR END PANEL AIR VENT COVER	Not Necessary	94.00 FL	*- FL
18	1		*SPARE TYRE PANEL	Repair	1,210.00 FL	*- FL
19	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	270.00 FL	*- FL
20	1		*SPARE TYRE PANEL INSULATOR	Necessary	300.00 FL	*150.00 FL
21	2		*TAILLAMP	Not Necessary	790.00 FL	*- FL
22	2		*TAILLAMP PANEL	Dented	370.00 FL	*370.00 FL
23	2		*REAR FENDER	Repair	1,890.00 FL	*- FL
24	2		*REAR FENDER INNER TRIM	Not Necessary	520.00 FL	*- FL
25	1		*REAR WINDSCREEN MOULDING	Not Necessary	151.00 FL	*- FL
26	1		*REAR WINDSCREEN CLIPS	Not Necessary	50.00 FL	*- FL
27	2		*REAR BUMPER COVER	Dislodged / Missing	200.00 FL	*98.00 FL
28	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
29	1		*BOOTLID SPOILER	Not Necessary	520.00 FS	*- FS
30	1		*BOOTLID CHROME MOULDING CLIPS	Necessary	50.00 FS	*30.00 FS
31	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*60.00 FS
32	2		*TAILLAMP SEAL	Not Necessary	160.00 FS	*- FS
33	2		*TAILLAMP BASE PANEL SEALANT	Necessary	200.00 FS	*60.00 FS
34	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
37	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
38	2		*REAR FENDER SEALANT	Not Necessary	200.00 FS	*- FS
39	2		*REVERSE SENSOR WITH MODULE	Dislodged	400.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
41	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					12,435.00	4,508.00
- List Item Discount on L Items 10.00/10.00% (S\$)					1,001.50	403.80
Total Parts (S\$)					11,433.50	4,104.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT.	New	100.00	60.00
2	R&R REAR WINDSCREEN.	New	200.00	0.00
3	R&R FUEL FILLER TANK.	New	280.00	0.00
4	R&R UPHOLSTERY.	New	100.00	50.00
5	R&R REVERSE SENSOR.	New	100.00	60.00
6	PANEL BEAT.	New	1,800.00	1,110.00
7	RUST PROOFING.	New	200.00	120.00
8	SPRAY PAINTING.	New	1,600.00	1,200.00
9	CONDUCT WATER LEAKAGE TEST.	New	60.00	0.00
10	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIR, RECONNECT AND CHECK FUNCTION.	New	80.00	50.00
Gross Labour Cost (S\$)			4,520.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >