CWS From (Person): Estimated Cost:	Eileen Fee	of		Date	Time: _	5.36 pm	36/6/19
-	PRES / OD RES /	EVA/INV/M	Bill to:				
To Inspect Vehicle	Nec :	CII 82	MOK	Insured:	8	HC 8200	8E
at Workshop m/s		Mova	Automotive	Tel:	82	723892	Ah Keon
of BIK!	008 Bulcit M	iemih lune	3 #01-04		F 12		9651009
Policy No:			Claim No:	D1900	367	4 MPSH	
Sum Insured:			Excess:			4	
() CST)						101	
				D.O	.A	2/6/2019	-
(Client's Record) CA / REV / RI	EP. / REV 24 HR	(Ds)					•
Make of Veh: (Client's Record) CA / REV / RI Date/Time: 9 le	EP. / REV 24 HRS)	ned: Nith			2/6/2019 DIT	
(Client's Record) CA / REV / RI Date/Time; 9 le	SP. / REV 24 HRS	Person Contact	ned: Nith				
Client's Record) CA / REV / RI Date/Time: 9 k	some 7/6/19 ction/Instruction 1 SLL 8 208 K	Person Contact	I 8022613/	Vehic	O.D. Endo		

PER

VEF:	FCf	•
1.00	1 0	_

		A551	GIVINIEIVI		oc L	0.2	10117
From:	Date: 76	119	Veh No	SLL 820		Yr Regn: 23	
Estimated Cost:			Type M.Car	M.Cycle / Bus	/ Van / Lorry	Taxi / Prime Move	er /
OD TP WS / TP RES / OD R	ES / EVA / INV / MV		Truck	/ Trailer or			1245
To Inspect Vehicle No:	SLL 82081	۷	Make:	Volkswagen	Caddy	C.C	1395
at Workshop m/s	Mura		Colour	Blue		/C: Insured / S	td / NI / NA
of BIK 1008 BIC	t Merch lone	3 # 01-04	Sp.Reading	7511	/§ T	/Radio: Insured / S	td / NI / NA
Insured:			Eng/No:	50			,
Policy No.			C/No:	WV2	222 2K2	2HX 06881	0
Claims No.			Gen. Cond	Good) Fair / Po	or / Burnt		
Sum Insured:	Excess:		Steering Ing	rder / Jammed	/ Leaked / Bu	rnt or	
(Client's Record)			Brake: (Inic	rder Jammed	/ Leaked / Bu	rnt or	
Make of Veh:	Momire		Modi: Nil	S/Rim)/ STD	A/Rim or	רומים	
		XX	Tyre Size:	F:	205/502	K1/	
(Policy Condition)		/		R:	4		
Remark: The veh had comme	1	N/S O/S	BS DUN I	EXNOVA / GY / I	FS / LIZA / MI	C / OHTSU / PIR / S	SUMI /
repair at the time of	f inspection.	ALX	TOYOTYO	KO or			
Bal. or Market Value:			Front			Rear	
IDAC Accident Rport:	Consistent? : Yes o	r No	R/Bal.	Z n	nm	R/Bal.	mm
GIA / PR Seen:	Consistent? : Yes o	r No	L/Bal.	1 111	nm	L/Bal.	mm
Est. Repairs:	days Res.: Yes	or No	D.O.A.	2/6/19		D.O.I. 7/6	117
Lum Sum:	% 3 Val.: Yes	or No	Survey held	at	Mora , (putal Much	
CA / REV / REP. / 24	HRS DS)		Des. of Dan	nages (Frt) Re	ear) O/S / N	IS / U/C / Roofto	op or
	\	/ehicle: IN / OUT		~ (9		CONTRACTOR OF THE PROPERTY OF
2010.	n Contacted:		The U/C	/ Chassis fram	me / Body St	ructure affected d	ue to collision.
Date / Time Action / Ins							
17/7/19 Finally	75K	nn 9 n	auf (Red 66	94.93	3090)	
27/1/11 / 1/1/10/10/	17410 0137300	,70 , 10	J.	(140)	,		
		WED 5 7	1111 2019	1			
	RECE	IVED 2 2	JOE 201				
					_		
Date/Time, File Pass 10?	: Preli. Report		Days Of R	epair: 9	(: 21/21
1)	: Final Report		Resurvey	No. of Trip:	2	Survey Fee:	170+ 180
Date/Time, File Return to?	8023		J			Transportation:	50
2) >> 17 - typist		Add Fe	particular de	e Insp (\$)S+RSSI	50+50
-			No. of Contract of	erview (\$		Photos [80]	127
Report Forms:	CWS			ch. Invs (\$) Others	
Lump Sum / LBJ: 0% L	S \$ 15,550	2	1 Miles	elend (8		07	
	•					DIMILATOR	627



MS First Capital Insurance Limited to Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore Q48580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

04-06-2019

Our Ref No. D19003674MFSH

Accident Date

02-06-2019

Claim Type. Third Party

Insured Vehicle

SHC8208E

Third Party Vehicle. SLL8208K

Survey Location

BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08

Contact Person.

NITHA

Contact No.

62723892/0

Fax No. 62708314

Survey Type

DIRECT SETTLEMENT:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

MOVA AUTOMOTIVE PTE

Attention, NIL

Cc : TP Solicitor

LTD NA

TP Solicitor Fax No. NA

Officer Incharge

EILEEN LEE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 10 June 2019 4:34 PM

To:

'CWS Motor Claims'

Cc: Subject: 'Eileen Lee'; SUR RE: SURVEY ASSESSMENT - D19003674MFSH/1, SLL 8208K

Attachments:

SLL 8208K PRELI ADVISED.pdf

Dear Sir/Madam.

Enclosed preliminary revised of vehicle SLL 8208K

Date of survey: 7/6/2019 Number of days: 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 7 June 2019 9:21 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Eileen Lee' < Eileen Lee@msfirstcapital.com.sg>; SUR < sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19003674MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 6 June 2019 5:36 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee < EileenLee@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19003674MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software. www.avg.com

Company Registration No. 19960719E

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 625643

Your ref:

D19003674MFSH

Our ref:

CS/FCI19010075/Evd3

Date: 10/6/2019

The Motor Claims Department

MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 8208K

We thank you for your instruction on 6/6/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on

7/6/2019

at the premises of M/s

MOVA AUTOMOTIVE PTE LTD

and have the following to report:-

Workshop Estimate Amount

: S\$22,115.01

Revised Estimate Amount

: S\$14,536.56

"Check" Items Amount

: S\$5,361.54

Market Value

: S\$

LTA Reimbursement Value

: S\$

Nett Value


: S\$

Description of Damage:

The vehicle sustained damages at the

front and rear portion

roor



front

Comments/Present Status:

Damages Consistent

Yours faithfully,

STEVE CHEN

Automotive Assessor

. . Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1044X
Vehicle Details	
/ehicle No.:	SLL8208K
/ehicle to be Exported:	No
ntended Deregistration Date:	07 Jun 2019
/ehicle Make:	VOLKSWAGEN
/ehicle Model:	CADDY MAXI 1.4 TSI AT SAJHK5
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CZC639549
Chassis No.:	WV2ZZZ2KZHX068816
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,865.00
Original Registration Date:	23 Feb 2017
First Registration Date:	23 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$23,211.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Feb 2027
PARF Rebate Amount: ntended COE Rebate Details	\$17,408.00
COE Expiry Date:	22 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$37,323.00

The information contained herein is correct as at 07 Jun 2019

OK



Japanese boyband member



Flowers - Lin Lu Zai Art Exhibition and Eternal Blossoming of the Red Flowers...



with Variety Pass at Subscribe Now | Startfub

Recommended by

Volkswagen's Caddy debuts as a viable alternative to traditional seven-seater MPVs



The Volkswagen Caddy offers decent leg room in every row and the third row can be removed to accommodate extra-large items. PHOTO: VOLKSWAGEN SINGAPORE

O PUBLISHED SEP 3, 2016, 5:00 AM SGT

Lynn Tan in Malacca

Mention that a vehicle is based on a concept car or sportscar and people invariably go,
"Oh!" But when they are told that it is based on a commercial vehicle, their reaction is
more likely to be "Oh?".

Those coming face to face with the Volkswagen Caddy seven-seater are likely to have the second reaction.

So, does throwing in extra seats and adding rear windows make the Caddy - long known as a compact delivery van - an MPV?

Believe it or not, it does. And at \$126,400, it is also the least expensive VW seven-seater.

Look beyond its boxy silhouette and you will begin to notice some car-like qualities. With xenon headlamps and daytime-running lights, it has some resemblance to the Touran MPV in front.

SPECS / VOLKSWAGEN CADDY

Price: \$126,400 with COE

Engine: 1,395cc 16-valve turbocharged inline-4

Transmission: Seven-speed dualclutch with manual override

Power: 125bhp at 5,000rpm

Torque: 220Nm at 1,500-3,500rpm

0-100kmh: 10.9 seconds (Caddy Maxi 11.3 seconds)

Top speed: 183kmh

Fuel consumption: 5.8 litres/100km

Agent: Volkswagen Group Singapore Its 17-inch alloy wheels and roof rails give it a rugged and sporty demeanour. Chrome elements on its door panels and front grille up the premium feel.

ADVERTISING

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby consaforesaid.	ent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	03/06/2019 23:13
Date Of Accident	02/06/2019 01:00
Exact Location Of Accident	GEYLANG ROAD NEAR IN FRONT OF CITY PLAZA.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLL8208K
Insured/Policyholder	
Name Of Registered Owner	MAKAN MATTERS
Co Reg No	53241044X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91282097
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	CADDY MAXI 1.4 TSI AT SAJHK5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy	NO

THIRD PARTY

PRIVATE CAR

COMPREHENSIVE

AVIVA LTD

20000793

NO

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category

Insurance Company

Name of Insurance Company

Type Of Coverage Fleet Policy

Policy Number

Cover Note Number

Driver

Name of Driver SEE CHAILEE NRIC No S1287782Z Date Of Birth 13/11/1958 Occupation **INDOOR** Date Of Driving Pass 23/11/1977

Driving Experience 41 YEARS AND 6 MONTHS

Gender **FEMALE**

Mobile Number (LOCAL) +65-91282097

Fax Number

Contact Number

EMail Address TANLIANGG@GMAIL.COM Address NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

CLEAR Weather Conditions Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I was on queue at the junction going to Turn Right". Upon the lights are in our favor, all the vehicles moved forward intending to Turn Right". Suddenly the vehicle ahead of me jammed brakes, I jammed my brakes too and at the same time I felt an impact from my rear vehicle. I later realized that my vehicle was being hit from the rear and my vehicle hit the vehicle ahead of me, Later I realized that I am involve in a chain accident. Involving 4 vehicles. Mine is the 3rd vehicle from the front vehicle. I exchange particulars. No injury involved.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC8208E

Vehicle Make/Model/Colour MERCEDES BENZ E220 BLUETEC WHITE

Details Of Properties NA Vehicle Category TAXI

Name of Driver LOW KIM KEE

NRIC/Passport Number

Contact Number 97387889

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJM7557C

Vehicle Make/Model/Colour

TOYOTA WISH 2.0 AUTO GREY

Details Of Properties

NA

Vehicle Category

PRIVATE CAR

Name of Driver

SUFFIAN

NRIC/Passport Number

S9643143J

Contact Number

84102030

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SJY5998M

Vehicle Make/Model/Colour

TOYOTA WISH 2.0 AUTO WHITE

Details Of Properties

NA

Vehicle Category

PRIVATE CAR

Name of Driver

ASPHARI

S7728738H

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

all the vehicles moved forward intending me jammed brakes, I jammed my brake	Turn Right". Upon the lights are in our favour, ing to Turn Right". Suddenly the vehicle ahead of es too and at the same time I felt an impact from evehicle was being hit from the rear and my
Later I realised that I am involve in a ch 3rd vehicle from the front vehicle.	nain accident. Involving 4 vehicles. Mine is the
I exchange particulars.	
No injury involved.	
Taxi Voucher No.:	
DECLARATION	
We declare that the above particulars & information prov	rided above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER - MOHAMMAD AZALY BIN ABDULLAH	Dr.
MARS Officer	
	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time:
3 June 2019 at 3:19 PM	3 June 2019 at 3:12 PM

Automotive

Main Office:

Mova Building No. 22, Jalan Kilang, Singapore 159419 Tel: (65) 6476 3333 Fax: (65) 6271 5891 www.mova.com.sg

Workshop Dept: Block 1008, Bukit Merah Lane 3,

#01-04/06/08/94 Singapore 159722 Tel: (65) 6272 3892

Fax: (65) 6270 8314

Co. Reg. 198904033G GST Reg. M2-0088864-2

Estimate

04/06/2019

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road #16-01 City House Singapore 068877.

Attention :- XA026

Veh# SLL8208K

Veh Model :- VOLKSWAGEN CADDY

Estimate# :- CK419246

Claim #

ACC. Date :- 02/06/19

Terms

- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LIST ITEMS:			
1.	BONNET	1 PC	2,514.35	2,514.35
2.	BONNET SPONGE CLIPS	20 PC	3.90	20 / 78.00
3.	BONNET SPONGE CLIPS BONNET HINGE L+R X	2 PC	116.95	233.90)
4.	BONNET LOCK TOP X / 4	1 PC	85.40	85.40
5.	BONNET LOCK LOWER / 17	1 PC	140.85	140.85
6.	GRIILE / DR	1 PC	436.75	436.75
7.	GRILLE LOGO / M	1 PC	119.15	119.15
8.	GRILLE LOGO BASE / ///	1 PC	45.30	45.30
9.	HEADLAMP L+R (1)	2 PC	2,097.50	4,195.00
10.	HEADLAMP TOP PANEL L+R / VIII 0 × ////	2 PC	68.15	136.30
11.	HEADLAMP LOWER BRACKET L+R	2 PC	22.30	44.60
12.	HEADLAMP FASTENER	4 PC	17.20	20 / 68.80
13.	SUPPORT PANEL / LIK	1 PC	1,227.75	1,227.75
14.	BRACE PANEL / BT OF	1 PC	107.55	107.55
15.	FRONT BUMPER / //	1 PC	1,161.90	1,161.90
16.	FRONT BUMPER LOWER GRILLE	1 PC	271.65	271.65
17.	FRONT BUMPER CHROME	1 PC	235.30	235.30
18.	FRONT BUMPER TOW COVER / CKM 2 X /V/	1 PC	39.65	39.65
19.	FRONT BUMPER FOG LIGHT L+R	2 PC	225.60	451.20
20.	FRONT BUMPER FOG LIGHT COVER L+R	2 PC	121.90	243.80
21.	FRONT BUMPER SPONGE / III	1 PC	170.00	170.00
22.	FRONT BUMPER REINFORCEMENT	1 PC	748.80	5/1/ 748.80
23.	FRONT BUNIFER WASHER JET LTR	2 PC	146.25	292.50,
24.	THORT BOTT EN THIOTET BIOLOGE	2 PC	204.45	408.90
25.	FRONT BUMPER SIDE BRACKET L+R / //R	2 PC	67.75	135.50
26.	FRONT BUMPER CLIPS / PC	10 PC	3.90	30/ 39.00
27.	FRONT BUMPER WASHER TUBE	1 PC	141.20	141.20
28.	FRONT FENDER L+R / OU	2 PC	683.95	1,367.90
29.	FRONT FENDER COWLING L+R	2 PC	109.30	218.60
30.	THOUT PERSON CONTENTS AND	16 PC	3.90	62.40
31.	TROTT PERDER OF OTAL EARTH EFT	1 PC	38.45	38.45
32.	FRONT 1/4 GLASS WOOLDING LIT	1 PC	473.50	473.50
33.	A/C CONDENSER	1 PC	631.35	631.35
34.	AIR COOLER 1	1 PC	554.65	554.65
35.	RADIATOR PRACKET LED	1 PC	549.75	549.75
36.	RADIATOR BRACKET LERY	2 PC	45.10	
37.	NADIATOR HOSE TOP	1 PC	76.65	76.65
38.	RADIATOR HOSE LOWER ARRESONATOR	1 PC	146.10	146.10
39.	ALL THE SOLUTION THE STATE OF T	1 PC	210.55	210.55
40.		1 PC	62.45	62.45
41.	REAR EMBLEM "CADDY" / 1/20	1 PC	39.50	39.50
12.	REAR EMBLEM CADDY	1 PC	58.35	58.35
43.	REAR EMBLEM 131	1 PC	68.75	68.75
44.	REAR BUMPER	1 PC	362.35	362.35
45.		1 PC	985.80	985.80
16.		2 PC	280.85	561.70
17.	REAR BOWIFER REFLECTOR LIT	1 PC	42.35	42.35
18.		1 PC	46.10	46.10
19.	REAR BOWN EX REINFORGEMENT	1 PC	680.55	680.55
50.	KLAN DOWN EN LOWER DRACKET	1 PC	36.70	36.70
51.	REAR BUMPER LOWER GARNISH	1 PC	62.10	62.10



Main Office:

Mova Building No. 22, Jalan Kilang, Singapore 159419 Tel: (65) 6476 3333 Fax: (65) 6271 5891

www.mova.com.sg **Workshop Dept:**

Block 1008, Bukit Merah Lane 3, #01-04/06/08/94 Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8314

Co. Reg. 198904033G GST Reg. M2-0088864-2

Estimate

04/06/2019

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road #16-01 City House Singapore 068877.

Attention :- XA026

Estimate# :- CK419246

Page #

Veh#

Veh Model :-

ACC. Date :- 02/06/19

Terms

Claim #

:- C.O.D Days

SLL8208K

VOLKSWAGEN CADDY

135172

Remarks

No.	Description	Qty	U.Price Amounts S\$
52.	REAR BUMPER CLIPS / n/c LIST TOTAL S\$ SVM - Wash tank / CRU \$140	10 PC	3.90 3.90 3.900 21,238.90 -2,123.89
	P- 19B	7-60	19,115.01
1.	SPECIAL NET ITEMS: FRONT NUMBER PLATE / BR SVM - 144.5	1 PC	60.00 35 60.00
	SPECIAL NET TOTAL 35	J-7S	60.00
	LABOUR: TO CUT AND WELD SUPPORT. TO REPAIR FRONT 1- 2160 INNER PANEL, FRONT DOOR LH, REAR BOOT, REAR PANEL. TO STRAIGHTEN & REALIGN AFFECTED AREAS	· 7	900 1,400.00
	TO SPRAY AFFECTED AREAS	0-13	1/90 1,200.00
	TO REMOVE & REFIX REAR SENSOR & CHECK WIIRNG	5,567.90	30 40.00
	TO REMOVE & REFIX A/C CONSENSER, ELECTRIC FAN HOSE PIPE, VACUUM & REFILLING GAS	5,550.00	100/? 150.00
	TO CHECK WIRING & FOCUS HEAD LIGHT		30 150.00
	LABOUR TOTAL S\$		2,940.00

E. & O.E

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parl Customer's Signature/Co. Stamp
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

22244.92

22, 244.93

22,115.01

1,548.05

23,663.06

NON-TAX AMOUNT S

AMOUNT S\$

GST @ 7 %

AMOUNT DUE S\$

Stew (LKX) INL AMIL 7/6/19, 11-30 and LIS 9 dy Ry AC SM. 1



Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008, Bukit Merah Lane 3, #01-04/06/08/94 Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8314

Co. Reg. 198904033G GST Reg. M2-0088864-2

Estimate

04/06/2019

MS FIRST CAPITAL INSURANCE LIMITED 36 Robinson Road #16-01 City House

Singapore 068877.

Attention :- XA026

Veh # :- SLL8208K

Veh Model :- VOLKSWAGEN CADDY

Estimate# :- CK419246

Claim #

ACC. Date :- 02/06/19

Terms .- C.O.D Days

Remarks :-

VO.	Description	Qt	У	U.Price	Amounts S\$
	LIST ITEMS: An	mentary \$ 144.35 1			
1.	BONNET	1 25 1111	PC	2,514.35	2,514.35
2.	BONNET SPONGE CLIPS / 1/2 DK WOOLD	tank \$ 147.3) 20	PC	3.90	
3.	/	2	PC	116.95	233.90
4.	BONNET LOCK TOP X	-1	PC	85.40	
5.	BONNET LOCK LOWER / 1/T	4	PC	140.85	
6.	GRIILE / DR	1	PC	436.75	
7.	GRILLE LOGO / CK GRILLE LOGO BASE / DK	1	PC	119.15	
8.	21	1	PC	45.30	
9.	HEADLAMP L+R / 100	2	PC	2,097.50	4,195.00
10.	HEADLAMP TOP PANEL L+R / VII 0 ×	2	PC	68.15	136.30
11.	HEADLAMP LOWER BRACKET L+R	2	PC	22.30	44.60
12.	HEADLAMP FASTENER	4	PC	17.20	68.80
13.	SUPPORT PANEL / NA	1	PC	1,227.75	1,227.75
14.	BRACE PANEL / 87	1	PC	107.55	107.55
15.	FRONT BUMPER > UX	1	PC	1,161.90	1,161.90
16.	FRONT BUMPER LOWER GRILLE	1	PC	271.65	271.65
17.	FRONT BUMPER CHROME	1	PC	235.30	235.30
18.	FRONT BUMPER TOW COVER / (KM) ×	1	PC	39.65	39.65
19.	FRONT BUMPER FOG LIGHT L+R	2	PC	225.60	451.20
20.	PRONT BUMPER FUG LIGHT COVER L+R	2	PC	121.90	243.80
21.	FRONT BUMPER SPONGE / 1/1	. 1	PC	170.00	170.00
22.	FRONT BUMPER REINFORCEMENT	1	PC	748.80	748.80
23.	FRONT BUMPER WASHER JET L+R FRONT BUMPER WASHER JET BRACKET	2	PC	146.25	292.50
24.	A.	2	PC	204.45	408.90
25. 26.	FRONT BUMPER SIDE BRACKET L+R / //R FRONT BUMPER CLIPS / /P(2	PC	67.75	135.50
27.	0 - 607	10	PC	3.90	39.00
28.		1	PC	141.20	
29.	FRONT FENDER COWLING LAB	2	PC	683.95	
30.	FRONT FENDER COWLING L+R × FRONT FENDER COWLING RIVET X	2	PC	109.30	
31.	EBONT FENDER CICNAL LAND LL X	16		3.90	
32.	FRONT 1/4 GLASS MOULDING LH X	1	PC	38.45	
33.	A/C CONDENSER	1	PC	473,50	
34.	AIR COOLER	1	PC	631.35	
35.	RADIATOR ?	1	PC	554.65	
36.	RADIATOR BRACKET WAR ? RH / PR	1	PC	549.75	
37.	RADIATOR HOSE TOP	2	PC	45.10	
38.	PARIATOR HOSE LOWER Y	1	PC	76.65	
39.	AIR RESONATOR	1	PC	146.10	
40.	AIR DUCT X	1	PC	210.55	
41.	AIR HOSE X	1	PC	62.45	
42	REAR EMBLEM "CADDY"	1	PC	39.50	
43.	and the second s	1	PC	58.35	
44.	REAR BOOT LOWER CHROME ?	1	PC	68.75	
45.	PEAR RUMPER / (PV	1	PC	362,35	
46.	REAR BUMPER SENSOR / DR	1		985.80	
47.	REAR BUMPER REFLECTOR,LH X		PC	280.85	
48.	REAR BUMPER SPONGE × 1 / 00	1	90	42.35	
49.	REAR BUMPER REINFORCEMENT - A	1	1	46.10	
50.	REAR BUMPER LOWER BRACKET	1		680.55	
51.	REAR BUMPER LOWER GARNISH	1	1100000	36.70	
51.	REAR BUMPER LOWER GARNISH	1	PC	62.10	62.10



Main Office:

Mova Building No. 22, Jalan Kilang, Singapore 159419 Tel: (65) 6476 3333 Fax: (65) 6271 5891 www.mova.com.sg

Workshop Dept: Block 1008, Bukit Merah Lane 3, #01-04/06/08/94 Singapore 159722

Tel: **(65) 6272 3892** Fax: **(65) 6270 8314**

Co. Reg. 198904033G GST Reg. M2-0088864-2

Estimate

04/06/2019

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road #16-01 City House

Singapore 068877.

Estimate# :-CK419246

VOLKSWAGEN CADDY

:- SLL8208K

135172

Claim #

ACC. Date :- 02/06/19

Page#

Veh#

Veh Model :-

:- C.O.D Days

Attention :- XA026

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
52.	REAR BUMPER CLIPS / 1016	10 PC	3.90	J# 39.00
	LIST TOTAL S\$			21.238.90
	10% DISCOUNT S\$ 19301.20			-2,123.89
	Syppolementaly 144.35		-	19,115.01
	SPECIAL NET ITEMS: \$ 19445.55		-	
1.	FRONT NUMBER PLATE / NK	- 1 PC	60.00	35 60.00
	SPECIAL NET TOTAL S\$ -10% 1944.55		-	60.00
	LABOUR: \$ 17501.5	5	***	
		10 - SNet		Oal
	PANEL. TO STRAIGHTEN & REALIGN AFFECTED AREAS 22 (0 - 0	OU - LB		900 1.400.00
	TO SPRAY AFFECTED AREAS			1100 1.200.00
	TO REMOVE & REFIX REAR SENSOR & CHECK WIIRNG # 19746.	55		30 40.00
	TO REMOVE & REFIX A/C CONSENSER, ELECTRIC FAN	1		2
	HOSE PIPE, VACUUM & REFILLING GAS	0		150.00
	TO CHECK WIRING & FOCUS HEAD LIGHT			30 150.00
	LABOUR TOTAL S\$ 9 days		\$221	2,940.00
				1

E. & O.E

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

NON-TAX AMOUNT S

AMOUNT S\$ GST @ 7 %

22,115.01 1,548.05

AMOUNT DUE S\$

23,663.06

Steve Chen (LKK Auto)

From:

Keong <keong@mova.com.sg>

Sent:

Saturday, July 20, 2019 11:19 AM

To:

Steve Chen (LKK Auto); Veron Chen (LKKAuto)

Cc:

'Enny'; 'Suann'; 'JIAYU'

Subject:

RE: SLL8208K Ready For Finalise

Dear Steve Confirmed

Best Regards,

Goh Chai Hock (Keong)

Claims Estimator

Mova Automotive Pte Ltd

HP: 96510098

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]

Sent: Friday, 19 July 2019 5:58 PM
To: Keong; Veron Chen (LKKAuto)
Subject: SLL8208K Ready For Finalise

Hi Ah Keong,

We have come out with the finalize \$15,550.00 (L/S, before GST). 9 days.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: <u>SteveChen@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keong [mailto:keong@mova.com.sq]

Sent: Friday, July 19, 2019 9:37 AM

To: Steve Chen (LKK Auto); Veron Chen (LKKAuto)

Subject: SLL8208K Ready For Finalise



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

383		Affiliated to Federation Interna	ationale Des Experts En Auton	nobile
MS I	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI190100	75/Evd3e2
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 08-08-2019 Code: FCI2	
١.		Policy Particula	rs :- THIRD PARTY CLAI	IM
	Insured Veh.	SHC 8208E	Veh. Inspected	SLL 8208K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19003674MFSH	Excess (\$)	0.00
	Assign From	EILEEN LEE	Assign Date	06/06/2019
2.	THE PARTY OF	Vehicle Pa	rticulars & Condition	
	Make & Model	VOLKSWAGEN CADDY	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WV2ZZZ2KZHX068816	Colour	BLUE
	Odometer	75118	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Cond	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/50Z R17	DUNLOP	7 mm
	L/H Front Tyre	205/50Z R17	DUNLOP	7 mm
	R/H Rear Tyre	205/50Z R17	DUNLOP	7 mm
	L/H Rear Tyre	205/50Z R17	DUNLOP	7 mm
1.		Descrip	otion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT AND REAR PORTIC	DN.
	DAMAGES SEE D	ETAILS.		
5.		Gene	eral Information	
	Accident Date	02/06/2019	Inspection Date	07/06/2019
	Survey held at	MOVA AUTOMOTIVE PTE L	TD	
		BLK 1008 BUKIT MERAH LA SINGAPORE 159722	NE 3 #01-04/06/08 .	
5a.		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Remarks	
	B)THE INSPECTION	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A"\ CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	

Estimate Days of Repair

9 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8208K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	DENTED	2,514.35	2,514.35
20	BONNET SPONGE CLIPS @\$3.90	NECESSARY	78.00	20.00
2	BONNET HINGE L+R @\$116.95	NOT NECESSARY	233.90	-
1	BONNET LOCK TOP	BENT	85.40	85.40
1	BONNET LOCK LOWER	BENT	140.85	140.85
1	GRILLE	BROKEN	436.75	436.75
1	GRILLE LOGO	BROKEN	119.15	119.15
1	GRILLE LOGO BASE	BROKEN	45.30	45.30
2	HEADLAMP L+R @\$2097.50	BROKEN	4,195.00	4,195.00
2	HEADLAMP TOP PANEL L+R @\$68.15	DENTED	136.30	136.30
2	HEADLAMP LOWER BRACKET L+R @\$22.30	NOT NECESSARY	44.60	:=
4	HEADLAMP FASTENER @\$17.20	NECESSARY	68.80	20.00
1	SUPPORT PANEL	BROKEN	1,227.75	1,227.75
1	BRACE PANEL	BENT	107.55	107.55
1	FRONT BUMPER	BROKEN	1,161.90	1,161.90
1	FRONT BUMPER LOWER GRILLE	CRUSHED	271.65	271.65
1	FRONT BUMPER CHROME	BROKEN	235.30	235.30
1	FRONT BUMPER TOW COVER	CRUSHED	39.65	39.65
2	FRONT BUMPER FOG LIGHT L+R @\$225.60	NOT NECESSARY	451.20	-
2	FRONT BUMPER FOG LIGHT COVER L+R @\$121.90	BROKEN	243.80	243.80
1	FRONT BUMPER SPONGE	BROKEN	170.00	170.00
1	FRONT BUMPER REINFORCEMENT	BENT	748.80	571.00
2	FRONT BUMPER WASHER JET L+R @\$146.25	NOT NECESSARY	292.50	-
2	FRONT BUMPER WASHER JET BRACKET @\$204.45	BROKEN	408.90	408.90
2	FRONT BUMPER SIDE BRACKET L+R @\$67.75	BROKEN	135.50	135.50
10	FRONT BUMPER CLIPS @\$3.90	NECESSARY	39.00	30.00
1	FRONT BUMPER WASHER TUBE	CUT	141.20	141.20
2	FRONT FENDER L+R @\$683.95	DENTED	1,367.90	1,367.90
2	FRONT FENDER COWLING L+R @\$109.30	NOT NECESSARY	218.60	-
16	FRONT FENDER COWLING RIVET @\$3.90	NOT NECESSARY	62.40	
1	FRONT FENDER SIGNAL LAMP LH	NOT NECESSARY	38.45	-

Report Ref No. CS/FCI19010075/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT 1/4 GLASS MOULDING LH	CRUSHED	473.50	473.50
1	A/C CONDENSER	DENTED	631.35	631.35
1	AIR COOLER	DENTED	554.65	554.65
1	RADIATOR	DENTED	549.75	549.75
2	RADIATOR BRACKET L+R @\$45.10	O/S BROKEN	90.20	45.10
1	RADIATOR HOSE TOP	NOT NECESSARY	76.65	-
1	RADIATOR HOSE LOWER	NOT NECESSARY	146.10	-
1	AIR RESONATOR	BROKEN	210.55	210.55
1	AIR DUCT	NOT NECESSARY	62.45	-
1	AIR HOSE	NOT NECESSARY	39.50	-
1	REAR EMBLEM "CADDY"	NECESSARY	58.35	58.35
1	REAR EMBLEM "TSI"	NECESSARY	68.75	68.75
1	REAR BOOT LOWER CHROME	NECESSARY	362.35	362.35
1	REAR BUMPER	CRUSHED	985.80	985.80
2	REAR BUMPER SENSOR @\$280.85	BROKEN	561.70	561.70
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	42.35	-
1	REAR BUMPER SPONGE	NOT NECESSARY	46.10	-
1	REAR BUMPER REINFORCEMENT	DENTED	680.55	680.55
1	REAR BUMPER LOWER BRACKET	NOT NECESSARY	36.70	-
1	REAR BUMPER LOWER GARNISH	NOT NECESSARY	62.10	-
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	30.00
1	WASHER TANK	CRUSHED	144.35	144.35
	LESS 10% DISCOUNT		-2,138.33	-1,918.20
			19,244.92	17,263.75
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BROKEN	60.00	35.00
			60.00	35.00
	LABOUR			
	TO CUT AND WELD SUPPORT. TO REPAIR FRONT INNER PANEL, FRONT DOOR LH, REAR BOOT, REAR PANEL. TO STRAIGHTEN & REALIGN AFFECTED AREAS.		1,400.00	900.00
	TO SPRAY AFFECTED AREAS.		1,200.00	1,100.00
	TO REMOVE & REFIX REAR SENSOR & CHECK WIRING.		40.00	30.00

Report Ref No. CS/FCI19010075/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE & REFIX A/C CONDENSER, ELECTRIC FAN HOSE PIPE, VACUUM & REFILLING GAS.		150.00	100.00
	TO CHECK WIRING & FOCUS HEAD LIGHT.		150.00	30.00
			2,940.00	2,160.00
	GRAND TOTAL		22,244.92	19,458.75

RECOMMENDED COST OF LUMP SUM REPAIRS	15,550.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI19010075/Evd3e2

1

CHEN TSUE YEE

Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.