

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0726/2019/DY/TF
Date : 7-Jun-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Zulaiha Binti Yusuf
Address : 156 Mariam Way
#04-08
Singapore 507082
Telephone : (HP) +65 96249893
Type of Claim : Own Damage Claim
Policy No. : 1800126076
Vehicle No : **SMF 275 M**
Model Code : Audi A3 Sedan 1.0 TFSI CO
Model / Year : Oct-18
Engine No : CZE 697739
WAUZZZ8V9J1080215
Mileage : 11841
Date In : 6-Jun-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jun-19
Place of Accident : Thomson Flyover PIE (Tuas)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMF 0275 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00 ? ✓	
3	To dismantle and renew front bumper, lhs front fender, bonnet and both headlights. Remove and renew lock carrier and align console to position. Reinstall all parts removed.	\$ 5,600.00 2750	1250 (without lock carrier) 2500 (with lock carrier)
4	To respray front bumper, lhs front fender, bonnet and hinges.	\$ 3,200.00 1100	
5	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 10,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 0275 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	FRONT BUMPER Distorted.	\$	1,830.00	✓ 1464
2	FRONT BUMPER FIXING PARTS <i>2 pieces</i>	\$	170.00	+
3	FRONT BUMPER GUIDE SECTION - LH <i>Damaged</i>	\$	35.00	+ 27.52 ✓
4	FRONT BUMPER GRILLE - CENTER <i>Crushed</i>	\$	146.00	✓ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Crushed</i>	\$	488.00	x. ✓ 390
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Crushed</i>	\$	540.00	x. ✓ 216
7	FRONT BUMPER COVER TRIM - LH / RH <i>RH Deformed.</i>	\$	296.00	? ✓ 118.40
8	FRONT BUMPER ADAPTER - LH / RH <i>Not new</i>	\$	68.00	x
9	RADIATOR GRILLE <i>Crushed</i>	\$	1,304.00	✓ 1040.20
10	RADIATOR GRILLE CLOSING ELEMENT <i>Crushed</i>	\$	174.00	✓ 138.30
11	FRONT AIR GRILLE - LH / RH <i>Not new LH Damaged.</i>	\$	342.00	x ✓ 136.40 ✓
12	FRONT CARRIER <i>Bent.</i>	\$	660.00	? ✓ 527.60
13	FOAM FILLER PIECE <i>Deformed</i>	\$	172.00	? ✓ 137.60
14	FRONT CARRIER COVER <i>Deformed.</i>	\$	111.00	? ✓ 88.80
15	A/C STICKER <i>Not</i>	\$	7.00	✓ 5.12
16	CAUTION STICKER <i>Not</i>	\$	13.00	✓ 9.76
17	BONNET <i>Deformed.</i>	\$	2,898.00	✓ 2318.40
18	BONNET ATTACHMENT PARTS <i>Not new</i>	\$	149.00	? x
19	BONNET HINGE - LH / RH <i>Not new</i>	\$	112.00	x
20	BONNET ABSORBER <i>Not new</i>	\$	109.00	x
SUB - TOTAL SPARE PARTS CHARGES		\$	9,624.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 0275 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONNET CATCH - TOP <i>Damaged</i>	\$ 81.00	? ✓ 64.72
22	BONNET STRIKER <i>Part</i>	2 \$ 200.00	? ✓ 159.04
23	BONNET EDGE PROTECTION <i>new</i>	\$ 25.00	✓ 19.92
24	BONNET CATCH - BOTTOM <i>Bent.</i>	\$ 58.00	? ✓ 45.76
25	BONNET LOCK <i>new new</i>	2 \$ 367.00	? X
26	BONNET BOWDEN CABLE	\$ 53.00	X
27	BONNET BOWDEN CABLE COVER	\$ 9.00	X
28	BONNET LOCK CABLE	\$ 67.00	X
29	FRONT FENDER - LH <i>new new</i>	\$ 778.00	X
30	FRONT FENDER RIVET <i>new</i>	\$ 15.00	X
31	FRONT FENDER ATTACHMENT PARTS - LH	\$ 65.00	X
32	FRONT FENDER BRACKET	2 \$ 60.00	X
33	FRONT FENDER BRACE - LH	\$ 88.00	X
34	FRONT WHEEL HOUSING LINER SEAL - LH	\$ 31.00	X
35	FRONT WHEEL HOUSING LINER - LH	\$ 158.00	X
36	HEADLIGHT - LH / RH <i>LH cracked RH</i>	\$ 10,058.00	5029. 4023.20
37	LIFT CYLINDER HOSE	\$ 61.00	X
38	LIFT CYLINDER - LH	\$ 128.00	X
39	LIFT CYLINDER - RH	\$ 128.00	X
40	HORN - LOW / HIGH TONE <i>Not New</i>	\$ 364.00	X
SUB - TOTAL SPARE PARTS CHARGES		\$ 12,794.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 0275 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	LOCK CARRIER <i>Del'd</i>	\$ 663.00	?/530.40
42	A/C CONDENSER <i>Bent</i>	\$ 503.00	?/402
43	RADIATOR <i>Bent</i>	\$ 878.00	?/702.40
44	ADDITIONAL COOLER <i>Bent</i>	\$ 837.00	?/669.60
45	COOLANT <i>New</i>	\$ 84.00	?/67.20
46	FAN RING <i>New</i>	\$ 181.00	?/X
47	RADIATOR FAN WITH FAN RING <i>New</i>	\$ 1,046.00	?/X
48	RADIATOR AIR GUIDE - LH / RH <i>Behind</i>	\$ 44.00	?/34.24
49	RADIATOR SEAL - RIGHT OUTER <i>New</i>	\$ 8.00	?/5.68
50	RADIATOR AIR GUIDE - CENTRE <i>Del'd</i>	\$ 11.00	?/8.32
51	FRONT NO. PLATE <i>Bent.</i>	S/N \$ 40.00	✓
52	SUNDRIES <i>New</i>	\$ 300.00	?/1184
	TOTAL SPARE PARTS CHARGES	\$ 27,013.00	
	TOTAL LABOUR CHARGES	\$ 10,552.00	
	GRAND TOTAL	\$ 37,565.00	

38079

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *06/06/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 06 Days (Without lock carrier)
08 Days (With lock carrier)*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0726/2019/DY/TF

13-Jun-19

Glory Tan

1 of 1

SMF 275 M

Audi A3 Sedan 1.0 TFSI CO

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front bumper guide section RHS <i>CR</i>	\$ 35.00	27.52
2	Bonnet lid lock with micro switch <i>BT</i>	\$ 367.00	293.60
3	Front bumper bracket <i>BT</i>	\$ 17.00	13.44
4	Radiator bush <i>ac</i>	\$ 18.00	14.24
5	Radiator bracket <i>Bay d</i>	\$ 77.00	✓ 30.64
		<u>\$ 514.00</u>	

LABORS

TOTAL \$ 514.00

For Premium Automobiles Pte Ltd

Authorised Signature

LKIC Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (if any) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: