

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991630/AMK**Date: 17 Jun 2019****Policy No: 5093719884-01****Veh Reg No: SFV7900U****Make/Model: FORD FOCUS 1.6
TREND 5DR****WS Ref: TP/AIG/AMK****Claim Type: Third Party****Accident Date: 02/06/2019****Chassis No: WF0PXXWDPBC62050****Engine No: BC62050****Reg. Date: 14/09/2011****Estimate Repair Cost to Vehicle No :SFV7900U**

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	1,050.00	1 PC	1,050.00	✓
2 FRONT BUMPER RH SIDE RETAINER	45.00	1 PC	45.00	✓
3 FRONT BUMPER RH FOG LAMP	298.00	1 PC	298.00	?
4 FRONT BUMPER RH FOG LAMP GARNISH	85.00	1 PC	85.00	?
5 FRONT BUMPER CLIP	5.50	6 PC	33.00	✓
6 HEADLAMP RH	395.00	1 PC	395.00	✓
7 FRONT RH FENDER	589.00	1 PC	589.00	✓
			2,495.00	
		Less 20%	499.00	1,996.00
Labour				
8 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, RADIATOR & MOTOR, FRT RH FENDER; TO KNOCKING & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	600.00	1 LA	600.00	450
9 TO PUTTY & RESPRAY ON FRT RH FENDER, FRT RH DOOR, FRT SUPPORT PANEL, FRT BUMPER & AFFECTED AREAS	800.00	1 LA	800.00	600
10 REMOVE & REFIX FRT RH SPORT RIM, REPAIR, PUTTY & RESPRAY & CONDUCT COMPUTER ON WHEEL BEARING	100.00	1 LA	100.00	60
11 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,530.00	1,530.00
		Total	S\$ 3,526.00	
		Add GST @ 7%	246.82	
		Total Amount Payable	S\$ 3,772.82	

*** SURVEY VEHICLE AT ANG MO KIO WORKSHOP****For Cheng Hoe Motor Pte Ltd****DORLYN LI****AUTHORISED SIGNATURE**

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date: