

ASS. REC. BY:

REF: CS/SM019010137/ E4d3n2

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Wong Lee Sin

of SMO

Date/Time: 6.6.2019 16.52 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 8437L

Insured:

at Workshop m/s Kah Motor

Tel: 90721769

of 255 Alexandra Road

Policy No: D18M1PV01016812

Claim No: CM1D190296

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 3.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.6.19 2.07 pm

Person Contacted: Sin Hui

Vehicle **IN** / OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 8437L-X
10/6/19	Revised 1A via Merimen
	Part by Part \$9,980.97 (Red: 5799.92: 36%)

ASS. REC. BY:

Steve

REF: SMO

ASSIGNMENT

From:

Date:

7/6/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLH 8437L

at Workshop m/s

Kah Motor

of

No. 255 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Sin Hai
After 11am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

81K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA

REV

REP. / 24 HRS

if consistent

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLH 8437L

Yr Regn:

21/11/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c.

1597

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp Reading

36659

T/Radio:

Insured / Std / NI / NA

Eng/No:

MRHFC 56596T000-537

C/Nr:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/55R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

3/6/19

D.O.I.

7/6/19

Survey held at

Kah motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-8/K

RECEIVED 17 JUN 2019

Date/Time, File Pass to?

☐

Prel. Report

1) 14/6 Typist

☒

Final Report

Date/Time, File Return to?

2)

Report Form:

MD

Lump Sum / UIC

9980.97

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos:

Others:

TOTAL

450

11

461

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: WONG, LEE SIN LORRIANCE

Date: 10 Jun 2019

Preliminary Advice

Vehicle No	: SLH8437L	Accident Date	: 03/06/2019
Make	: HONDA CIVIC	Policy No.	: D18MTPV01016812
Assignment Date	: 06/06/2019	Excess	: S\$500.00
Date of Inspection	: 07/06/2019	Est. Duration of Repair	: 12.00
Inspection At	: KAH MOTOR CO SDN BHD (ALEXANDRA) 255 ALEXANDRA ROAD SINGAPORE -		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,453.16
Revised Amount	:S\$	9,382.64
Check Items (Estimated)	:S\$	2,914.79
Total	:S\$	12,297.43

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	81,000.00
COE / PARF Rebate	:S\$	54,265.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,735.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019		06 Jun 2019 16:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TOH HONG SENG, ID: S8114831G, Tel: +6591099452, Email: NOEMAIL								
Vehicle Reg. No.:	SLH8437L	Date of Loss:	03/06/2019 16:00 - :59						
Claim Type:	OD / CMTD1902696	Policy/Cover Note No.:	D18MTPV01016812 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by WONG, LEE SIN LORRIANCE - 6329 5175]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/06/2019]								
Driver/Custodian:	TOH HONG SENG (38 / Male) , NRIC: S8114831G, Tel: +6591099452 Email: NOEMAIL								
Adj Asg. Remarks:	SIN HAI 90721769 / 6471 5419 ESTIMATE NOT READY - PLS ARR SUV TMR 07/06/19								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
• GraceTeo (07/06/2019): OD EXCESS & AUTHORISATION									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 14 June 2019 4:18 PM
To: shng@kahmotor.onmicrosoft.com
Subject: RE: Submission Pre-Invoice for vehicle SLH8437L

Dear Sin Hai,

Confirm part by part \$9,980.97 before excess and GST, 7days.

Please submit your documents directly to Sompoo insurance.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Friday, 14 June 2019 8:47 AM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SLH8437L

Dear Mr Steve,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$9,480.97 (before GST)

No of working days : 07 days. (LOR)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/06/2019 20:36
Date Of Accident	03/06/2019 16:05
Exact Location Of Accident	AYE TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH8437L
Insured/Policyholder	
Name Of Registered Owner	TOH HONG SENG
NRIC No	S8114831G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91099452
Alternative Phone No	OFFICE-91099452

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	TOH HONG SENG
NRIC No	S8114831G
Date Of Birth	21/05/1981
Occupation	INDOOR
Date Of Driving Pass	07/03/2002
Driving Experience	17 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91099452
Fax Number	
Contact Number	OFFICE-91099452
EEmail Address	NOEMAIL

REPUBLIC OF SINGAPORE DRIVING LICENCE

Vehicle Number: S8114831G

Name: TOH HONG SENG

Birth Date: 21 May 1981

Valid Until: 27 Feb 2023

NRIC Number: S8114831G



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8114831G

Name: TOH HONG SENG

Chinese Name: 李鴻生

Race: CHINESE

Date of Birth: 21-05-1981

Sex: M

Country of Birth: SINGAPORE




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which combined does not exceed 2500 kilograms

Valid Until: 27 May 2023

NRIC Number: S8114831G

NP 4284



4780744

NRIC No: S8114831G

Date of Issue: 08-11-2011

APT BLK 948D JURONG WEST STREET 81 #04-214 SINGAPORE 944848

NRIC No: S8114831G Date: 04/12/2015




[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	4831G

Vehicle Details

Vehicle No.:	SLH8437L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	R16B21600706
Chassis No.:	MRHFC5650GT000537
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,689.00
Original Registration Date:	21 Nov 2016
First Registration Date:	21 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$19,689.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2026
PARF Rebate Amount:	\$14,766.00

Intended COE Rebate Details

COE Expiry Date:	20 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$39,499.00
Total Rebate Amount:	\$54,265.00

The information contained herein is correct as at 07 Jun 2019

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: SOMPO INSURANCE SINGAPORE PTE LTD	Document No.	: SQT19002473	Page	1
	50 RAFFLES PLACE #05-01/06	Date	: 6. Jun 2019		
	SINGAPORE LAND TOWER	Customer No.	: WH023		
	SINGAPORE 048623	Svc Advisor	: NG SIN HAI		
Registration No	: SLH8437L	Engine No	: R16B21600706		
Chassis No	: MRHFC5650GT000537	Date Time	: 6. Jun 2019 6:37:31 PM		
Model	: CIVIC 1.6 VTI YM2016	Surveyor Name	:		
Owner's Name	: TOH HONG SENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 3/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO:						
	POLICY/CLAIMS NO:						
	OWNER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	AUTHORIZED ON:						
	REF NO:						
BOSUN	SUNDRIES <i>rel</i>	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 <i>/</i>		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 <i>/</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 <i>? X</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00 <i>/</i>		80.00	5.60	85.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00 <i>/</i>		560.00	39.20	599.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 <i>/</i>		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	560.00 <i>? X</i>		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00 <i>/</i>		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>280</i>		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL <i>560 (Fhr - 440)</i>	1	5000.00 <i>2800</i>		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>450</i>	1	3000.00 <i>2700</i>		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	450.00 <i>? X</i>		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	560.00 <i>480</i>		560.00	39.20	599.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00 <i>? X</i>		450.00	31.50	481.50
			Sum Labor		12400.00	868.00	13,268.00
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00 <i>X W</i>		45.00	3.15	48.15

Printed on 6/6/2019 6:47:04 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SLH8437L
Chassis No : MRHFC5650GT000537
Model : CIVIC 1.6 VTI YM2016
Owner's Name : TOH HONG SENG
Ins Policy No. :
Date of Accident : 3/6/2019

Document No. : SQT19002473 Page 2
Date : 6. Jun 2019
Customer No. : WH023
Svc Advisor : NG SIN HAI
Engine No : R16B21600706
Date | Time : 6. Jun 2019 6:37:31 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	28.10	25	21.07	1.47	22.54
39670-TEX-Y01	SENSOR UNITPARKING	1	62.50	25	46.87	3.28	50.15
39680-TEX-Y41ZT	① SENSOR ASSY,PARKING	1	145.80	25	437.40	30.62	468.02
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
33550-TEA-T01	② TAILLIGHT ASSYL	1	281.30	25	210.97	14.77	225.74
34150-TEX-Y01	LIGHT ASSYR.LID	1	122.30	25	91.72	6.42	98.14
34155-TEX-Y01	LIGHT ASSYL.LID	1	122.30	25	91.72	6.42	98.14
68500-TEA-N00ZZ	③ LID COMP TRUNK	1	486.20	25	364.65	25.53	390.18
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	44.80	25	33.60	2.35	35.95
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	44.80	25	33.60	2.35	35.95
74851-TEA-003	④ LOCK ASSYTRUNK	1	74.30	25	55.72	3.90	59.62
74865-TEA-T01	⑤ WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	⑥ GARNISH ASSYRR.LICENSE	1	100.60	25	75.45	5.28	80.73
75722-TBA-A00	⑦ EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	⑧ EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	⑨ FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	⑩ GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71503-TEA-T00	⑪ GARNISH R.RR.BUMPER SIDE	1	8.40	25	6.30	0.44	6.74
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71508-TEA-T00	⑫ GARNISHL.RR.BUMPER SIDE	1	7.80	25	5.85	0.41	6.26
71530-TEA-T00ZZ	⑬ BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71593-TEA-T01	⑭ SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	⑮ SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	⑯ CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TEC-307ZZ	⑰ PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	216.70	25	162.52	11.38	173.90
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	60.20	25	45.15	3.16	48.31

Printed on 6/6/2019 6:47:04 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SLH8437L
Chassis No : MRHFC5650GT000537
Model : CIVIC 1.6 VTI YM2016
Owner's Name : TOH HONG SENG
Ins Policy No. :
Date of Accident : 3/6/2019

Document No. : SQT19002473
Date : 6. Jun 2019
Customer No. : WH023
Svc Advisor : NG SIN HAI
Engine No : R16B21600706
Date | Time : 6. Jun 2019 6:37:31 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84542-TET-H00	BOX COMPTOOL X NAI	1	38.00	25	28.50	2.00	30.50
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE X NAI	1	48.90	25	36.67	2.57	39.24
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE X NAI	1	48.90	25	36.67	2.57	39.24
72841-SH3-315	OILSHEET ? NAI	3	40.70	25	91.57	6.41	97.98
Sum Item					3053.16	213.72	3,266.88

Survey By

Date & Time

Excess

Status

Signature

Total Amount 15,453.16 1,081.72 16,534.88

Total (Inclusive of GST) 16,534.88

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 6/6/2019 6:47:04 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651 Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937 Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: ****4831G / TOH HONG SENG
Chassis No: MRHFC5650GT000537
License No: SLH8437L
Mileage: 34625
Engine No: R16B21600706

Document No: SVO19035814
Printed By: SHNG
Order Date: 7. June 2019
Order Time: 1:43:20 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	SUPPLEMENTARY						
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	25	6.52	0.46	6.98
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
39530-TBA-A01	CAMERA ASSYRR.VIEW	1	315.60	25	236.70	16.57	253.27
38387-TZ5-A01	ANTENNA ASSYLF.	1	59.30	25	44.47	3.11	47.58
	SUM PARTS:				327.73	22.94	350.67
	TOTAL SGD				327.73	22.94	350.67

Total Payable (SGD)

350.67

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WH023 / SOMPO INSURANCE
Chassis No: MRHFC5650GT000537
License No: SLH8437L
Mileage: 34625
Engine No: R16B21600706

Document No: SVO19035814
Printed By: SHNG
Order Date: 7. June 2019
Order Time: 1:43:20 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: OWNER:TOH HONG SENG ACC DATE:03/06/2019 SURVEYED BY:STEVE DATE:07/06/2019 AUTHORIZED ON : REF NO : EXTERNAL LABOUR SALES - INS. EXCESS						
54206		-1	500.00		-500.00	-35.00	-535.00
	SUM EXCESS:				-500.00	-35.00	-535.00
39680-TEX-Y41ZT	1 SENSOR ASSY,PARKING	1	145.80	25	109.35	7.65	117.00
33550-TEA-T01	2 TAILLIGHT ASSYL	1	281.30	25	210.97	14.77	225.74
68500-TEA-N00ZZ	1 LID COMP TRUNK	1	486.20	25	364.65	25.53	390.18
74851-TEA-003	4 LOCK ASSYTRUNK	1	74.30	25	55.72	3.90	59.62
74865-TEA-T01	5 WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	6 GARNISH ASSYRR LICENSE	1	100.60	25	75.45	5.28	80.73
75722-TBA-A00	7 EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	8 EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	9 FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	10 GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71503-TEA-T00	11 GARNISH R,RR.BUMPER SIDE	1	8.40	25	6.30	0.44	6.74
71508-TEA-T00	12 GARNISHL,RR.BUMPER SIDE	1	7.80	25	5.85	0.41	6.26
71530-TEA-T00ZZ	13 BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17
71593-TEA-T01	14 SPACERR,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	15 SPACERL,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91506-TM8-003	16 CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TEC-307ZZ	17 PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
71506-TEX-Y00	18 COVERRR.TOWING HOOK	1	8.70	25	6.52	0.46	6.98
66114-TBA-A00ZZ	19 STIFFENER,R,RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	20 STIFFENERL,RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
39530-TBA-A01	21 CAMERA ASSYRR.VIEW	1	315.60	25	236.70	16.57	253.27
38387-TZ5-A01	22 ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
	SUM PARTS:				2,050.97	143.56	2,194.53
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0669 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	1610 SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	1610 SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BC012R	1610 RESET VEHICLE SMART ENTRY	1	560.00		560.00	39.20	599.20
BML02I	1610 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Customer: WH023 / SOMPO INSURANCE
Chassis No: MRHFC5650GT000537
License No: SLH8437L
Mileage: 34625
Engine No: R16B21600706

Document No: SVO19035814
Printed By: SHNG
Order Date: 7. June 2019
Order Time: 1:43:20 PM
Service Advisor: NG SIN HAI

BMI02D	0669 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00	560.00 /	39.20	599.20
BKTG02R	0669 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	280.00	280.00 /	19.60	299.60
BKRP02M	0669 CUT OFF & RENEW RR PANEL RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,800.00	2,800.00 /	196.00	2,996.00
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	2,700.00	2,700.00 /	189.00	2,889.00
BKBU01R	0669 REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00	480.00 /	33.60	513.60
			SUM LABOUR:	7,930.00 /	555.10	8,485.10
			TOTAL SGD	9,480.97 /	663.66	10,144.63
Total Payable (SGD)						10,144.63

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19010137/ETD3N2

Date: 19/06/2019

REFERENCE

Insured/Claimant: TOH HONG SENG Policy No: D18MTPV01016812
Date of Loss: 03/06/2019 Nature of Claim: OD Claim No: CMTD1902696

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH8437L
Make & Model: HONDA CIVIC, 1.8 (A) Engine No: R16B21600706
Reg. Date: 21/11/2016 (Man. Year: 2016) Chassis No: MRHFC5650GT000537
Colour: Blue Odometer: 36659 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$81,000.00
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R16 Rear Tyre Size: 215/55R16
Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm
Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,480.89	2,080.97	1,399.92	40.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,300.00	7,900.00	4,400.00	35.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,780.89	9,980.97	5,799.92	36.75
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	15,280.89	9,480.97	5,799.92	37.96
+ GST 7.00/7.00% (\$\$)	1,069.66	663.67	405.99	37.96
Nett Amount (\$\$)	16,350.55	10,144.64	6,205.91	37.96

INSPECTION

Date of Assignment: 06/06/2019
Date Inspected: 07/06/2019 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -
Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2019)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH8437L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*NUMBER PLATE WITH CASING-L	Not Necessary	45.00 FS	*- FS
3	1		*SUB CORDRR BUMPER CORNER SENS	Not Necessary	21.07 FS	*- FS
4	1		*SENSOR UNITPARKING	Not Necessary	46.87 FS	*- FS
5	1		*SENSOR ASSY PARKING (4 Pcs)	Broken (1 Pc only)	437.40 FS	*109.35 FS
6	1		*TAILLIGHT ASSYR	Not Necessary	196.05 FS	*- FS
7	1		*TAILLIGHT ASSYL	Broken	210.97 FS	*210.97 FS
8	1		*LIGHT ASSYR LID	Not Necessary	91.72 FS	*- FS
9	1		*LIGHT ASSYL LID	Not Necessary	91.72 FS	*- FS
10	1		*LID COMP TRUNK	Dented	364.65 FS	*364.65 FS
11	1		*HINGE COMPR TRUNK	Not Necessary	33.60 FS	*- FS
12	1		*HINGE COMPL TRUNK	Not Necessary	33.60 FS	*- FS
13	1		*LOCK ASSYTRUNK	Bent	55.72 FS	*55.72 FS
14	1		*WEATHERSTRIP TRUNK LID	Crumpled	52.50 FS	*52.50 FS
15	1		*GARNISH ASSYRR LICENSE	Crumpled	75.45 FS	*75.45 FS
16	1		*EMBLEM SETRR	Necessary	8.85 FS	*8.85 FS
17	1		*EMBLEMRR	Necessary	8.25 FS	*8.25 FS
18	1		*FACE ASSY RR BUMPER	Dented	462.90 FS	*462.90 FS
19	1		*GARNISH RR BUMPER LOWER	Cut	27.30 FS	*27.30 FS
20	1		*GARNISH R RR BUMPER SIDE	Cut	6.30 FS	*6.30 FS
21	1		*BRACKETR RR BUMPER SIDE	Not Necessary	1.72 FS	*- FS
22	1		*GARNISH L RR BUMPER SIDE	Cut	5.85 FS	*5.85 FS
23	1		*BEAM COMPRR BUMPER	Dented	123.52 FS	*123.52 FS
24	1		*BRACKETL RR BUMPER SIDE	Not Necessary	1.72 FS	*- FS
25	1		*SPACERR RR BUMPER SIDE	Broken	8.62 FS	*8.62 FS
26	1		*SPACERL RR BUMPER SIDE	Broken	8.62 FS	*8.62 FS
27	1		*CLIP BUMPER (7 Pcs)	Necessary	12.07 FS	*12.07 FS
28	1		*PANEL SETRR	Dented	182.32 FS	*182.32 FS
29	1		*PAN COMPSPARE TIRE	Not Necessary	162.52 FS	*- FS
30	1		*LINING ASSYRR PANEL	Not Necessary	37.72 FS	*- FS
31	1		*LID ASSYSPARE TIRE	Not Necessary	45.15 FS	*- FS
32	1		*BOX COMPTOOL	Not Necessary	28.50 FS	*- FS
33	1		*LINING ASSYR TRUNK SIDE	Not Necessary	36.67 FS	*- FS
34	1		*LINING ASSYL TRUNK SIDE	Not Necessary	36.67 FS	*- FS
35	3		*OILSHEET	Not Necessary	91.57 FS	*- FS
36	1		*COVERRR TOWING HOOK	Missing	6.52 FS	*6.52 FS
37	1		*STIFFENER R RR PANEL SIDE	Dented	20.02 FS	*20.02 FS
38	1		*STIFFENERL RR PANEL SIDE	Dented	20.02 FS	*20.02 FS
39	1		*CAMERA ASSYRR VIEW	Broken	236.70 FS	*236.70 FS
40	1		*ANTENNA ASSYL.F	Broken	44.47 FS	*44.47 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 3,480.89 2,080.97

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSORS-4 PCS	New	180.00	180.00
2	SEALANT FOR REAR END PANEL	New	80.00	80.00
3	SEALANT FOR REAR FLOOR PANEL	New	80.00	0.00
4	SEALANT FOR TAILGATE	New	80.00	80.00
5	RESET VEHICLE SMART ENTRY SYSTEM	New	560.00	560.00
6	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	180.00	180.00
7	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	0.00
8	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	560.00	560.00
9	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST	New	560.00	280.00
10	CUT OFF & RENEW RR PANEL	New	5,000.00	2,800.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	2,700.00
12	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	0.00
13	REMOVE,RE-FIX AND ALIGN REAR VIEW CAMERA	New	560.00	480.00
14	APPLY BODY UNDERSIDE COATING	New	450.00	0.00
Gross Labour Cost (\$\$)			12,300.00	7,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >