

UN0000

INS. CASE OWNER:

LOU CHIE HONG CC 6/AIG1900 10141, 4h6b

LKK:

IDAC:

Surveyor:

MARINS

DOI:

ASSIGNMENT

10/6/19

Date / Time:

10/6/19

Registered in Merimen:

10/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMJ 22365

Name of Insured:

STK LHM LHM MONGA

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

9/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

808A555G AGG

Policy No.:

190000109

Make / Model:

K10

Place of Accident:

UE

If NO. Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT YES / NO:

YES

NO

TP GIA REPORT YES / NO

YES

NO

Insured Liability:

%

Final ? Yes / No

GBC 9/11/19



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

4/11/19 - LCP (HONG KONG) 11/11/19

007/19/19 - 1

- OI VIDEO FOOTAGE w/ TRAFFIC POLICE

18/6/19

called OI on TP claim

- PINKU200

- TP LOD IN.

22/08/19

- THE REPORT FOR MANDATE APPROVAL

REPORT DONE.

12/09/19

- SUBMIT MANDATE TO AIG.

- AIG APPROVED MANDATE.

- SEND ACCIDENTANCE BULK TO TP

- ALL DONE IN ORBIT.

- TO CLOSE.

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI:

After call Itr to OI:

10/06/19 - SHAW

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L9

SS 10,500.00

7 days

Reduction: 47 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

Repair Cost: (w/60r)

SS 11,235.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

800.00

8 days

Loss of Income (LOI):

SS

(5 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

SS

200

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS 13,037.00

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

12,037.00

Name 1:

FASTECH AUTO MFG LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

-

Payee 3: (Strike if N.A.)

SS

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4520.00

ASS. REC. BY: *maxcus*

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/7/19

LTA 8009
L/S \$10,500 confirmed with Aler.
(RND: \$9,159.70 / 47%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
Date 10/6/19
10/6/19 7dy. 10500

VEHICLE NO: GBC 9511T

QTY	PARTICULAR			
1 PCS	FRONT BUMPER	452.60	75	\$745.20
1 PCS	FRONT BUMPER BRACKET O/S		11	\$290.00
1 PCS	HEADLAMP O/S		320	\$1,065.00
1 PCS	HEADLAMP RUBBER O/S		1011	\$28.00
1 PCS	FRONT GRILLE	680.10	cm	\$899.10
1 PCS	FRONT GRILLE LOGO		rer	\$68.50
1 PCS	FRONT PANEL		DO/ingh	\$1,685.10
1 PCS	FRONT PANEL 'DYNA' EMBLEM		rer	\$88.50
1 PCS	FRONT PANEL TOP BLACK GARNISH		11	\$288.10
1 PCS	FRONT CORNER PANEL O/S		2.5	\$405.00
1 PCS	FRONT CORNER PANEL TOP BLACK GARNISH O/S		cmg	\$186.10
1 PCS	FRONT CORNER PANEL TOP GARNISH O/S		CUT/cra	\$384.10
1 PCS	FRONT DOOR O/S		705	\$1,645.10
2 PCS	FRONT DOOR HINGES @\$165.00		twi	\$330.00
1 PCS	FRONT DOOR RUBBER O/S		rer	\$148.00
1 PCS	FRONT DOOR INNER LOCK O/S		twi	\$399.10
1 PCS	FRONT DOOR INNER TRIM BOARD O/S		re/crm	\$665.10
1 SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S		rer	\$50.00
1 PCS	FRONT DOOR GLASS OUTER MOULDING O/S		11	\$121.10
1 PCS	FRONT DOOR GLASS REGULATOR O/S		11	\$265.10
1 PCS	FRONT DOOR GLASS REGULATOR MOTOR O/S		shhl	\$331.50
1 PCS	FRONT DOOR OUTER PILLAR O/S		1021.10	\$1,021.10
1 PCS	FRONT STEP PANEL GARNISH O/S		320	\$388.10
1 PCS	FRONT WHEEL ARCH PANEL O/S	546.10	3rd/3rd	\$565.10
1 PCS	FRONT WHEEL ARCH PANEL GARNISH O/S		rer	\$311.10
1 PCS	FRONT SHOCK ABSORBER O/S		rer	\$266.50
1 PCS	FRONT LOWER ARM O/S		twi	\$845.10
1 PCS	FRONT KNUCKLE ARM O/S		3rd	\$866.50
1 PCS	REAR PILLAR 'D-40' EMBLEM O/S		rer	\$68.50
				\$14,399.70
	S.NETT	2570		
1 PCS	FRONT DOOR ROC STICKER O/S	2640.3	rer	\$50.00
1 SET	FRONT DOOR CORPORATE STICKER O/S	9480.22	rer	\$500.00
		13240.22		
		10552		
	LABOUR CHARGES			
	TOWING CHARGE			\$120.00
	TO CHECK WIRING			\$80.00
	TO SPRAY RUST PROOFING			\$100.00
	TO DISMANTLE & REFIX FRONT DOOR COMPONENTS			\$100.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY			\$100.00
	TO CONDUCT WHEEL ALIGNMENT			\$120.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN			\$120.00
	TO DISMANTLE & REFIX FRONT DASHBOARD			\$300.00
	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE			\$250.00
	TO REFILL AIR-CON GAS			\$120.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,800.00

TO PUTTY & SPRAY PAINTING

\$1,500.00

1100

TOTAL

\$19,659.70

3260

LKF Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 8700K

Vehicle Details

Vehicle No.: GBC9511T

Vehicle to be Exported: No

Intended Deregistration Date: 10 Jun 2019

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA DYNA 150 MANUAL

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: 1KD2369000

Chassis No.: JTFAT35Y90K202780

Maximum Power Output: -

Open Market Value: \$27,856.00

Original Registration Date: 18 Mar 2014

First Registration Date: 18 Mar 2014

Transfer Count: 0

Actual ARF Paid: \$1,393.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Mar 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$16,796.00

COE Rebate Amount: \$8,009.00

Total Rebate Amount: \$8,009.00

The information contained herein is correct as at 10 Jun 2019

OK

Free Car Valuation

Unsure of how much your car is worth?
Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



3.18%PA \$0 Admin Fees@Gv
Finance 2 Years Warranty \$2500
Down Monthly From \$638
Gv Credit Pte Ltd StarAd

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

View our cars

Browse by Category

Sort by Date Posted 20 results/page

12 vehicles

toyota dyna

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota dyna		Any	Any	2014	Any	Any	Any	Available
	Toyota	Dyna 150 3.0M	\$42,800	\$7,950 /yr	27-Oct-2014	2,982 cc	82,245 km	Truck	Available
Fuel Type: Diesel Under Utilised Lorry For Sale! Toyota Borneo Agent Full Service Records. Smooth Manual Transmission, No Further Repairs Needed. Great Work Horse For Newly Start Up. High Loan Available, Please Call Fo...									
Ezy-1 Pte Ltd Posted: 10-Jun-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$40,800	\$7,970 /yr	23-Jul-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel 100% Loan Available! As Low As \$776 Monthly! Definitely Cheaper Than Rental! Huge 7ft Box With Big Storage! Efficient And High Productivity! New Cushion Wrap/Paintwork! No Repairs Needed. Single Fussy...									
Car (S) Pte Ltd Posted: 10-Jun-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$43,800	\$8,010 /yr	25-Nov-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel New Paintwork, Workshop Checked & Service, All In Good Condition To Serve You! Free 6 Month Road Tax Trade In, Full Cash / High Full Loan All Welcome! Low Interest Rate! Please Call Our Friendly Sales Con...									
Car (S) Pte Ltd Posted: 09-Jun-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$42,800	\$7,820 /yr	28-Nov-2014	2,982 cc	118,000 km	Truck	Available
Fuel Type: Diesel 1 Owner Only! Well Maintained, Excellent Condition! In House Loan Available. Call For More Enquiries!									
Posted: 05-Jun-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Motul Scooter Gear 80W90 (120ml) Extreme pressure transmission oil specially designed for the heavy working scooters and mopeds transmissions. Find out more!								
	Toyota	Dyna 150 3.0M	\$40,800	\$7,410 /yr	11-Dec-2014	2,982 cc	101,030 km	Truck	Available
Fuel Type: Diesel This Unit At Super Low Mileage (101030KM) Only! Please Call To Arrange For Viewing, Thanks!									
Posted: 04-Jun-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$41,800	\$7,790 /yr	21-Oct-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel Good Condition, High In House Loan Available! Call Our Friendly Sales Team For Viewing Now.									
ABWIN (1994) Pte Ltd Posted: 01-Jun-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO PTE LTD
N: GBC9511 T
Date: 13.6.19 13:39



GBC9511 T

Toyota : Dyna : KDY/LY(220,230,250,260) Independent Front Suspension Models : 2006.9- : KDY231R-TLMKY

Front : Left

Actual	Before	Specified Range
0°32'	0°32'	-0°15' 1°15'
3°39'	3°39'	2°25' 3°55'
0°26'	0°26'	0°07' 0°12'
22°07'	22°07'	
22°39'	22°39'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°05'	-1°05'	-0°15' 1°15'
4°39'	4°39'	2°25' 3°55'
0°31'	0°31'	0°07' 0°12'
19°20'	19°20'	
18°15'	18°15'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
1°37'	1°37'	-0°30' 0°30'
-0°59'	-0°59'	-0°30' 0°30'
2°47'	2°47'	-0°30' 0°30'
0°57'	0°57'	0°14' 0°24'

Rear : Left

Actual	Before	Specified Range
-0°12'	-0°12'	
-0°14'	-0°14'	

Camber
Toe

Rear : Right

Actual	Before	Specified Range
0°02'	0°02'	
-0°45'	-0°45'	

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°13'	-0°14'	
-0°58'	-0°58'	
0°16'	0°15'	

Print Received Message

This mail is associated with :

***GBC9511T (8084555646SG)
[SMJ2236S]**

TP

HOCK SOON HUAT HARDWARE & MACHINERY CO

Jun 9 2019 11:00AM

[SECK LING LING, MELISSA]

Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 12/09/2019 11:25 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12037.00) - GBC9511T - Claim Handler: Loh, Chee-Heng

Approved:12037.00.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 8700K

Vehicle Details

Vehicle No.: GBC9511T
Vehicle to be Exported: Yes
Intended Deregistration Date: 10 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: TOYOTA DYNA 150 MANUAL
Primary Colour: Silver
Manufacturing Year: 2014
Engine No.: 1KD2369000
Chassis No.: JTFAT35Y90K202780
Maximum Power Output: -
Open Market Value: \$27,856.00
Original Registration Date: 18 Mar 2014
First Registration Date: 18 Mar 2014
Transfer Count: 0
Actual ARF Paid: \$1,393.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Mar 2024
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$16,796.00
COE Rebate Amount: \$8,009.00
Total Rebate Amount: \$8,009.00

The information contained herein is correct as at 10 Jun 2019

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

Date : 08.08.2019

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: GBC 9511T AND SMJ 2236S ON 09.06.2019

We are the authorized repair workshop for the owner of motor vehicle no: **GBC 9511T**, which was involved in the captioned accident with your insured vehicle no: **SMJ 2236S**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	11,235.00
2) Loss Of Use (7 days + 1 sun X \$100)	\$	800.00
3) GIA Search Fee	\$	2.00
	\$	12,037.00

We enclosed herewith the following documents to support the claims:

- | | |
|---------------------------------|------------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) GIA Report/GIA Search Result | d) I/C & Driving Licence |
| e) Insurance Certificate | f) Letter of Authorisation, etc... |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang

For Fastech Auto Pte Ltd





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG19010141/Uhb3

18 JUNE 2019

SECK LING LING, MELISSA
10 AVA ROAD
#11-06
Singapore 329949

Dear Sir/Madam,

ACCIDENT INVOLVING SMJ2236S AND GBC9511T ON 09/06/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third-Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third-Party claim. However, if your policy has an NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Jimmy
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Hock Suen Huat Hardware and Machinery Co ("the third party claimant")
of 2 moonstone Lane 5328450 (address),
owner of GBC 9511T (vehicle no.) hereby authorize
Fastech Auto Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. GBC 9511T that was
damaged pursuant to the accident which occurred on 9/6/19 (date) along
CTE towards AGE (location)
involving vehicle no/s SMJ 2236S ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 10 day of 06 (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I Fastech Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 11,235.00 (repair costs), S\$ 800.00 (loss of use/rental), S\$ 200 (search fees) for vehicle no. GBC9511T that was damaged pursuant to the accident which occurred on 9/6/19 (date) along GTE towards AYE (location) involving vehicle no/s SMJ 22365.

This is pursuant to the inspection conducted on 10/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Hock Soon Hui Horwure and Machinery CO ("third party claimant") of vehicle no. GBC9511T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBC9511T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 day of 09 (month) 20 19 (year)



CK6

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax.Reg No: 200006262D

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 21157

Date: 08.08.2019

Vehicle No: GBC 9511T

Make/Model: TOYOTA DYNA

Accident Date: 09.06.2019

Claim No : 0619-21157

Reference :

Policy No :

	Amount
To proceed on lump sum repair	S\$ 10,500.00

E. & O. E.	Total : S\$	10,500.00
	GST @ 7% : S\$	735.00
	Amount Due : S\$	11,235.00


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

TAX INVOICE

Our Ref No: GR-19-091138

Date of Request: 10/06/2019

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 10/06/2019
Enquiry By: Tang Kok Wee, Allan
Vehicle No.: SMJ2236S
Accident Date: 09/06/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-091138
Date of Request: 10/06/2019

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 10/06/2019
Enquiry By: Tang Kok Wee, Allan
Vehicle No.: SMJ2236S
Accident Date: 09/06/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SMJ2236S	AIG Asia Pacific Insurance Pte. Ltd.	26/02/2019-25/02/2021	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019 Edit Reg		10 Jun 2019 00:00 Edit Adj Rpt	S\$10,500.00 Edit Estimates	S\$10,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SECK LING LING, MELISSA , ID: S8706877C								
Main Claimant:	HOCK SOON HUAT HARDWARE & MACHINERY CO. , Co. Reg. No.: NA								
Vehicle Reg. No.:	GBC9511T	Date of Loss:	09/06/2019 11:00 - :59 62 Months and 22 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / 8084555646SG	Policy/Cover Note No.:	1900020109 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMJ2236S	Policy No. (Claimant):	P1735421						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (12/09/2019): Alert - Adj Mandate Approved (S\$12037.00) - GBC9511T - Claim Handler: Loh, Chee-... - AIG_SG (11/06/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC9511T (8084555646SG)

[SMJ2236S]

TP

HOCK SOON HUAT HARDWARE & MACHINERY CO

Jun 9 2019 11:00AM

[SECK LING LING, MELISSA]

Fastech Auto Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	10/06/19 19:24	Chassis Number		Load JPG	☒	
2	10/06/19 19:24	Odometer Reading		Load JPG	☒	
3	10/06/19 19:24	General View		Load JPG	☒	
4	10/06/19 19:24	General View		Load JPG	☒	
5	10/06/19 19:24	General View		Load JPG	☒	
6	10/06/19 19:24	General View		Load JPG	☒	
7	10/06/19 19:24	General View		Load JPG	☒	
8	10/06/19 19:24	General View		Load JPG	☒	
9	10/06/19 19:24	General View		Load JPG	☒	
10	10/06/19 19:24	General View		Load JPG	☒	
11	10/06/19 19:24	General View		Load JPG	☒	
12	10/06/19 19:24	General View		Load JPG	☒	
13	10/06/19 19:24	General View		Load JPG	☒	
14	10/06/19 19:25	General View		Load JPG	☒	
15	10/06/19 19:25	General View		Load JPG	☒	
16	10/06/19 19:25	General View		Load JPG	☒	
17	10/06/19 19:25	General View		Load JPG	☒	
18	10/06/19 19:25	General View		Load JPG	☒	
19	10/06/19 19:25	General View		Load JPG	☒	
20	10/06/19 19:25	General View		Load JPG	☒	
21	10/06/19 19:25	General View		Load JPG	☒	
22	10/06/19 19:25	General View		Load JPG	☒	
23	10/06/19 19:25	General View		Load JPG	☒	
24	10/06/19 19:25	General View		Load JPG	☒	
25	10/06/19 19:25	General View		Load JPG	☒	
26	10/06/19 19:25	General View		Load JPG	☒	
27	10/06/19 19:25	General View		Load JPG	☒	
28	10/06/19 19:25	General View		Load JPG	☒	
29	10/06/19 19:25	General View		Load JPG	☒	
30	10/06/19 19:25	General View		Load JPG	☒	
31	10/06/19 19:25	General View		Load JPG	☒	
32	10/06/19 19:25	General View		Load JPG	☒	
33	10/06/19 19:25	General View		Load JPG	☒	
34	10/06/19 19:25	General View		Load JPG	☒	
35	10/06/19 19:25	General View		Load JPG	☒	
36	10/06/19 19:25	General View		Load JPG	☒	
37	10/06/19 19:25	General View		Load JPG	☒	
38	10/06/19 19:25	General View		Load JPG	☒	
39	10/06/19 19:25	General View		Load JPG	☒	
40	10/06/19 19:25	General View		Load JPG	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	10/06/19 19:25	General View	 Load JPG	☒
42	10/06/19 19:25	General View	 Load JPG	☒
43	10/06/19 19:25	General View	 Load JPG	☒
44	10/06/19 19:25	General View	 Load JPG	☒
45	10/06/19 19:25	General View	 Load JPG	☒
46	10/06/19 19:25	General View	 Load JPG	☒
47	10/06/19 19:25	General View	 Load JPG	☒
48	10/06/19 19:25	General View	 Load JPG	☒
49	10/06/19 19:25	General View	 Load JPG	☒
50	10/06/19 19:25	General View	 Load JPG	☒
51	10/06/19 19:25	General View	 Load JPG	☒
52	10/06/19 19:25	General View	 Load JPG	☒
53	10/06/19 19:25	General View	 Load JPG	☒
54	10/06/19 19:25	General View	 Load JPG	☒
55	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
56	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
57	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
58	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
59	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
60	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
61	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
62	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
63	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
64	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
65	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
66	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
67	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
68	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
69	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
70	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
71	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
72	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
73	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
74	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
75	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
76	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
77	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
78	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
79	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
80	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
81	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
82	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
83	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
84	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
85	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
86	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
87	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
88	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
89	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
90	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
91	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
92	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
93	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
94	11/06/19 17:17	Reinspection Photo	 Load JPG	☒
95	11/06/19 17:17	Reinspection Photo	 Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	11/06/19 17:17	Reinspection Photo		Load JPG	☒
97	11/06/19 17:17	Reinspection Photo		Load JPG	☒
98	13/06/19 17:16	Reinspection Photo		Load JPG	☒
99	13/06/19 17:16	Reinspection Photo		Load JPG	☒
100	13/06/19 17:16	Reinspection Photo		Load JPG	☒
101	13/06/19 17:16	Reinspection Photo		Load JPG	☒
102	13/06/19 17:16	Reinspection Photo		Load JPG	☒
103	13/06/19 17:16	Reinspection Photo		Load JPG	☒
104	13/06/19 17:16	Reinspection Photo		Load JPG	☒
105	13/06/19 17:16	Reinspection Photo		Load JPG	☒
106	13/06/19 17:16	Reinspection Photo		Load JPG	☒
107	13/06/19 17:16	Reinspection Photo		Load JPG	☒
108	13/06/19 17:16	Reinspection Photo		Load JPG	☒
109	13/06/19 17:16	Reinspection Photo		Load JPG	☒
110	13/06/19 17:16	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/06/19 19:52	TP GIA REPORT		Load PDF	
2	18/06/19 15:58	Letter to OI		Load PDF	
3	23/08/19 15:30	TP ESTIMATE - MARKED		Load PDF	
4	06/09/19 09:58	GIA SEARCH		Load PDF	
5	06/09/19 09:58	LOD		Load PDF	
6	19/09/19 12:48	WORKSHOP INVOICE		Load PDF	
7	19/09/19 12:48	AUTHORISATION TO ACT FORM		Load PDF	
8	19/09/19 12:48	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	14/06/19 09:59	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SMJ2236S (Insd veh)	Model:	TOYOTA DYNA 1.5T 3.0 (A)
	GBC9511T (TP veh)		
Date of Accident:	09/06/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	21,035.88
Final Repair Cost	:	\$	11,235.00
Loss of Use	:	\$	800.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	12,037.00

8.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 12,037.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

19 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19010141/UHB3Q2

Date: 19/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900020109
 Claimant: GBC9511T Insured Vehicle No: SMJ2236S
 Vehicle No: GBC9511T
 Date of Loss: 09/06/2019 Nature of Claim: TP Claim No: 8084555646SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC9511T
 Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 1KD2369000
 Reg. Date: 18/03/2014 (Man. Year: 2014) Chassis No: JTFAT35Y90K202780
 Colour: Silver Odometer: 210191 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
 Front Left Side: Bridgestone 6 mm Rear Left Side: Yokohama 6/6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,949.70	9,710.22	5,239.48	35.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,710.00	3,530.00	1,180.00	25.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,659.70	13,240.22	6,419.48	32.65
Approved Total (Overridden) (S\$)		10,500.00		
(S\$)	19,659.70	10,500.00	9,159.70	46.59
+ GST 7.00/7.00% (S\$)	1,376.18	735.00	641.18	46.59
Nett Amount (S\$)	21,035.88	11,235.00	9,800.88	46.59
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,037.00		

INSPECTION

Date of Assignment: 10/06/2019
 Date Inspected: 10/06/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	745.20 F	*455.60 FL
2	1		*FRONT BUMPER BRACKET O/S	Not Necessary	290.00 F	*- FL
3	1		*HEADLAMP O/S	Broken	1,065.00 F	*1,065.00 FL
4	1		*HEADLAMP RUBBER O/S	Torn	28.00 F	*28.00 FL
5	1		*FRONT GRILLE	Cracked	899.10 F	*680.10 FL
6	1		*FRONT GRILLE LOGO	Necessary	68.50 F	*68.50 FL
7	1		*FRONT PANEL	Dented / Warped	1,685.10 F	*1,685.10 FL
8	1		*FRONT PANEL DYNA EMBLEM	Necessary	88.50 F	*88.50 FL
9	1		*FRONT PANEL TOP BLACK GARNISH	Not Necessary	288.10 F	*- FL
10	1		*FRONT CORNER PANEL O/S	Distorted	405.00 F	*405.00 FL
11	1		*FRONT CORNER PANEL TOP BLACK GARNISH O/S	Cracked	166.10 F	*166.10 FL
12	1		*FRONT CORNER PANEL TOP GARNISH O/S	Cut / Cracked	384.10 F	*384.10 FL
13	1		*FRONT DOOR O/S	Distorted	1,645.10 F	*1,645.10 FL
14	2		*FRONT DOOR HINGES	Twisted	330.00 F	*330.00 FL
15	1		*FRONT DOOR RUBBER O/S	Necessary	148.00 F	*148.00 FL
16	1		*FRONT DOOR INNER LOCK O/S	Twisted	399.10 F	*399.10 FL
17	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed / Cracked	665.10 F	*665.10 FL
18	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 F	*50.00 FL
19	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Not Necessary	121.10 F	*- FL
20	1		*FRONT DOOR GLASS REGULATOR O/S	Not Necessary	265.10 F	*- FL
21	1		*FRONT DOOR GLASS REGULATOR MOTOR O/S	Shorted	331.50 F	*331.50 FL
22	1		*FRONT DOOR OUTER PILLAR O/S	Badly Dented	1,021.10 F	*1,021.10 FL
23	1		*FRONT STEP PANEL GARNISH O/S	Broken	388.10 F	*388.10 FL
24	1		*FRONT WHEEL ARCH PANEL O/S	Bent / Buckled	565.10 F	*545.10 FL
25	1		*FRONT WHEEL ARCH PANEL GARNISH O/S	Twisted	311.10 F	*311.10 FL
26	1		*FRONT SHOCK ABSORBER O/S	Serviceable	266.50 F	*- FL
27	1		*FRONT LOWER ARM O/S	Twisted	845.10 F	*845.10 FL
28	1		*FRONT KNUCKLE ARM O/S	Bent	866.50 F	*866.50 FL
29	1		*REAR PILLAR D-40 EMBLEM O/S	Necessary	68.50 F	*68.50 FL
30	1		*FRONT DOOR ROC STICKER O/S	Necessary	50.00 FS	*30.00 FS
31	1		*SET FRONT DOOR CORPORATE STICKER O/S	Necessary	500.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **14,949.70** **12,870.30**
 - List Item Discount on L Items 0.00/25.00% (S\$) 0.00 3,160.08

Total Parts (S\$) **14,949.70** **9,710.22**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGE	New	120.00	50.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO SPRAY RUST PROOFING	New	100.00	100.00
4	TO DISMANTLE & REFIX FRONT DOOR COMPONENTS	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	100.00	80.00
6	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
7	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	120.00	80.00
8	TO DISMANTLE & REFIX FRONT DASHBOARD	New	300.00	200.00
9	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	New	250.00	150.00
10	TO REFILL AIR-CON GAS	New	120.00	100.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,500.00
12	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
Gross Labour Cost (S\$)			4,710.00	3,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >