



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	: SMF2929Y
Make / Model	: MITSUBISHI EVO X
Chassis number	: JMFSNCZ4A9U000243
Accident date	: 5/6/19
Reference	: 1906-17

AIG SINGAPORE
78 SHENTON WAY #07-16
SINGAPORE 079120

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BOOTLID SENSOR	ex X 100.00
1	REAR BOOTLID SENSOR LOGO	X 90.00
2	REAR BOOTLID RUBBER	de 380.00
1	REAR BOOTLID 'LANCER' EMBLEM	re 85.00
1	REAR BOOTLID 'EVOLUTION' EMBLEM	re 100.00
1	REAR BOOTLID 'MIVEC' EMBLEM	re 85.00
1	REAR BOOTLID 3RD BRAKE	dis 390.00
1	REAR BOOTLID INNER TRIM	de 250.00
2	REAR BOOTLID REFLECTOR TAILLAMP	? 380.00
1	REAR BOOTLID WEATHERSTRIP	re 190.00
1	REAR BOOTLID MECHANISM	bt 120.00
1	REAR BOOTLID LOCK CATCH	Ry 80.00
2	REAR BOOTLID HYDRAULIC SIDE DAMPER	Ry 180.00
2	REAR BOOTLID HINGE	bt 250.00
1	REAR BOOTLID	bt 1800.00
1	REAR END PANEL	bt 550.00
1	REAR END PANEL TOP GARNISH	de 320.00
1	REAR END PANEL LOCK SENSOR	CR 220.00
1	TOP SPEAKER PANEL	Ry 690.00
1	SPEAKER INNER BRACE PANEL	X 550.00
1	SPEAKER TOP BOARD	X 450.00
1	SPEAKER BOX	X 980.00
1	FLOOR PANEL	Ry 590.00
1	REAR SPARE TYRE TOP BOARD	? 240.00
2	REAR SPARE TYRE SIDE BOARD	? 300.00
2	REAR SIDE BOARD SPONGE	? 550.00
1	REAR HEATSHIELD	? 120.00
2	REAR TAILLAMP	LH-? RH-? 1300.00
2	REAR TAILLAMP PANEL	LH-X RH-bt 480.00
1	REAR LH FENDER	Ry 880.00
1	REAR LH INNER WHEELHOUSE	Ry 700.00
2	REAR FENDER INNER SHIELD	? 350.00
2	REAR FENDER INNER TRIM	? 480.00
1	REAR BUMPER REINFORCEMENT BAR	bt 400.00

2	REAR BUMPER REINFORCEMENT BRACKET	st	380.00
1	REAR BUMPER ASSY	de	1500.00
2	REAR BUMPER SIDE RETAINER	de	190.00
2	REAR BUMPER BRACKET	de	190.00
2	REAR BUMPER REFLECTOR	LH-? RH-as	190.00
2	REAR BUMPER NUMBER PLATE LAMP BRACKET	dis	150.00
			17230.00
Less 20 %			3446.00
Subtotal			13784.00
Balance C/F			13784.00

Vehicle number : SMF2929Y

Make Model : MITSUBISHI EVO X

Reference : 1906-17

Qty Particulars

Unit Price - SGD \$

		<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>	
		Balance B/F	13784.00
1SET	REAR BUMPER CLIP	30 ne	80.00
1	JOINT SEALANT	50 ne	180.00
1SET	REAR FENDER INNER TRIM CLIP	30 ne	80.00
1	FLOOR INSULATOR	?	180.00
1	REAR BOOTLID SPOILER (AFTERMARKET)	Rp	3200.00
1SET	REAR BOOTLID INNER TRIM CLIP	20 ne	70.00
1	TRUST EXHAUST ASSY	?	6300.00 *check price
1	REAR CARBON DIFFUSER	one	2500.00
1	REAR NUMBER PLATE	1st	80.00 as
1SET	REAR REVERSE SENSOR	X	420.00
1SET	REVERSE CAMERA	X	180.00
		Subtotal	27054.00
		Balance C/F	27054.00

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
S/NO	Balance B/F	27054.00
1	CHECK REAR WIRING AND LIGHTING SYSTEM	90.00 30.
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	250.00 60.
3	REMOVE AND RENEW REAR REVERSE SENSOR	180.00 X
4	REMOVE AND RENEW REAR EXHAUST ASSY	180.00 80.
5	REMOVE AND RENEW FLOOR INSULATOR	180.00 40.
6	REMOVE AND RENEW REAR REVERSE CAMERA	180.00 X
7	DIAGNOSIS CHECK AND CLEAR FAULT CODE	500.00 150.
8	CHECK REAR WHEEL ALIGNMENT	180.00 X
9	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	220.00 60.
10	PANEL BEATING ON AFFECTED AREAS	2800.00 1300.
11	SPRAY PAINTING ON AFFECTED AREAS	1800.00 400.
12	APPLY ANTI RUSH ON AFFECTED AREAS	180.00 40.
Subtotal		33794.00
Grand total		33794.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 9749544
WP

20/6/19 24 pm

humpson

Reony after repair.

2 days - 9 days.

taufik@lkhant.com