

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0743/2019/TG  
**Date** : 13-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

**Your insured vehicle no. : XD 4933 B**

## AXA Insurance Singapore Pte Ltd

8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

**Attn: Motor Claims Dept**  
**Tel: 6880 4602 - Fax 6880 4838**

**Owner's Name** : Mr. Wong Fui Keong  
**Address** : Blk 184 Stirling Road  
#10-248  
Singapore 140184  
**Telephone** : (HP)+65 92380030  
**Type of Claim** : Third Party Claims  
**Policy No.** : PNPV2018-00016995  
**Vehicle No** : **SBH 27 H**  
**Model Code** : A3 Sedan 1.4 TFSI (Attraction)  
**Model / Year** : Dec-16  
**Engine No** : CZC 556133  
**Chassis No** : WAUZZZ8V5G1099353  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 1-Jun-19  
**Place of Accident** : In Front Blk 26 Jalan Membina

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SBH 27 H

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear cradl management components. Reinstall all parts removed.	\$ 1,050.00 700.
3	To respray rear bumper.	\$ 900.00 700.
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>2,422.00</u>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SBH 27 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 1,708.00	de ✓
2	REAR BUMPER FIXING SETS	\$ 175.00	?
3	REAR BUMPER GUIDE SECTION - LH	\$ 15.00	?
4	REAR BUMPER GUIDE SECTION - RH	\$ 15.00	?
5	REAR BUMPER GUIDE PIN	2 \$ 53.00	?
6	REAR BUMPER SPOILER	\$ 216.00	cul ✓
7	REAR LIGHT REFLECTOR - LH	1 \$ 38.00	X
8	REAR BUMPER IMPACT REINFORCEMENT BAR	1 \$ 522.00	?
9	BRACKET - LH	1 \$ 12.00	?
10	BRACKET - RH	1 \$ 12.00	?
11	PARKING AID SENSOR	2 \$ 462.00	?
12	SEAL RING	4 \$ 12.00	he ✓
13	SUNDRIES	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		: \$ 3,440.00	
TOTAL LABOUR CHARGES		\$ 2,422.00	
GRAND TOTAL		\$ 5,862.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

Tanpin 9A495745  
WP  
17/6/19 @ 220pm  
23 days  
Respray & paint  
surroundings

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant