

INSURANCE

INS. CASE OWNER:

Yvonne.

CC 4 ASM
AXA1900 10155 / E 9/23/19

LKK

IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

11/6/19

Date / Time:

10/6/19

Registered in Meriton:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDD 5594B

Name of Insured:

UHO ENH LEE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

8/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: UHO 714 4549 746

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SAM02002 / 120469

Policy No.:

GA046687

Make / Model:

MERCEDES

Place of Accident:

TANJONG KATONG RD SOUTH

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUF 52872



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng
Hoe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SUF 52872 - X

SDD 5594B - X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

21/10/19

22/10

29/10

29/10

Send LOI
File pass KSC to get finalise amt.

To seek mandate.

Pending mandate approval (approved)

Settle @ \$325 as per LOD. File pass cu to

sendov.

21/10/19

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

US

SS 3100.00

(5 days)

Reduction: \$1087.92 % 26

Email

Call

FINAL SETTLEMENT

Date/Time:

29/10/19

Confirm with

June

Email

Call

Final Liability:

% 100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost:

(WAS)

SS 3319.00

Loss of Rental (LOR):

SS

(5 days)

Loss of Use (LOU):

SS

400.00

(5 80 x 5 days)

Loss of Income (LOI):

SS

(5 x 5 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

8.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3325

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3225.00

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF: AdA /

9

Reinerh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hwa

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 55K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 546 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLF 5281 Yr Regn: 03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or WagonMake: Honda Stream cc 1799Colour: White A/C: Insured / Std / NI / NASp. Reading: 167311 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RNB 10864P5Gen. Cond: Good Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

R/Bal: 1 mmL/Bal: 1 mmD.O.A. 8/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to
EH not readyMV: 55KLTA: 15,750NV: 39,25045 * \$3100 - (Red = \$1087.95 / 26%)

Date/Time: File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:
\$ - RS. \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. is

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chunhow@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 08/06/2019

TP Veh Reg No: SDD5594B

Estimate No: ES1991611
Date: 12 Jun 2019
Policy No: 5109241335
Veh Reg No: SLF5281Z
Make/Model: HONDA STREAM 1.8 X
AUTO

Chassis No: RN61086495

Engine No: R18A1795911

Reg. Date: 16/03/2009

Estimate Repair Cost to Vehicle No :SLF5281Z

Description	U/Price	Quantity	List Price	Amount
List Price			S\$	S\$
1 REAR BUMPER	688.50	1 PC	CM 688.50	✓
2 REAR BUMPER TOW COVER	17.00	1 PC	MT 17.00	✓
3 REAR BUMPER CLIP	3.70	6 PCS	MT 22.20	✓
4 REAR TAILGATE	903.50	1 PC	MT 903.50	✓
5 TAILGATE INNER LOCK	151.80	1 PC	MT 151.80	✓
6 TAILGATE EMBLEM - STREAM	31.60	1 PC	MT 31.60	✓
7 TAILGATE INNER RUBBER	121.40	1 PC	MT 121.40	50812
8 REAR WINDSCREEN GLASS MOULDING	65.80	1 PC	MT 65.80	✓
9 REAR PANEL OUTER	306.40	1 PC	MT 306.40	✓
10 REAR EXHAUST PIPE	514.20	1 PC	MT 514.20	✓
			2,822.40	
		Less 20%	564.48	2,257.92
Special Net				
11 REVERSE SENSOR	200.00	1 PC	Short 200.00	✓
12 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	MT 40.00	✓
			240.00	240.00
Labour				
13 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
14 TO PANEL BEATING	700.00	1 LA	700.00	✓
15 TO PUTTY AND RESPRAY PAINTING	700.00	1 LA	700.00	✓
16 RUSTPROOFING	60.00	1 LA	60.00	✓
17 TO REMOVE AND REFIX REVERSE CAMERA AND RESETTNG	50.00	1 LA	50.00	✓
18 TO REMOVE AND REFIX REAR EXHAUST PIPE	60.00	1 LA	60.00	✓
			1,690.00	1,690.00
			Total	S\$ 4,187.92
			Add GST @ 7%	293.15
			Total Amount Payable	S\$ 4,481.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S: AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

ATTN: Motor Claim Department

FAX: 68804739

Estimate No: ES1991611

Date: 12 Jun 2019

Policy No: 5109241335

Veh Reg No: SLF5281Z

Make/Model: HONDA STREAM 1.8 X
 AUTO

Chassis No: RN61086495

Engine No: R18A1795911

Reg. Date: 16/03/2009

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 08/06/2019

TP Veh Reg No: SDD5594B

Not Authorized

1/2 Day & ?

Resurvey After Paint 5 days

Estimate Repair Cost to Vehicle No :SLF5281Z

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	688.50	1 PC	688.50	✓
2 REAR BUMPER TOW COVER	17.00	1 PC	17.00	✓
3 REAR BUMPER CLIP	3.70	6 PCS	22.20	✓
4 REAR TAILGATE	903.50	1 PC	903.50	✓
5 TAILGATE INNER LOCK	151.80	1 PC	151.80	✓
6 TAILGATE EMBLEM - STREAM	31.60	1 PC	31.60	✓
7 TAILGATE INNER RUBBER	121.40	1 PC	121.40	?
8 REAR WINDSCREEN GLASS MOULDING	65.80	1 PC	65.80	✓
9 REAR PANEL OUTER	306.40	1 PC	306.40	?
10 REAR EXHAUST PIPE	514.20	1 PC	514.20	?
			2,822.40	
		Less 20%	564.48	2,257.92
Special Net				
11 REVERSE SENSOR	200.00	1 PC	200.00	✓
12 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			240.00	240.00
Labour				
13 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
14 TO PANEL BEATING	700.00	1 LA	700.00	?
15 TO PUTTY AND RESPRAY PAINTING	700.00	1 LA	700.00	Good
16 RUSTPROOFING	60.00	1 LA	60.00	?
17 TO REMOVE AND REFIX REVERSE CAMERA AND RESETING	50.00	1 LA	50.00	✓
18 TO REMOVE AND REFIX REAR EXHAUST PIPE	60.00	1 LA	60.00	?
			1,690.00	1,690.00
			Total	S\$ 4,187.92
			Add GST @ 7%	293.15
			Total Amount Payable	S\$ 4,481.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SLF 5281Z

1 pc rear bumper ✓ cm
 _____ tow cover _____ 2.1

6, _____ clips ✓

1 pc tail gate R ✓
 _____ inner lock R ✓

_____ emblem 'STREAM' ✓

_____ inner rubber ?

1 pc rear w/ green moulding ✓

1 pc rear panel outer ?

1 pc rear exhaust pipe ?

1 set reverse sensor

\$200/ SN ✓

1 pc rear w/ green gun

\$40/ SN ✓

① R & R rear w/ green

\$120/ ✓

② Panel beating

\$70/ ?

③ fitting a new

\$700/ 600

④ Rubdown

\$60/ ?

⑤ R & R reverse camera

\$80/ ✓

⑥ R & R rear exhaust

\$60/ ?

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0577B

Vehicle Details

Vehicle No.: SLF5281Z
Vehicle to be Exported: No
Intended Deregistration Date: 08 Jun 2019
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8X A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: R18A1795911
Chassis No.: RN61086495
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$21,266.00
Original Registration Date: 16 Mar 2009
First Registration Date: 16 Mar 2009
Transfer Count: 2
Actual ARF Paid: \$21,266.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Mar 2024
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$16,509.00
COE Rebate Amount: \$15,745.00
Total Rebate Amount: \$15,745.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jun 2019

OK

Enquire Vehicle & Owner Information (Vehicle No. SDD5594B As At 08 Jun 2019 / 12:10:00)*** Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SLF5281

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S0037051G

Owner Name: CHOO ENG LEE

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 20

Registered Street Name: AMBER ROAD

Registered Unit No.: # 12 - 02

Registered Building Name: -

Registered Postal Code: 439869

Current Vehicle Details

Vehicle No.: SDD5594B

Make Description/Model: MERCEDES BENZ / E200 AUTO

Insurance Company Name: AXA INSURANCE PTE LTD

◀ Service Request Details

Claim

S9M01Q02

Reference

None ✎

Loss Date

8 June 2019

Report Date

10 Jun 2019 11:30:00 AM

Request Date

10 June 2019

Due Date

17 June 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLF5281Z

p. efeada

T: 1.25p.m

V: out

E. ✓

ISSUED

STREAM-1.8

Service Address

...

Primary Contact/Insured

CHOO ENG LEE

20 AMBER ROAD, #12-02, 439869, Singapore

96311202

Claim Handler

ANG Yvonne

6568804461

yvonne.ang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Monday, 10 June, 2019 10:26 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Repair Survey (Single Joint Expert) - SLF5281Z

Categories: Shekhar

Dear Sir,

OUR CLIENT – SLF5281Z

DOA

: 8/6/19 @12.10pm

AX

A

INSURED : SDD5594B

We refer to the above.

Under Protocol - SJE, pls provide list of surveyors for our selection.

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/10/2019

Survey Details:

Date of loss	8-Jun-19
Date of appointment	10-Jun-19
Date of survey	11-Jun-19
Location of survey	CHENG HOE MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLF 5281Z
Make and Model	HONDA STREAM
Date of registration	16/3/2009
Excess	
Market Value	\$55,000
Parf Rebate	\$15,750
Nett Loss	\$39,250

Repair details:

Initial Estimate	\$ 4,187.92
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,461.55
Check items (estimate)	\$ -
Labour	\$ 1,450.00
Total	\$ 3,911.55
Lump Sum(if applicable)	\$ 3,100.00

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (W/GST)	\$ 3,317.00	
Loss of use	\$ 400.00	5days X \$80
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 8.00	
Others	\$ -	
Proposed Total	\$ 3,725.00	

 **<MANDATE IA> - S9M01Q02 {ACCIDENT INVOLVING
SDD 5594B (OI) & SLF 5281Z (TP) ON 08/06/2019}**

Type

 Question

Message

LIABILITY: 100% BOLA S28 (OI LAST): INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$3,725.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

[Reply](#)



Re:<MANDATE IA> - S9M01Q02 {ACCIDENT INVOLVING SDD 5594B (OI) & SLF 5281Z (TP) ON 08/06/2019}

Type

🔗 Question

Message

Please proceed

Reply

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA
Claim Type: Third Party
Accident Date: 08/06/2019
TP Veh Reg No: SDD5594B

NO: **CL8190929**
Date: 29 Aug 2019
Policy No: 5109241335
Veh Reg No: **SLF5281Z**
Make/Model: HONDA STREAM 1.8 X
AUTO
Job No: JC1600404

Description

Quantity

List Price

PAGE:1
Amount
S\$

To Supply all replaced parts, all necessary and agreed labour &
miscellaneous charges.
(As recommended by your appointed surveyor)

1 PC

S\$ 3,100.00

S\$ 3,100.00

Total

S\$ 3,100.00

Add GST @ 7%

217.00

Total Amount payable


S\$ 3,317.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date:

01 OCT 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SLF5281Z & SDD5594B ON 08/06/2019
TANJONH KATONG SOUTH ROAD.**

We are authorized by SLF5281Z for their above matter.

Record reveals that you are the insurer of SDD5594B. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 3317.00
2. Loss of Use (5 x \$80/Day)	S\$ 400.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 3725.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Without Prejudice

Dear Sirs

Accident involving **SGJ498L** & **SLH5964B** on 20/10/2018

We are instructed by the owner **SLH5964B** to write, negotiate and settle claim on his behalf for the above mentioned accident. Our client's vehicle: **SLH5964B** was inspected and surveyed by your surveyor. As the accident was caused solely due to the negligence of your insured: **SGJ498L** we are now seeking the total amount of claim as follow:

We are now seeking the total amount of claim as follow:

Repair cost	S\$6420.00(with gst)
Rental	1080.00

TOTAL SS 7500.00

We shall appreciate if you could kindly consider our claim at your earliest convenience and kindly let us have your acknowledgement of receipt of this letter within 14days of your receipt of this letter.

Yours faithfully



Jouis seow

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19010155/Kgb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-11-2019



ATTN:YVONNE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDD 5594B	Veh. Inspected	SLF 5281Z
Policy No.	GA046685	Coverage (\$)	0.00
Claim No.	S9M01Q02	Excess (\$)	0.00
Assign From		Assign Date	10/06/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	RN61086495	Colour	WHITE
Odometer	167311	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	WEST LAKE	1 mm
L/H Front Tyre	205/55 R16	WEST LAKE	1 mm
R/H Rear Tyre	205/55 R16	WEST LAKE	8 mm
L/H Rear Tyre	205/55 R16	WEST LAKE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/06/2019	Inspection Date	11/06/2019
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5281Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	CRACKED	688.50	688.50
1	REAR BUMPER TOW COVER (CONSISTENT)	MISSING	17.00	17.00
6	REAR BUMPER CLIP @\$3.70 (CONSISTENT)	NECESSARY	22.20	22.20
1	TAILGATE INNER LOCK (CONSISTENT)	DENTED	151.80	151.80
1	TAILGATE EMBLEM -STREAM (CONSISTENT)	NECESSARY	31.60	31.60
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	65.80	65.80
1	REAR PANEL OUTER (CONSISTENT)	BENT	306.40	306.40
1	REAR EXHAUST PIPE (CONSISTENT)	BENT	514.20	514.20
1	REAR TAILGATE (CONSISTENT)	BENT	903.50	903.50
	LESS 20% DISCOUNT		-540.20	-540.20
			2,160.80	2,160.80
1	TAILGATE INNER RUBBER (CONSISTENT) (SN) (50%)	CUT	121.40	60.75
	LESS 20% DISCOUNT		-24.28	-
			97.12	60.75
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			240.00	240.00
LABOUR				
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	TO PANEL BEATING.		700.00	600.00
	TO PUTTY AND RESPRAY PAINTING.		700.00	600.00
	RUSTPROOFING.		60.00	30.00
	TO REMOVE AND REFIX REVERSE CAMERA AND RESETTING.		50.00	50.00
	TO REMOVE AND REFIX REAR EXHAUST PIPE.		60.00	50.00
			1,690.00	1,450.00
GRAND TOTAL			4,187.92	3,911.55

Report Ref No. CC4/ASM19010155/Kgb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00
---	--	--	----------

Report Ref No. CC4/ASM19010155/Kgb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9M01Q02
Reference	CCA/ASM19010155/Kgb3a2
Loss Date	8 June 2019
Report Date	10 Jun 2019 11:20:00 AM
Request Date	10 June 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #	SLF5281Z
Make	TPVD HONDA
Model	STREAM-1.8
Service Address	

...

Primary Contact/Insured

CHOO ENG LEE
20 AMBER ROAD, #12-02, 439869, Singapore
96311202

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	------------------

Accident Statement

Reports & Statement

Meemin

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (8).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKHInspection (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKHAdjustment1a (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 PAYMENT BREAKDOWN, EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019
 MANDATE IA DO 25102019 .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LCD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019
 PARF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019
 EMAIL TP PIRI.png	Letters and Correspondence	Workshop	VISHNU BATHAM Shukhar	10 June 2019
 LIST OF SURVEYOR SENT.png	Letters and Correspondence	Workshop	VISHNU BATHAM Shukhar	10 June 2019
 GJA SLF52812 TP.pdf	Reports & Statement	GJA Report	VISHNU BATHAM Shukhar	10 June 2019
 EMAIL TP PIRI.png	Letters and Correspondence	Workshop	VISHNU BATHAM Shukhar	10 June 2019
 Service appointment in Vendor Portal (claim: 599401Q02 for vehicle SLF52812.html)	[[GetDocumentType_AsItem.documentType]]			10 June 2019