

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



11/7/2019
Sung & repa

GST REG. NO : M2 - 0020081 - X

10 JUN 2019

E S T I M A T E

Estimate No. : b1 51484
Date Estimated : 10/06/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lean Pek Kwan
15 VICTORIA PARK GROVE

Singapore 266098

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK6180L	G913517	29/04/2019	730Li	0

DESCRIPTION

VALUE

Remove left rear side fender attachment etc include repairs
on the accident area

850. 1,700.00

Spray painting left rear side fender

796 885.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230. 271.00

To check steering geometry and conduct wheel alignment in
accordance with BMW specifications. (1x)

451 531.00

To replace tyre and wheel rim including balancing. (1x).
left rear

80 94.00

Sundries.

? 150.00

Pirelli 275/40 R19 P Zero* r-f 101Y (1PC)
left rear

x 763.75

Total Labour 1: 4,394.75

DESCRIPTION

QTY

PRIC

VALUE

M BADGE

1 12.90

7 12.90

ALLOY RIM 8.5X19 DOUBLE SPK 674M

1 1,810.05

aut 1,810.05

HUB CAP WITH CHROME EDGE

1 28.35

? 28.35

Total Parts : 1,851.30

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51484
Date Estimated : 10/06/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK6180L	G913517	29/04/2019	730Li	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 01/07/19 Excess S\$ _____

Surveyor's Name Taufik Sign _____

Surveyor's Tel 97485749 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail Taufik@lkkauto.com

No. of Working Days Recommend 3 days - 4 days

Labour 1	:	4,394.75
Parts	:	1,851.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	437.22
Grand Total	:	6,683.27

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **