

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHD 9235P - CHINA

LI DAN

Not Authored
21 Sep 83050p

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9235P - LI DAN

LK1LA69RJBB057454*

CHEVROLET

CHEVROLET EPICA 2.0

03.09.2013

CHINA

PART			LIST	
1	1	Rear Bumper (Bumper A-RR)	\$	<i>Br</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00 X
3	1	Front Bumper Reinforcement	\$	<i>R</i> 356.00 X
4	1	Rear Bumper Side Retainer RH	\$	<i>Dir</i> 68.76 ✓
5	1	Rear Bumper Reflectors RH	\$	<i>Mts (M)</i> 119.74 ✓
6	1	Rear Fender RH	\$	<i>Br</i> 1,145.00 ✓
7	1	Rear Fender Inner Cowling RH	\$	<i>Sn</i> 76.60 X
8	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30 X
9	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40 X
TOTAL			\$	3,755.80
10%			\$	375.58
			\$	3,380.22

Specical Nett

1 Set	Rear Bumper Fastener Clip	\$	<i>Mr</i> 24.00 ✓
1 Set	Rear Fender Liner Clip	\$	<i>nn</i> 20.00 X
1	Rear Windscreen Weatherstrip Seal	\$	<i>Mr</i> 68.50 3050 ✓
1	Rear windscreen inner top garnish	\$	<i>nn</i> 80.00 X
2	Rear Windscreen Sealant	\$	<i>Mr</i> 100.00 4050 ✓
1	Parking Sensor	\$	<i>Sn</i> 300.00 X
TOTAL		\$	592.50

TOTAL PARTS \$ 3,972.72

Panel Beating, Knocking And Straightening
 The Necessary Portion, Remove And
 Renewal Of Parts, Adjust And Realign The
 Same

\$ 1,400.00 *600p*

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHD 9235P - CHINA

LI DAN

<i>To Rust-Proofing Of The Affected Areas.</i>	\$	200.00 <i>300</i>
<i>Putty and Spray Painting Of The Affected Portion.</i>	\$	1,350.00 <i>500</i>
<i>To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.</i>	\$	330.00 <i>100</i>
<i>To Reinstall Rear Bumper Parking Sensor.</i>	\$	170.00 <i>60</i>
<i>To Remove And Refit Rear W/ Screen Glass To Facilitate Bodywork Repair.</i>	\$	170.00 <i>120</i>
<i>To Check Electrical Lighting Concerned.</i>	\$	170.00 <i>20</i>

TOTAL	\$	3,790.00
--------------	-----------	-----------------

Over All Total	\$	7,762.72
-----------------------	-----------	-----------------

REPAIR DAYS

5 DAYS